


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised January 1, 2008  
Copy to appropriate District Office

f MCB 1121649923

**Release Notification and Corrective Action**

n MCB 1121650284

**OPERATOR**

Initial Report  Final Report

Name of Company: DCP Midstream, LP <b>36785</b>	Contact: Johnnie Bradford
Address: 10 Desta Drive, Suite 400 W, Midland, TX., 79705	Telephone# & E-mail: 432.620.4166 / jbradford@dcpmidstream.com
Facility Name: W-13 pipeline	Facility Type: Pipeline

Surface Owner: Unk <b>FED</b>	Mineral Owner: Unk	Well API No.: NA
-------------------------------	--------------------	------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	14	19	31		S		E	<del>ten</del> Eddy

Latitude N32.6610 Longitude W103.8363

**NATURE OF RELEASE**

Type of Release : Liquid and Gas	Volume of Release: ~20-25 bbls oil/~430 Mcf of Gas	Volume Recovered: 0
Source of Release: Pipeline	Date & Hour of Occurrence: 05/19/2011 unknown hour	Date & Hour of Discovery: 5/19/2011 ~09:00 MST
Was Immediate Notice Given OCD? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom @ OCD? NA	
By Whom? NA	Date and Hour: NA	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	

If a Watercourse was Impacted, Describe Fully.\*  
NA

Describe Cause of Problem and Remedial Action Taken. (If water spilled, give Chloride content)\*  
The W-13 pipeline developed a leak at the coordinates listed above. The pipeline was isolated to prevent additional leakage to the environment and a crew was dispatched to begin the process of making repairs. The pipeline will be repaired by digging up the affected area and applying a clamp to seal the hole. Any contaminated soil will be removed and disposed in an approved OCD landfill. Once the contamination has been removed, the affected area will be backfilled with material indigenous to the area.

Describe Area Affected, Dimensions, and Cleanup Action Taken.\*  
Affected area consisted of mostly over spray with some liquid that followed cow trails for several feet. Overall demensions of the spill area is approximately 75 feet by 150 feet.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Johnnie Bradford</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Johnnie Bradford	Signed By <i>Mike Brannon</i>	
Title: Sr. Environmental Specialist	Approved by District Supervisor:	
E-mail Address: jbradford@dcpmidstream.com	Approval Date: <b>AUG 04 2011</b>	Expiration Date:
Date: 06/07/2011	Phone: 432.620.4166	Conditions of Approval: <b>2 RP# 811</b>

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**

*Closure has been submitted @ time of entry*

MLB 1121650796  
Comply # MCB 1121650850

## Bratcher, Mike, EMNRD

---

**From:** Bradford, Johnnie [JBRADFORD@dcpmidstream.com]  
**Sent:** Tuesday, June 07, 2011 2:39 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** vernon@hungry-horse.com  
**Subject:** C-141 - W-13 Pipeline - DCP Midstream, LP  
**Attachments:** 20110519-W13Pipeline.pdf

Mike,

Please find a C-141 for the W-13 pipeline leak that was discovered 05/19/2011 by DCPM Operations. This leak is on BLM land and Mr. Paul Evans was present at the leak site during isolation efforts. This site is located at T19S R31E S14 or N32.6610 W103.8361.

If you should have any questions, please don't hesitate to give me a call at one of the numbers listed below.

Johnnie Bradford  
DCP Midstream, LP  
432.620.4166 (off)  
432.425.1416 (cell)