

Bratcher, Mike, EMNRD

From: tgregsto@blm.gov
Sent: Friday, August 26, 2011 10:52 AM
To: dfrick@linnenergy.com; dpotter@linnenergy.com; Bratcher, Mike, EMNRD; boonearch@yahoo.com
Subject: Turner B 80: spill map, spill report, and archeological issues
Attachments: Turner B 80-flowline spill map-081711.jpg

To All,

Attached you will find the spill map for the Turner B 80 flowline spill. Staff archeologists have reviewed the case and have stipulated the following:

1. An archeological monitor is required during cleanup and reclamation activities.

I do not yet have a spill report for this event. The spill report for this event is due in our office by **09/01/11**. Failure to submit the required report by the due date will result in an issuance of an Incidence of Noncompliance for failure to comply with requirements specified in NTL-3A.

Thank you for your attention to these concerns,

Terry Gregston
Environmental Protection Specialist
Bureau of Land Management
620 E. Greene St.
Carlsbad, NM 88220
Office (575) 234-5958
Cell (575) 361-2635
Fax (575) 234-5927

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

Spill-Saltwater 0 7805

Spill-Other 0 5401

TURNER B.#052



029

Spill-Oil and Saltwater 0 1004

