

District I  
1625 N French Dr , Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr , Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

n MCB 1207650453 OPERATOR  Initial Report  Final Report

Name of Company	Oxy Permian Ltd. <i>116696</i>	Contact	Chancey Summers
Address	1017 W. Stanolind Road; Hobbs, NM 88240	Telephone No.	575-397-8216
Facility Name	Cypress 34 Federal 4H	Facility Type	Well Site
Surface Owner	BLM	Mineral Owner	
		Lease No.	NM-86024, API#30-015-35742

**LOCATION OF RELEASE**


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	34	23S	29E	480'	N	560'	W	Eddy County, NM

Latitude 32.26677° Longitude 103.97932°

**NATURE OF RELEASE**

Type of Release	Oil & Produced water	Volume of Release	45 bbls	Volume Recovered	0 bbls
Source of Release	Overflow of Tank at Well during flowback	Date and Hour of Occurrence	01/30/2012 @ 7:00 a.m.	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Chancey Summers	Mike Bratcher-OCD, James Amos- BLM			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input type="checkbox"/> No	Date and Hour	02/16/2012 @ 11:33 a.m.		
		If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

During flowback, the tank overflowed causing a leak of 45 bbls of oil. 40 bbls were recovered.

Describe Area Affected and Cleanup Action Taken.\*

Remediate to NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Chancey Summers	Approved by District Supervisor:	
Title: HES Specialist	Approval Date: <b>APR 05 2012</b>	Expiration Date:
E-mail Address: chancey_summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>3-22-12</b> Phone: (575) 397-8216	Remediation per OCD Rules & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 5/5/2012</b>	

\* Attach Additional Sheets If Necessary


*2 RP-1081*



PHONE (575) 397-6388 • FAX (575) 397- 0397 • 1324 W MARLAND • P.O BOX 805 • HOBBS, NM 88241-0805  
E-MAIL cbrunson@bbcinternational.com

---

March 22, 2012



Mr. Mike Bratcher  
New Mexico Oil Conservation Division  
811 S. First Street  
Artesia, NM 88210

Re: Oxy Initial C-141 Notifications for AMAX 24 #8 CTB, Cypress 34 Federal 4H, and  
Riverbend B-11 Battery

Dear Mr. Bratcher:

On behalf of Oxy USA, BBC International, Inc. is pleased to enclose the initial C-141 notifications for the above referenced sites for your records.

Please let us know if you require any additional information.

Sincerely,

A handwritten signature in black ink, appearing to read "Cliff P. Brunson". The signature is fluid and cursive, with a long horizontal stroke extending to the right.

Cliff P. Brunson  
President

Enclosures

## Bratcher, Mike, EMNRD

---

**From:** Chancey\_Summers@oxy.com  
**Sent:** Thursday, February 16, 2012 11:33 AM  
**To:** Chancey\_Summers@oxy.com; Dusty\_Wilson@oxy.com; Bratcher, Mike, EMNRD; jamos@blm.gov  
**Cc:** cbrunson@bbcinternational.com; kswinney@bbcinternational.com  
**Subject:** Amax 24 # 8 and Cypress 34 Federal 4H

All, this email is to inform you of a Reportable leak that Oxy Permian had at the Amax 24 # 8 on January 24, 2012 . Total release was 30 bbls of oil and water mix, with 0 recovered. The leak was due to failure of end cap on rental Frac Tank. Battery is located in Section 24, Township 23s, and Range 31E of Eddy County. Oxy will be performing some initial clean up of the surface soils and gathering soil samples to be tested for impact in the near future. A C-141 will follow.

Oxy had an additional reportable leak at the Cypress 34 Fed 4H on January 30, 2012 . Total release was 45 bbls of oil and water mix, with 0 recovered. The leak was due to overfilling of tank during flowback . Battery is located in Unit D Section 34, Township 23s, and Range 29E of Eddy County. Oxy will be performing some initial clean up of the surface soils and gathering soil samples to be tested for impact in the near future. A C-141 will follow. If you have any questions feel free to reply.

Thank You

C.J. Summers

HES Specialist

Cell # 575-631-9436

Office # 575-397-8216

[Chancey\\_Summers@oxy.com](mailto:Chancey_Summers@oxy.com)

"When the blind lead the blind, get out of the way!"