


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nJM/1301556273

Name of Company Oxy Permian Ltd. <i>P2463</i>		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address 1502 W. Commerce Dr., Carlsbad, NM		Contact Christopher Jones		
Facility Name Jones Canyon 4 Federal #4		Telephone No. (575) 628-4121		
Facility Type				
Surface Owner		Mineral Owner	Lease No. API#30-015-30487	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	4	22S	24E					Eddy County, NM

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 500 bbls	Volume Recovered 50 bbls
Source of Release Failure in 2" steel production line	Date and Hour of Occurrence 12/13/2012	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher- OCD, James Amos-BLM, Terry Gregston-BLM	
By Whom? Christopher Jones	Date and Hour 12/13/2012 @ 11:20am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Failure in a 2" steel production line caused 500 bbls of produced water to leak onto the ground. 50 bbls of produced water were recovered via vacuum truck.

Describe Area Affected and Cleanup Action Taken.*

Failure in a 2" steel production line caused 500 bbls of produced water to leak onto the ground. 50 bbls of produced water were recovered via vacuum truck. Remediation will be performed in accordance with an OCD-approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:	Approved by District Supervisor:	
Printed Name: Christopher Jones	Approval Date: JAN 15 2013	Signed By:
Title: HES Specialist	Expiration Date:	Attached <input type="checkbox"/>
E-mail Address: Christopher.Jones@oxy.com	Conditions of Approval:	
Date: <i>1-3-13</i> Phone: (575) 628-4121		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: February 15, 2013**

2RP-1494

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Thursday, January 03, 2013 10:22 AM
To: Bratcher, Mike, EMNRD; jamos@blm.gov; tgregsto@blm.gov
Cc: christopher_jones@oxy.com; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Initial C-141 for Jones Canyon 4 Federal #4
Attachments: Initial C-141, signed and sent 1-3-13.pdf

Attached is the initial C-141 for a leak occurring at the Jones Canyon 4 Federal #4 on 12/13/2012 in Eddy County, NM. Receipt notification via email is greatly appreciated. If you have any questions, feel free to contact me.

Kathy Purvis

BBC International, Inc.

1324 W. Marland

Hobbs, NM 88240

Phone: (575) 397-6388

Fax: (575) 397-0397

Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From: Amos, James <jamos@blm.gov>
Sent: Thursday, January 03, 2013 1:11 PM
To: Kathy Purvis
Cc: Bratcher, Mike, EMNRD; tgregsto@blm.gov; christopher_jones@oxy.com; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Re: Initial C-141 for Jones Canyon 4 Federal #4

Received. Provide a copy of the water analysis of the spilled fluids and a schematic of the spill location and the flow path. thanks

On Thu, Jan 3, 2013 at 10:21 AM, Kathy Purvis <kathy@bbcinternational.com> wrote:

Attached is the initial C-141 for a leak occurring at the Jones Canyon 4 Federal #4 on 12/13/2012 in Eddy County, NM. Receipt notification via email is greatly appreciated. If you have any questions, feel free to contact me.

Kathy Purvis

BBC International, Inc.

1324 W. Marland

Hobbs, NM 88240

Phone: (575) 397-6388

Fax: (575) 397-0397

Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From: Christopher_Jones@oxy.com
Sent: Thursday, December 13, 2012 11:20 AM
To: Bratcher, Mike, EMNRD; jamos@blm.gov; Terry_Gregston@blm.gov
Cc: cbrunson@bbcinternational.com; kswinney@bbcinternational.com; kathy@bbcinternational.com
Subject: Jones Canyon 4 Fed 4

This is to inform you that Oxy Permian Primary had a spill of produced water at the Jones Canyon 4 Fed 4 on December 13, 2012. Oxy released 500 bbls of produced water, 50 bbls was recovered. Leak was due to failure in the 2" steel production line. Oxy will have BBC do some initial remediation, a C-141 to follow. BBC will delineate at a later date. REGULATORY LEASE # NM 83037 2714 FNL 271 FWL SECT 4 T25S R24E EDDY COUNTY NEW MEXICO OUT OF CARLSBAD GO NORTH ON 285 TURN LEFT ON SITTING BULL HWY TO MILE MARKER 42 GO LEFT TO TOP OF MOUNTAIN TURN LEFT TO MAGOOLTEE PEAK COMPRESSOR 1/2 MILE TAKE 1ST RIGHT.

Chris Jones
HES Specialist
Permian Primary Production
Carlsbad, NM
Cell 575-499-3337
Off 575-628-4121

"We do not inherit the earth from our ancestors; we borrow it from our children." Chief Seattle