

**RECEIVED**  
 MAR 12 2013  
 NMOC D ARTESIA

Form C-141  
 Revised October 10, 2003

District I  
 1625 N. French Dr., Hobbs, NM 88240  
 District II  
 1301 W. Grand Avenue, Artesia, NM 88210  
 District III  
 1000 Rio Brazos Road, Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy Minerals and Natural Resources  
 Oil Conservation Division  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

Submit 2 copies to appropriate  
 District Office in accordance  
 with Rule 116 on back  
 side of form

**Release Notification and Corrective Action**

*JMW 1308553143* OPERATOR  Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	16696	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM		Telephone No.	(575) 397-8216
Facility Name	Pure Gold A Federal #2 Battery		Facility Type	Gathering

Surface Owner	BLM	Mineral Owner		Lease No.	NM 38464
---------------	-----	---------------	--	-----------	----------

**LOCATION OF RELEASE** \*APT: 30-015-27243

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	21	23S	31E					Eddy

Latitude N 32.28428° Longitude W 103.79005

**NATURE OF RELEASE**

Type of Release	Oil and Produced water	Volume of Release	15 bbls water and 0.5 bbls skin oil	Volume Recovered	7 bbls
Source of Release	Flex Coupling broke on water transfer pump	Date and Hour of Occurrence	2/08/13	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Miko Bratcher- OCD; James Amos & Jennifer Van Curen- BLM		
By Whom?	Chancey Summers	Date and Hour	2/11/13 @ 7:29 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
 Flex coupling on a water transfer pump broke and caused 15 bbls of water and 0.5 bbl of skin oil to leak onto the ground. 7 bbls of fluid were recovered via vacuum truck. The coupling was repaired.

Describe Area Affected and Cleanup Action Taken.\*  
 Flex coupling on a water transfer pump broke and caused 15 bbls of water and 0.5 bbl of skin oil to leak onto the ground. 7 bbls of fluid were recovered via vacuum truck. The coupling was repaired. Remediation will be performed in accordance with an OCD and BLM approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Chancey Summers	Approved by District Supervisor:	Signed By <i>Miko Bratcher</i>
Title:	HES Specialist	Approval Date:	<b>MAR 26 2013</b> Expiration Date:
E-mail Address:	Chancey.Summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	<i>3-12-13</i> Phone: (575) 397-8216		

\* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines. **SUBMIT REMEDIATION**

**PROPOSAL NO LATER THAN:**  
*April 26, 2013*

*ZRP-1588*

## Bratcher, Mike, EMNRD

---

**From:** Kathy Purvis <kathy@bbcinternational.com>  
**Sent:** Tuesday, March 12, 2013 2:49 PM  
**To:** Bratcher, Mike, EMNRD; jamos@blm.gov; jvancure@blm.gov  
**Cc:** C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com  
**Subject:** Initial C-141s for two leaks at the Pure Gold A Federal #2 Battery  
**Attachments:** Initial C-141, signed and sent 3-12-13 leak 1.pdf; Initial C-141, signed and sent 3-12-13 leak 2.pdf

Attached are the initial C-141s for two leaks located at the Pure Gold A Federal #2 Battery on 02/08/2013 and 03/05/2013 in Eddy County, NM. Receipt notification via email is greatly appreciated. Please contact me if you have any questions.

*Kathy Purvis*

BBC International, Inc.  
1324 W. Marland  
Hobbs, NM 88240  
Phone: (575) 397-6388  
Fax: (575) 397-0397  
Email: [kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)

## Bratcher, Mike, EMNRD

---

**From:** Chancey\_Summers@oxy.com  
**Sent:** Monday, February 11, 2013 7:29 AM  
**To:** Chancey\_Summers@oxy.com; Bratcher, Mike, EMNRD; jamos@blm.gov; jvancure@blm.gov; cbrunson@bbcinternational.com; jgilkey@bbcinternational.com; kathy@bbcinternational.com; kswinney@bbcinternational.com  
**Subject:** PURE GOLD A FED 2 BATTERY

This is to inform you that Oxy Permian Primary had a produced water/oil leak on the PURE GOLD A FED 2 BATTERY on Friday February 18, 2013. Oxy released 15 bbls of water, and .5 barrels of skim oil due to SIZE 7 LOVEJOY FLEX COUPLING BROKE ON WATER TRANSFER PUMP. 7 barrels of fluid was recovered. The battery is located in SECT 21 T23S R31E of Eddy County. Oxy will do some initial remediation, a C-141 to follow. BBC International will delineate at a later date. Driving directions: OFF HWY 128 GO SOUTH ON PURE GOLD RD, 1ST BATTERY ON THE LEFT. If you have any questions let me know

Thank You  
C.J. Summers  
HES Advisor  
Cell # 575-631-9436  
Office # 575-397-8216  
[Chancey\\_Summers@oxy.com](mailto:Chancey_Summers@oxy.com)<mailto:Chancey\_Summers@oxy.com>  
"When the blind lead the blind, get out of the way!"

**Bratcher, Mike, EMNRD**

---

**From:** Van Curen, Jennifer <jvancure@blm.gov>  
**Sent:** Monday, February 11, 2013 7:30 AM  
**To:** Chancey\_Summers@oxy.com  
**Cc:** Bratcher, Mike, EMNRD; jamos@blm.gov; cbrunson@bbcinternational.com; jgilkey@bbcinternational.com; kathy@bbcinternational.com; kswinney@bbcinternational.com  
**Subject:** Re: PURE GOLD A FED 2 BATTERY

Thanks

JENNIFER E VAN CUREN  
ENVIRONMENTAL PROTECTION SPECIALIST  
DOI-BLM-CARLSBAD FIELD OFFICE  
320 E GREENE ST. CARLSBAD, NM 88220  
OFFICE- 575-234-5905  
CELL - 575-361-0042  
FAX - 575-234-5927

On Mon, Feb 11, 2013 at 7:28 AM, <[Chancey\\_Summers@oxy.com](mailto:Chancey_Summers@oxy.com)> wrote:

This is to inform you that Oxy Permian Primary had a produced water/oil leak on the PURE GOLD A FED 2 BATTERY on Friday February 18, 2013. Oxy released 15 bbls of water, and .5 barrels of skim oil due to SIZE 7 LOVEJOY FLEX COUPLING BROKE ON WATER TRANSFER PUMP. 7 barrels of fluid was recovered. The battery is located in SECT 21 T23S R31E of Eddy County. Oxy will do some initial remediation, a C-141 to follow. BBC International will delineate at a later date. Driving directions: OFF HWY 128 GO SOUTH ON PURE GOLD RD, 1ST BATTERY ON THE LEFT. If you have any questions let me know

Thank You

C.J. Summers

HES Advisor

Cell # 575-631-9436

Office # 575-397-8216

[Chancey\\_Summers@oxy.com](mailto:Chancey_Summers@oxy.com)<[mailto:Chancey\\_Summers@oxy.com](mailto:Chancey_Summers@oxy.com)>

"When the blind lead the blind, get out of the way!"