

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW 1326647545

OPERATOR Initial Report Final Report

Name of Company	Enterprise Field Services LLC <i>1000347</i>	Contact:	Jim Heap
	PO Box 4324, Houston, TX 77252	Telephone No.	432-686-5404
Facility Name	Pipeline ROW, Trunk A Line <i>9/1/13</i>	Facility Type:	Gas Gathering Pipeline
Surface Owner	Multiple Owners	Mineral Owner	NA
		Lease No.	NA

Surface Owner Fed/BLM


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	20	23S	31E					Eddy

Latitude: 32.283627 N Longitude: -103.795482 W

NATURE OF RELEASE

Type of Release	Natural Gas, minimal pipeline liquids	Volume of Release	128 MCF	Volume Recovered	0
Source of Release	Pipeline Leak	Date and Hour of Occurrence (Start)	09-01-2013 17:00 MDT	Date and Hour of Discovery (End)	09-12-2013 09:30 MDT
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* *Initial Report*
Suspected internal corrosion. The affected section of the 6-inch line was isolated. Producers were notified of production shut down. Line was blown-down, repairs are scheduled. A small amount of liquids (< 5BBL) were released; BLM was notified. A final report will be submitted on completion of the repair.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jon E. Fields</i>	OIL CONSERVATION DIVISION	
Printed Name: Jon E. Fields	Approved by District Supervisor Signed By <i>Mike Brannon</i>	
Title: Director - Field Environmental	Approval Date: SEP 23 2013	Expiration Date:
E-mail Address: jefields@eprod.com	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: Phone: 713-381-6595		

* Attach Additional Sheets If Necessary

fJMW 1326641638

PROPOSAL NO LATER THAN:
October 23, 2013

2RP-1925


iJMW 1326649235



ENTERPRISE PRODUCTS PARTNERS L.P.
ENTERPRISE PRODUCTS HOLDINGS LLC
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

September 16, 2013



7012 3460 0001 7235 6052
Return Receipt Requested

Mr. Mike Bratcher
New Mexico Oil Conservation Division
District 2 Office
811 South First Street
Artesia, New Mexico 88210

**RE: Form C-141 Report for Enterprise Products
Gas Loss Reported in the Carlsbad Gathering Field**

Mr. Bratcher:

Pursuant to 29 (19.15.29) NMAC please find enclosed the requisite C-141 Form for the September 12, 2013 release from our Trunk A gathering line in our Carlsbad Gathering Field, Eddy County. The leak is a suspected internal corrosion failure.

If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at jkheap@eprod.com or me at 713-318-6595.

Regards,

Jon E. Fields
Director, Field Environmental

/sjn
attachments