


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nJMW1326040559 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Down South State Com #001H	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-41442

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	19	26S	28E					Eddy

Latitude Longitude

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	25bbbls	Volume Recovered	20bbbls
Source of Release	Fitting on transfer pump	Date and Hour of Occurrence	09-05-2013	Date and Hour of Discovery	09-05-2013 5:00pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	09-06-2013 3:34pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A hole developed on the bottom of a 3" Victualic clamp. Replaced the Victualic Clamp with a new one.

Describe Area Affected and Cleanup Action Taken.*

Initially 25bbbls of produced water were released due to a hole that developed on the bottom of the Victualic clamp caused by corrosion. We were able to recover 20bbbls of produced water with a vacuum truck. The entire release was contained inside the lined facility. All free fluid has been recovered. Contaminated gravel has been removed and we have replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.


Signature:	<i>Robert Grubbs Jr.</i>	OIL CONSERVATION DIVISION	
Printed Name:	Robert Grubbs Jr.	Approved by District Supervisor:	Signed By <i>Michele Bratcher</i>
Title:	Senior Environmental Coordinator	Approval Date:	SEP 17 2013
E-mail Address:	rgrubbs@concho.com	Expiration Date:	
Date:	09-05-2013	Phone:	432-661-6601
Conditions of Approval:		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-1910

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Tuesday, September 10, 2013 3:07 PM
To: Bratcher, Mike, EMNRD
Cc: Robert McNeill
Subject: C-141's Initial - Final Reports - Sidewinder #001H, F.U.N. State Com #001H, Down South State Com #001H and the Patton 5 Fee #002H
Attachments: Sidewinder #001H (Tank Battery) -- Date of Release --09-03-2013.pdf; F.U.N. State Com #001H (Tank Battery) -- Date of Release -- 09-05-2013.pdf; Down South State Com #001H (Tank Battery) -- Date of Release -- 09-10-2013.pdf; Patton 5 Fee #002H (Tank Battery) -- Date of Release -- 09-10-2013.pdf



Mr. Bratcher,

Please see attached the C-141 Initial Reports for the following releases that occurred at our Sidewinder #001H, F.U.N. State Com #001H, Down South State Com #001H and the Patton 5 Fee #002H in Eddy County New Mexico. These are lined facilities.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Michelle Mullins <MMullins@concho.com>
Sent: Friday, September 06, 2013 2:34 PM
To: Bratcher, Mike, EMNRD
Cc: Robert Grubbs
Subject: Down South State #4H-Immediate Notification

Mr. Bratcher:

At approximately 5:00 p.m. on 9/5/2013, a produced fluid release was discovered at the above-referenced facility. An estimated 25 barrels of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report. GPS coordinates, driving directions and legal description is below.

32.02223 104.11917

Down South State #4H
Unit P Sec. 19 T26S R28E
660' FSL & 330' FEL
Eddy County, NM
API 30-015-37256

Thank you.

Michelle Mullins
HSE Field Technician
COG Operating, LLC
(432) 934-1052
mmullins@concho.com

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.