


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources



Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

*NJMW 1402149370*

**OPERATOR**

Initial Report  Final Report

Name of Company	Oxy Permian Ltd. <i>192463</i>	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Old Ranch Canyon 7 Federal #5y	Facility Type	Well Location

Surface Owner	BLM	Mineral Owner		API No.	30-015-30653
---------------	-----	---------------	--	---------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	7	22S	24E	1315	North	2315	West	Eddy County, NM

Latitude N 32.40886° Longitude W 104.53740°

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	15 bbls	Volume Recovered	5 bbls
Source of Release	Failure of a Victaulic clamp on a 1.5" steel line	Date and Hour of Occurrence	12/20/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	M. Bratcher, J.M. Warren- OCD, J. Amos, J. Van Curen- BLM		
By Whom?	Christopher Jones	Date and Hour	12/20/2013 @ 3:33 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
The failure of a Victaulic clamp on a 1.5" steel line caused 15 bbls of produced water to leak onto the ground. 5 bbls of produced water were recovered via vacuum truck and the clamp was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.\*  
The affected area is approximately 50' x 150'. Remediation will be completed in accordance with a plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Christopher Jones	Approved by District Supervisor: Signed By	
Title:	HES Specialist	Approval Date:	<b>JAN 21 2014</b>
E-mail Address:	Christopher.Jones@oxy.com	Expiration Date:	
Date:	<i>1/9/14</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	(575) 628-4121	Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	

\* Attach Additional Sheets If Necessary

**February 21, 2014**

**2RP-2153**

## Warren, JeanMarie, EMNRD

---

**From:** Kathy Purvis <kathy@bbcinternational.com>  
**Sent:** Thursday, January 09, 2014 9:20 AM  
**To:** Bratcher, Mike, EMNRD; Warren, JeanMarie, EMNRD; jamos@blm.gov; jvancure@blm.gov  
**Cc:** christopher\_jones@oxy.com; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com  
**Subject:** Initial C-141, Old Ranch Canyon 7 Federal #5Y  
**Attachments:** Initial C-141, Old Ranch Canyon 7 Fed #5Y.pdf

Attached is the initial C-141 for a leak that occurred at the Old Ranch Canyon 7 Federal #5Y on 12/20/2013 in Eddy County, NM. Receipt notification via email is greatly appreciated.

*Kathy Purvis*

BBC International, Inc.  
1324 W. Marland  
Hobbs, NM 88240  
Phone: (575) 397-6388  
Fax: (575) 397-0397  
Email: [kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)

**Warren, JeanMarie, EMNRD**

---

**From:** Christopher\_Jones@oxy.com  
**Sent:** Friday, December 20, 2013 3:33 PM  
**To:** Bratcher, Mike, EMNRD; Warren, JeanMarie, EMNRD; jamos@blm.gov; jvancure@blm.gov; Tiffney\_Burkham@oxy.com; kswinney@bbcinternational.com; cbrunson@bbcinternational.com; jgilkey@bbcinternational.com; kathy@bbcinternational.com  
**Subject:** Leak

This is to inform you that Oxy had a leak at the old ranch canyon 7 fed 5y 12-20-13. We put 15 bbls of produced water out on the ground and recovered 5 bbls. Bbc will be doing some initial delineation and a c141 will follow. Leak information is below;

VICTAULIC CLAMP ON 1.5 INCH STEEL LINE ON DISCHARGE SIDE LEAK IS AT THE HORIZONTAL VESSEL ESTIMATED DAILY PRODUCTION LOSS IS N/A NORMAL OPERATING PRESSURE IS UNKNOWN BY CALLER VOLUME OF LEAK IS 15 BBLS WATER SURFACE AREA IS 50 X 150 FT FURTHER REMEDIATION IS NECESSARY YES H2S NON SENSITIVE AREA NO PUBLIC EXPOSURE NO LANDMARK LEAK IS ABOVE GROUND SURFACE OWNER/LEASEE UNKNOWN BY CALLER LEASE NUMBER NM 81219 EDDY COUNTY NEW MEXICO SEC 7 T22S R24E FROM CARLSBAD NM GO NORTH ON HWY 285 TURN LEFT ON HWY 137 THEN FOLLOW TO MILE MARKER 42 TURN LEFT AT THE OXY SIGN GO .5 MILE THE LOCATION IS ON THE RIGHT

Chris Jones  
HES Specialist  
Permian Primary Production  
Carlsbad, NM  
Cell 575-499-3337  
Off 575-628-4121

"We do not inherit the earth from our ancestors; we borrow it from our children." Chief Seattle

## Bratcher, Mike, EMNRD

---

**From:** Christopher\_Jones@oxy.com  
**Sent:** Friday, December 20, 2013 3:33 PM  
**To:** Bratcher, Mike, EMNRD; Warren, JeanMarie, EMNRD; jamos@blm.gov; jvancure@blm.gov; Tiffney\_Burkham@oxy.com; kswinney@bbcinternational.com; cbrunson@bbcinternational.com; jgilkey@bbcinternational.com; kathy@bbcinternational.com  
**Subject:** Leak

This is to inform you that Oxy had a leak at the old ranch canyon 7 fed 5y 12-20-13. We put 15 bbls of produced water out on the ground and recovered 5 bbls. Bbc will be doing some initial delineation and a c141 will follow. Leak information is below;

VICTAULIC CLAMP ON 1.5 INCH STEEL LINE ON DISCHARGE SIDE LEAK IS AT THE HORIZONTAL VESSEL ESTIMATED DAILY PRODUCTION LOSS IS N/A NORMAL OPERATING PRESSURE IS UNKNOWN BY CALLER VOLUME OF LEAK IS 15 BBLS  
WATER SURFACE AREA IS 50 X 150 FT  
FURTHER REMEDIATION IS NECESSARY  
YES H2S  
NON SENSITIVE AREA  
NO PUBLIC EXPOSURE  
NO LANDMARK  
LEAK IS ABOVE GROUND  
SURFACE OWNER/LEASEE UNKNOWN BY CALLER  
LEASE NUMBER NM 81219  
EDDY COUNTY NEW MEXICO SEC 7 T22S R24E  
FROM CARLSBAD NM GO NORTH ON HWY 285 TURN LEFT ON HWY 137 THEN FOLLOW TO MILE MARKER 42 TURN LEFT AT THE OXY SIGN GO .5 MILE THE LOCATION IS ON THE RIGHT

Chris Jones  
HES Specialist  
Permian Primary Production  
Carlsbad, NM  
Cell 575-499-3337  
Off 575-628-4121

"We do not inherit the earth from our ancestors; we borrow it from our children." Chief Seattle