

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION
State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

NOV 10 2014
RECEIVED

FAB1501443511
NAB1501443670

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company <i>Enterprise Field Services LLC</i>		Contact <i>Dina Babinski</i>
Address <i>PO Box 4324, Houston TX 77252</i>		Telephone No. <i>210-528-3824</i>
Facility Name <i>Pipeline ROW, O8707M Gathering Lateral</i>		Facility Type <i>Gas Gathering Pipeline</i>
Surface Owner <i>Bureau of Reclamation</i>	Mineral Owner <i>NA - Pipeline</i>	API No. <i>NA</i>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>L 22</i>	<i>3</i>	<i>21S</i>	<i>26E</i>	<i>13</i>	<i>North</i>	<i>528</i>	<i>East</i>	<i>Eddy</i>

Latitude *N 32.520097* Longitude *W -104.282174*

NATURE OF RELEASE

Type of Release <i>Natural Gas</i>	Volume of Release <i>181 MCF</i>	Volume Recovered <i>NA</i>
Source of Release <i>Pipeline Leak and Blowdown</i>	Date and Hour of Occurrence <i>10/24/2014 @ 13:53 MDT</i>	Date and Hour of Discovery <i>10/10/2014 @ 13:53 MDT</i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Pipeline leak was detected by a third party pumper passing by. An unaffiliated vehicle backed into the tie-in vent valve causing a vapor leak. The leaking portion was isolated, and pipeline section was blown down to carry out repair activities immediately. Repair of the tie-in was complete on the same day.

Describe Area Affected and Cleanup Action Taken.*

No liquid spills occurred requiring any cleanup actions.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: <i>Jon E. Fields</i>	Approved by: 	
Title: <i>Director, Field Environmental</i>	Approval Date: <i>11/4/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>jefields@eprod.com</i>	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>
Date: <i>11-5-2014</i> Phone: <i>713-381-6684</i>		

* Attach Additional Sheets If Necessary

2 RP-2738



ENTERPRISE PRODUCTS PARTNERS L.P.
ENTERPRISE PRODUCTS HOLDINGS LLC
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

November 5, 2014

NM OIL CONSERVATION
ARTESIA DISTRICT

NOV 10 2014

7014 1200 0001 0918 2307
Return Receipt Requested

RECEIVED

Mr. Mike Bratcher
New Mexico Oil Conservation Division
District 2 Office
811 South First Street
Artesia, New Mexico 88210

**RE: Form C-141 Report for Enterprise Field Services LLC
Releases on Carlsbad Area Gathering Lines**

Dear Mr. Bratcher:

Enclosed, please find the required C-141 Form for the pipeline leak and blowdown on our 1005-O87O7M tie-in in Eddy County on October 24, 2014. The pipeline leak was detected by an Enterprise employee, and immediate repair activities were carried out to avoid further gas losses. This report is sent pursuant to NMAC 19.15.29 requirements for minor leaks.

If you have any questions or need additional information, please contact Dina Babinski, our area Environmental Supervisor at 210-528-3824 or by email at djbabinski@eprod.com, or me directly at 713-318-6684.

Yours truly,

Jon E. Fields
Director-Field Environmental

/bjm
Attachment