

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUL 14 2015

Form C-141
Revised August 8, 2011

Submit a Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1520127947 **OPERATOR** Initial Report Final Report

Name of Company: BOPCO, L.P. 8601737	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Indian Flats Bass Federal SWD (SWD is located 2996 ft. SW of Well #1 API 30-015-24968)	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-24968	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	35	21S	28E	1652	South	2150	East	Eddy

Latitude 32.434071° Longitude -104.055193°

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	13 bbls PW	Volume Recovered	1 bbl PW
Source of Release	Water transfer line	Date and Hour of Occurrence	7/13/2015 hour unknown	Date and Hour of Discovery	7/13/2015 at 8:30 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	N/A		
By Whom?	N/A	Date and Hour	N/A		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Surface steel water line developed a pinhole due to corrosion and produced water was released onto the well pad. The line was clamped, then isolated and repaired.

Describe Area Affected and Cleanup Action Taken.*

Leak affected 334 square feet of well pad within the bermed and fenced area. Vacuum truck recovered standing fluids. Impacted area was covered with plastic to prevent downward migration until addressed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amy Ruth	Approved by Environmental Specialist: 	
Title: Assistant Remediation Foreman	Approval Date: 7/14/15	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/14/2015 Phone: 432-661-0571	Remediation per O.C.D. Rules & Guidelines	

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 8/20/15

2RD-3129

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>
Sent: Tuesday, July 14, 2015 3:20 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: jamos@blm.gov
Subject: Initial C-141 - Indian Flats Bass Federal SWD (7-13-2015)
Attachments: Initial C-141 - Indian Flats Bass Fed SWD (7-13-2015).pdf

Please find the attached initial form C-141 for this leak and call me with any questions/concerns. Thanks ☺



Amy C. Ruth

BOPCO, L.P.

EH&S Remediation Specialist

522 W. Mermod, Suite 704

Carlsbad, NM 88220

Office: (575)887-7329

Fax: (575)887-7473

Cell: (432)661-0571