

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1534657219

Name of Company Burnett Oil Co. Inc. 3080		Contact Leslie Garvis
Address Burnett Plaza - Ste 1500, 801 Cherry St - Unit 9, Ft. Worth, TX 76102		Telephone No. 817-583-8730
Facility Name Gissler A 13		Facility Type Injection Well
Surface Owner BLM	Mineral Owner BLM	API No. 30-015-25683

Initial Report Final Report

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	14	17S	30E	660	North	1980	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 40 bbls	Volume Recovered 35 bbls
Source of Release Leak in Injection Line	Date and Hour of Occurrence 12/10/15 0800	Date and Hour of Discovery 12/10/15 0800
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM - S. Tucker, OCD - H. Patterson	
By Whom? Leslie Garvis	Date and Hour 1249 12/10/15	NM OIL CONSERVATION ARTESIA DISTRICT DEC 10 2015 RECEIVED
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

Describe Cause of Problem and Remedial Action Taken.*
One inch buried injection line from waterflood to injection well ruptured. Operator was on site when pipe ruptured and the pump at the water station was immediately turned off. The line was repaired and well was returned to injection.

Describe Area Affected and Cleanup Action Taken.*
Shallow berms were dug in order to contain the release on the location therefore the produced water did not leave the well pad. A vac truck was used to collect the produced water and 35 bbls were recovered. Remediation will begin as per BLM & OCD standards once remediation plan has been approved.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Leslie Garvis</i>	OIL CONSERVATION DIVISION	
Printed Name: Leslie Garvis	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Regulatory Coordinator	Approval Date: 12/11/15	Expiration Date: N/A
E-mail Address: igarvis@burnettoil.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/10/15 Phone: 817-583-8730	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 11/5/16**

2RD-3443

Patterson, Heather, EMNRD

From: Leslie Garvis <lgarvis@burnettoil.com>
Sent: Thursday, December 10, 2015 4:20 PM
To: Shelly Tucker (shelly@hudsonoil.com); Patterson, Heather, EMNRD
Cc: Walter Glasgow; Brady Sullivan; Trey Krampf; Belton Mathews; Johnny Titsworth; Kyle Adams
Subject: Release at the Gissler A 13 Injection Well | API # 30-015-25683
Attachments: 2015.12.10 GA13 C141_Smtd.pdf

Shelly/Heather,

As per my earlier phone call, attached you will find the initial C-141 for the release at the Gissler A 13.

Please let us know if you have any questions or need any additional information.

Thank you,

LESLIE M. GARVIS
REGULATORY COORDINATOR

BURNETT OIL Co., INC.
BURNETT PLAZA-SUITE 1500
801 CHERRY STREET - UNIT #9
FORT WORTH, TX 76102-6881
DIRECT LINE: 817.583.8730
MOBILE: 713.819.4371
FAX: (817) 332-2438
EMAIL: LGARVIS@BURNETTOIL.COM

This message is intended only for the person(s) to which it is addressed and may contain privileged, confidential and/or insider information. If you have received this communication in error, please notify us immediately by replying to the message and deleting it from your computer. Any disclosure, copying, distribution, or the taking of any action concerning the contents of this message and any attachment(s) by anyone other than the named recipient(s) is strictly prohibited.