

**Leking, Geoffrey R, EMNRD**

---

**From:** Hill, Larry, EMNRD  
**Sent:** Wednesday, June 01, 2011 10:18 AM  
**To:** Leking, Geoffrey R, EMNRD  
**Cc:** Gonzales, Elidio L, EMNRD  
**Subject:** FW: Flamenco Federal #1 (1RP-2281)

**HOBBS OCD**

**JUN 01 2011**

Geoff;

**RECEIVED**

Please take a look at this and let me know where we stand on this site.

Thanks;

LARRY W. 'BUDDY' HILL  
DISTRICT SUPERVISOR  
EMNRD - OCD DISTRICT I  
1625 N. FRENCH DRIVE  
HOBBS, NM 88240  
OFFICE: 575-393-6161 X-102  
CELL: 575-370-3180 FAX: 575-393-0720  
[LARRY.HILL@STATE.NM.US](mailto:LARRY.HILL@STATE.NM.US)

-----Original Message-----

**From:** Bob Asher [<mailto:BobA@yatespetroleum.com>]  
**Sent:** Wednesday, June 01, 2011 9:58 AM  
**To:** Hill, Larry, EMNRD  
**Cc:** Jerry Fanning  
**Subject:** FW: Flamenco Federal #1 (1RP-2281)

Buddy,

Yates has requested an extension with the BLM on restoration/reseeding work at the above location until July 1, 2011. This is in conjunction to a release that occurred on 8/11/2009, impacted soils were excavated and sample results are below RRAL's for the site ranking of zero (depth to ground water is zero). A Final C-141 and supporting documents were submitted on April 13, 2010. With the BLM's request to have this site restored/reseeded this summer, if there are no objections, Yates will begin work on June 15, 2011 which includes backfilling with clean soils to create a 3' cap of the excavation area and reseed with a BLM #2 seed mixture. Yates plans to have this project to be completed on or before by July 1, 2011 to take advantage of future monsoonal rains.

If you have any questions, please contact me.

Thank you.

Robert Asher  
Yates Petroleum Corporation  
Office: (575) 748-4217  
Cell: (575) 365-4021  
Fax: (575) 748-4662  
[boba@yatespetroleum.com](mailto:boba@yatespetroleum.com)

-----Original Message-----

**From:** Bob Asher

Sent: Wednesday, June 01, 2011 9:26 AM  
To: 'jamos@blm.gov'  
Cc: Jerry Fanning  
Subject: RE: Flamenco Federal #1 (1RP-2281)

Jim,

Yates Petroleum Corporation would like to request an extension on restoration work on the SE corner of the location and the release area (west of pad) in preparation of reseeding until July 1, 2011.

Thank you.

Robert Asher  
Yates Petroleum Corporation  
Office: (575) 748-4217  
Cell: (575) 365-4021  
Fax: (575) 748-4662  
[boba@yatespetroleum.com](mailto:boba@yatespetroleum.com)

-----Original Message-----

From: [jamos@blm.gov](mailto:jamos@blm.gov) [<mailto:jamos@blm.gov>]  
Sent: Sunday, February 06, 2011 8:38 AM  
To: Bob Asher  
Subject: Flamenco Federal 1

Bob,

I received your E-mail dated 12/14/10 showing the work completed. I finally got around to look at the completion. Al has not completed the job as per our onsite of 11/3/10. We were going to rebuild the berm and fence across the west end. This has not been done as per inspection of 1/16/11. The area outside the fence to the SE has not been touched. I would like to see the restoration of that SE corner as well as the spill area prior to 6/1/11 and seeded prior to the monsoons. If any questions get back to me. Thanks