

NM OIL CONSERVATION
ARTESIA DISTRICT

JUL 27 2016

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1621452433

OPERATOR

Initial Report Final Report

| | |
|---|----------------------------|
| Name of Company: COG Operating LLC <i>229137</i> | Contact: Robert McNeill |
| Address: 600 West Illinois Avenue, Midland TX 79701 | Telephone No. 432-683-7443 |
| Facility Name: FIREFOX 4 FEDERAL COM #005H | Facility Type: Battery |
| Surface Owner: Federal | Mineral Owner: Federal |
| API No. 30-015-41423 | |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| M | 4 | 19S | 31E | 670 | South | 250 | West | Eddy |

Latitude/Longitude 32.684082,-103.8822098

NATURE OF RELEASE

| | | |
|--|---|---|
| Type of Release: Produced Water | Volume of Release: 6 bbls PW | Volume Recovered: 4 bbls PW |
| Source of Release: Battery piping | Date and Hour of Occurrence: 7/20/2016 unknown | Date and Hour of Discovery: 7/20/2016 12:00 pm |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? | |
| By Whom? | Date and Hour: | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a hole in the tee on the load line. A vacuum truck was dispatched to recover free liquids.

Describe Area Affected and Cleanup Action Taken.*

This release occurred in the containment. Concho will have the spill site inspected for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|---|--|-----------------------------|
| Signature: <i>Amanda T. Davis</i> | OIL CONSERVATION DIVISION | |
| Printed Name: Amanda Trujillo Davis | Signed By <i>Mike Brumley</i> | |
| Title: Senior Environmental Coordinator | Approved by Environmental Specialist: | |
| E-mail Address: atrujillo@concho.com | Approval Date: <i>7/28/16</i> | Expiration Date: <i>N/A</i> |
| Date: July 27, 2016 Phone: 575-748-6940 | Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> | |
| SUBMIT REMEDIATION PROPOSAL NO | | |
| LATER THAN: <i>9/2/16</i> | | |

* Attach Additional Sheets If Necessary

2RP-3810

Bratcher, Mike, EMNRD

From: Amanda Trujillo Davis <ATrujillo@concho.com>
Sent: Wednesday, July 27, 2016 7:07 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; James_Amos@blm.gov; Shelly Tucker
Subject: (Notification) FIREFOX 4 FEDERAL COM #005H (30-015-41423)
Attachments: 7-20-2016 Firefox 4 Federal Com #5H (TB) Initial.pdf

Mr. Bratcher/Ms. Tucker,

COG Operating LLC is reporting a release on the FIREFOX 4 FEDERAL COM #005H (30-015-41423)
Unit M Section 4 Township 19S Range 31E
The release occurred at 12:00 pm on 7/20/2016
Released: 6 bbls PW
Recovered: 4 bbls PW

This release was caused by a hole in battery piping. Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo Davis

Senior Environmental Coordinator
COG Operating LLC
Cell: 505.350.1336
Office: 575.748.6930
atrujillo@concho.com

1401 Commerce Drive
Carlsbad, NM 88220



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.