

MAR 06 2018

Form C-141
Revised April 3, 2017

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company	<i>Enterprise Field Services, LLC</i>	Contact	<i>Alena Miro</i>
Address	<i>PO Box 4324, Houston, TX 77210</i>	Telephone No.	<i>575-628-6802</i>
Facility Name	<i>Pipeline ROW, B-7</i>	Facility Type	<i>Natural Gas Pipeline</i>

Surface Owner	<i>BLM</i>	Mineral Owner	<i>N/A</i>	API No.	<i>N/A</i>
---------------	------------	---------------	------------	---------	------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Unit Line	Feet from the	East/West Line	County
<i>B</i>	<i>18</i>	<i>20S</i>	<i>29E</i>	<i>130</i>	<i>North</i>	<i>700</i>	<i>West</i>	<i>Eddy</i>

Latitude *N 32.580296* Longitude *W -104.112435* NAD83

NATURE OF RELEASE

Type of Release	<i>Natural Gas</i>	Volume of Release	<i>259 MCF</i>	Volume Recovered	<i>N/A</i>
Source of Release	<i>Pipeline Release</i>	Date and Hour of Occurrence	<i>2/24/2018 @ 10:00 MDT</i>	Date and Hour of Discovery	<i>2/24/2018 @ 10:00 MDT</i>
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required				
By Whom?	If YES, To Whom?				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
If a Watercourse was Impacted, Describe Fully.* <i>N/A</i>					
Describe Cause of Problem and Remedial Action Taken.* <i>Natural gas was released due to a pipeline leak. Pipeline segment was isolated, blown down, and will be repaired following a standard one-call.</i>					
Describe Area Affected and Cleanup Action Taken.* <i>No pipeline liquids were involved in this release.</i>					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature:	OIL CONSERVATION DIVISION		
Printed Name: <i>Jon E. Fields</i>	Approved by Environmental Specialist: <i>[Signature]</i>		
Title: <i>Director, Field Environmental</i>	Approval Date: <i>3/6/18</i>	Expiration Date: <i>N/A</i>	
E-mail Address: <i>jefields@eprod.com</i>	Conditions of Approval: <i>FINAL</i>		Attached: <i>[Signature]</i>
Date: <i>3/5/2018</i>	Phone: <i>713-381-6684</i>		

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Nolan, Shiver <SNolan@eprod.com>
Sent: Tuesday, March 6, 2018 6:06 AM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Yolanda Jordan (yjordan@BLM.gov)
Cc: Miro, Alena; Reineremann, Paul
Subject: B-7 Line Leak - C-141
Attachments: Eddy County C-141 Release Report B-7 ROW (2-24) March 2018.pdf

Attached for your review is the subject report- should you need additional information, please contact Alena Miro 575-628-6802.

Shiver J. Nolan
Sr. Compliance Administrator
Enterprise Products Operating LLC

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.