

District I

1624 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Road, Artesia, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural ResourcesOil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505Form C-141
Revised October 10, 2005Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR		☒ Initial Report	☐ Final Report
Name of Company - Evans Oil Company (TRIO)		Contact - James R. Evans	
Address - P.O. Box 1076		Telephone No. (432) 557-5870 or (432) 561-5953	
Facility Name - Persons Lease, well No. 2		Facility Type - Producing Oil & Gas Lease	
Surface Owner - Amos Persons, in care of J.T. Cooper, P. O. Box 55, Monument, NM 88265		Mineral Owner - Various API # 30-025-04084	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	27	19S	36E	1980'	FSL	1980'	FEL	Lea

API # 3002504084000 Latitude N 32° 37' 45.4" Longitude W 105° 20' 20.9"

NATURE OF RELEASE

Type of Release - Produced fluid (Oil & Wt)	Volume of Release - 4 Bbls	Volume Recovered - 3 Bbls
Source of Release - Stuffing Box Leak	Date and Hour of Occurrence 12/23/06 (7AM to 3 PM)	Date and Hour of Discovery 12/23/06 (2 PM)
Was Immediate Notice Given? ☐ Yes ☒ No ☐ Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Resolved? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.

Initial Report, evaluation planned to determine impact.


Describe Cause of Problem and Remedial Action Taken.

Stuffing box leak at well head after Lease Operator made property on 12/23/06. Lease Operator notified at approximately 3 PM, turned well off, repaired stuffing box, used vacuum truck and backhoe to remove fluid and soil impacted.

Describe Area Affected and Cleanup Action Taken.

Approximate dimensions 12' x 20' with fluid spilling down access road to well. Vacuum truck removed oil & water from spill and hauled to public SWD. Backhoe & dump truck used to removed surface soil affected by spill. Produced water chlorides 112,000 ppm. Work Plan will be turned in after initial assessment from Eddy Seay Environmental Consulting (505) 392-2216, fax - (505) 392-6949.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: James R. Evans		Approved by District Supervisor: 	
Title: Owner's Agent		Approval Date: 2-20-07	Expiration Date: 4-20-07
E-mail Address: j.evans@ecogc.com		Conditions of Approval:	Attached ☐
Date: 2-15-07 Phone: (432) 561-5953 wk		AS PER PLAN SUBMITTED	

* Attach Additional Sheets If Necessary

BY SENG DATED 2-19-07


incident - NPAC0705228052
application - NPAC0705228174

RP# 1210

RP
1210

TRIO OIL CO.
PERSONS #2
Unit J, Sect. 27, T. 19 S., R. 36 E.
GPS: 32 37' 45" N & 103 20' 21" W

WORKPLAN



Prepared by
Eddie Seay Consulting
February 2007

February 19, 2007

NMOCD Environmental
ATTN: Larry Johnson
1625 N. French Drive
Hobbs, NM 88240

RE: Trio Oil Co.
Persons #2
Remediation & Spill


Mr. Johnson:

At the request of Jim Evans with Trio Oil, (432-561-5953), a workplan is being filed. On or about December 2006, Trio was notified about a stuffing box leak at well #2. The leak was fixed and the fluids were vacuumed up and the area covered with sand to stabilize the containment. Trio was also ordered by the OCD to cleanup a 25 x 30 flowline leak which is approximately 200 ft. East of the well.

Trio has filed a C-141 and will wait for workplan approval to begin remediation.

If you have any questions, please call.

Sincerely,



Eddie W. Seay, Agent
Eddie Seay Consulting
601 W. Illinois
Hobbs, NM 88242
(505)392-2236
seay04@leaco.net

cc: Jim Evans

WORKPLAN

General:

On or about December 2006, a stuffing box leak occurred running down access road approximately 200 ft. Also, a flowline leak 200 ft. East of well was discovered, the area affected was 25' x 30' . We plan to remediate both areas.

Groundwater:


According to the water information, the depth of groundwater occurs at approximately 20 ft.


Remediation Proposal:

All available fluid was picked up. Our cleanup proposal will be to excavate and haul the contaminated soil to an OCD approved facility. After contaminated soil has been removed, the area will be sampled for final cleanup, and only after OCD approval, we will backfill, level and seed.

Ranking Criteria Score - 20

Shallow groundwater and location of spill. This site has a 100 ppm cleanup and will cleanup chloride per OCD.





TRIO OIL COMPANY
PERSONS NO. 2
UNIT J, SEC. 27-T19S-R36E
LEA COUNTY, NM







