

B. BERNARD LANKFORD, JR., P.E.
CONSULTING ENGINEER
DRILLING AND COMPLETIONS
P. O. BOX 238
MIDLAND, TEXAS 79702
TELEPHONE 915 682-6386

JUL 14 1978
CONSERVATION COMM.
Santa Fe

NSL-981
Rule 104 F
I'm in date

July 10, 1978

Mr. Joe D. Ramey, Secretary-Director
New Mexico Oil Conservation Commission
P. O. Box 2088
Santa Fe, New Mexico

Dear Mr. Ramey:

Southern Union Exploration Company plans to drill the Exxon Federal A No. 2. This well is 1700' FNL and 1780' FWL of Section 25, 20-S, 25-E, Eddy County, New Mexico.

This is a non-standard location and requires the approval of the New Mexico Oil Conservation Commission. Both the USGS and BLM have conducted an on-site inspection and this is the location that they recommended.

We own the acreage to the West, South, and North, the areas which would be affected by the well, and respectfully request administrative approval of the non-standard location.

Yours truly,

B. Bernard Lankford, Jr.

B. Bernard Lankford, Jr.
Consulting Engineer for Southern
Union Exploration Company

BBL/jls

Encl.

Ownership
Plot of
Rights


Waivers or
notice that they
were notified
by Roy's hand
Or mail

West Bubbling
Springs -
Morrow Pool
N/2/Sec 25

To check
to Lankford
7-11-78
to file
with
BLS

By phone 8-30-78

For una form



B. BERNARD LANKFORD, JR., P.E.

CONSULTING ENGINEER
DRILLING AND COMPLETIONS

P. O. BOX 238
MIDLAND, TEXAS 79702

TELEPHONE 915 682-6386

AUG 14 1978


August 11, 1978

Mr. Joe D. Ramey, Secretary-Director
New Mexico Oil Conservation Commission
P.O. Box 2088
Santa Fe, New Mexico

Dear Mr. Ramey:

As a follow up to our letter of July 10, 1978, I am sending
you a copy of the ownership map and the waiver from Amoco.
We plan to drill this well to the Morrow.


Yours truly,




B. Bernard Lankford, Jr.
Consulting Engineer for Southern
Union Exploration Company

BBL/lkm

Enclosure



<p>30 Rogers Stevens 30372 U.S.</p>	<p>31 Rogers Stevens 30373 U.S.</p>	<p>32 Rogers Stevens 30374 U.S.</p>	<p>33 Rogers Stevens 30375 U.S.</p>	<p>34 Rogers Stevens 30376 U.S.</p>	<p>35 Rogers Stevens 30377 U.S.</p>	<p>36 Rogers Stevens 30378 U.S.</p>	<p>37 Rogers Stevens 30379 U.S.</p>	<p>38 Rogers Stevens 30380 U.S.</p>	<p>39 Rogers Stevens 30381 U.S.</p>	<p>40 Rogers Stevens 30382 U.S.</p>
<p>17 Rogers Stevens 30383 U.S.</p>	<p>18 Rogers Stevens 30384 U.S.</p>	<p>19 Rogers Stevens 30385 U.S.</p>	<p>20 Rogers Stevens 30386 U.S.</p>	<p>21 Rogers Stevens 30387 U.S.</p>	<p>22 Rogers Stevens 30388 U.S.</p>	<p>23 Rogers Stevens 30389 U.S.</p>	<p>24 Rogers Stevens 30390 U.S.</p>	<p>25 Rogers Stevens 30391 U.S.</p>	<p>26 Rogers Stevens 30392 U.S.</p>	<p>27 Rogers Stevens 30393 U.S.</p>
<p>28 Rogers Stevens 30394 U.S.</p>	<p>29 Rogers Stevens 30395 U.S.</p>	<p>30 Rogers Stevens 30396 U.S.</p>	<p>31 Rogers Stevens 30397 U.S.</p>	<p>32 Rogers Stevens 30398 U.S.</p>	<p>33 Rogers Stevens 30399 U.S.</p>	<p>34 Rogers Stevens 30400 U.S.</p>	<p>35 Rogers Stevens 30401 U.S.</p>	<p>36 Rogers Stevens 30402 U.S.</p>	<p>37 Rogers Stevens 30403 U.S.</p>	<p>38 Rogers Stevens 30404 U.S.</p>
<p>39 Rogers Stevens 30405 U.S.</p>	<p>40 Rogers Stevens 30406 U.S.</p>	<p>41 Rogers Stevens 30407 U.S.</p>	<p>42 Rogers Stevens 30408 U.S.</p>	<p>43 Rogers Stevens 30409 U.S.</p>	<p>44 Rogers Stevens 30410 U.S.</p>	<p>45 Rogers Stevens 30411 U.S.</p>	<p>46 Rogers Stevens 30412 U.S.</p>	<p>47 Rogers Stevens 30413 U.S.</p>	<p>48 Rogers Stevens 30414 U.S.</p>	<p>49 Rogers Stevens 30415 U.S.</p>
<p>50 Rogers Stevens 30416 U.S.</p>	<p>51 Rogers Stevens 30417 U.S.</p>	<p>52 Rogers Stevens 30418 U.S.</p>	<p>53 Rogers Stevens 30419 U.S.</p>	<p>54 Rogers Stevens 30420 U.S.</p>	<p>55 Rogers Stevens 30421 U.S.</p>	<p>56 Rogers Stevens 30422 U.S.</p>	<p>57 Rogers Stevens 30423 U.S.</p>	<p>58 Rogers Stevens 30424 U.S.</p>	<p>59 Rogers Stevens 30425 U.S.</p>	<p>60 Rogers Stevens 30426 U.S.</p>



AMERICAN QUASAR PETROLEUM CO.

1000 THE MIDLAND NATIONAL BANK TOWER / MIDLAND / TEXAS 79701 U.S.A. /
TELEPHONE (915) 682-9411

May 12, 1978

Mr. Joe D. Ramey, Secretary-Director
New Mexico Oil Conservation Commission
P. O. Box 2088
Santa Fe, New Mexico 87501

Re: Non-Standard Location Waiver
Exxon Federal No. 3
Sec. 24-T-20-S, R-25-E
Eddy County, New Mexico


Dear Mr. Ramey:

We have been informed that Southern Union Exploration Company has made application for a permit to drill the Exxon Federal No. 3 as a wildcat well at a non-standard location in Eddy County, New Mexico.

The proposed location is described as being 660' FWL and 660' FSL of Section 24, T-20-S, R-25-E.

As an offset operator, American Quasar has no objection to this application and waives notice and hearing.

Very truly yours,


Robert A. Caudle

RAC/db

B. BERNARD LANKFORD, JR., P.E.

CONSULTING ENGINEER
DRILLING AND COMPLETIONS

P. O. BOX 238
MIDLAND, TEXAS 79702

TELEPHONE 915 682-6386

May 26, 1978

Mr. Joe D. Ramey, Secretary-Director
New Mexico Oil Conservation Commission
P.O. Box 2088
Santa Fe, New Mexico 87501


Dear Mr. Ramey:

Enclosed are four Non-Standard Location Waivers signed by Gulf Oil Corporation for the Exxon Federal No. 3, in Sec. 24-T-20-S, R-25-E, Eddy County, New Mexico. American Quasar has apparently sent their waivers directly to your office.

This should be all that you need to grant us exception to the Non-Standard location.

If you should have any questions or problems, please let me know.

Yours truly,



B. Bernard Lankford, Jr.
Consulting Engineer for Southern Union Exploration Company

BBL/jls

Enclosures

MAY 31 1978

April 25, 1978

RE: Non-Standard Location Waiver
Exxon Federal No. 3
Sec. 24-T-20-S, R-25-E
Eddy County, New Mexico

Mr. Joe D. Ramey, Secretary-Director
New Mexico Oil Conservation Commission
P.O. Box 2088
Santa Fe, New Mexico 87501

Dear Sir:

We have been informed that Southern Union Exploration Company has made application for a permit to drill the Exxon Federal No. 3 as a wildcat well at a non-standard location in Eddy County, New Mexico.


The proposed location is described as being 660' FWL and 660' FSL of Section 24, T-20-S, R-25-E.

As an offset operator, Gulf Oil Company has no objection to this application and waives notice and hearing.

Yours very truly,

GULF OIL CORPORATION

BY:


R.J. PANKRATZ MANAGER ENGINEERING

DATE: MAY 8, 1978



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION

JERRY APODACA
GOVERNOR

August 14, 1978

NICK FRANKLIN
SECRETARY

POST OFFICE BOX 2088
STATE LAND OFFICE BUILDING
SANTA FE, NEW MEXICO 87501
(505) 827-2434

B. Bernard Lankford, Jr., P.E.
P. O. Box 238
Midland, Texas 79702

Re: Application for Non-Standard
Location Southern Union Expl.
Co. Exxon Federal A No. 2, 1700'
FNL and 1780' FWL, Sec. 25, T-20-S,
R-25-E, Eddy County, New Mexico

We may not process the subject application for non-standard location until the required information or plats checked below (is) (are) submitted.

- A plat must be submitted showing the ownership of the offsetting leases.
- * A statement must be submitted that offset owners have been notified of the application by certified mail.
- A plat must be submitted fully identifying the topography necessitating the non-standard location.
- The application must be signed.

Very truly yours,

R. L. STAMETS
Technical Support Chief

*There is no indication that Exxon has been sent notice of this application even though they are shown as an offset operator on the plat submitted.