

P. O. Box 1290 Farmington, NM 87499 Telephone (505) 325-3587

September 4, 1984

NSL-1878 1915

Rule 104FI Release Immediately

Energy and Minerals Department Oil Conservation Division P.O. Box 2088 Santa Fe, New Mexico 87501

Attn: Joe Ramey

Reference: 5W/4SW/4 dedicated

SF 078430

(Newsom "A" #3)

Section 4, T26N-R8W San Juan County, NM

Federal lease.

Dear Mr. Ramey:

It is respectfully requested that Union Texas Petroleum Corporation be granted administrative approval to recomplete their Newsom "A" #3 well in the Undesignated Gallup formation, in a non-standard location due to the well being situated in a non-standard location for the new zone completion.

This proposed well would be located (935 feet from the South line and (1190 feet from the West line of Section 4, Township 26 North, Range 8 West, N.M.P.M., San Juan County, New Mexico.)

Attached are the following copies:

- 1. C-102 "Acreage Dedication Plat"
- Offset Operator's Plat
- Copies of Letters to Offset Operators

Your earliest consideration would be most appreciated.

Yours truly,

UNION TEXAS PETROLEUM CORPORATION


R. D. Motto

Area Operations Manager

RDM:1 im

cc: Oil Conservation Division-Aztec

Frank Chavez



September 4, 1984

El Paso Natural Gas Company P.O. Box 990 Farmington, NM 87499

Gentlemen:

Union Texas Petroleum proposes to drill their Newsom A #3 Gallup well located in a non-standard location as follows: 935' FSL; 1190' FWL, of Section 4, Township 26 North, Range 8 West, N.M.P.M., San Juan County, New Mexico.

This well was plugged back from a Dakota well and recompleted in the Gallup formation which made it a non-standard location.

Your prompt attention to this matter would be appreciated.

Yours truly,

UNION TEXAS PETROLEUM CORPORATION

Rudy D. Motto

Area Operations Manager

RDM:svr

This above non-standard location is hereby approved:



September 4, 1984

Southern Union Exploration P.O. Box 2179 Farmington, NM 87499

Gentlemen:

Union Texas Petroleum proposes to drill their Newsom A #3 Gallup well located in a non-standard location as follows: 935' FSL; 1190' FWL, of Section 4, Township 26 North, Range 8 West, N.M.P.M., San Juan County, New Mexico.

This well was plugged back from a Dakota well and recompleted in the Gallup formation which made it a non-standard location.

Your prompt attention to this matter would be appreciated.

Yours truly,

UNION TEXAS PETROLEUM CORPORATION

Rudy D. Motto

Area Operations Manager

RDM:svr

This above non-standard location is hereby approved:



STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

OIL CONSERVATI BOX 2088	ON DIVISION	•		•				
SANTA FE, NEW	MEXICO 87501		•	٠.				
DATE 9-/	8-84		• . ′		• •			
RE: Proposed Proposed Proposed Proposed Proposed Proposed	DHC NSL SWD WFX							
Gentlemen:		•		·		•		
I have examine for the Major	d the applicate of the desired of th	ion dated	9-1 Dep 1 Lease and	10-84 lewson Well No	"A" #3	3 <i>M</i>	-4-2601 nit, S-T-	<u>'- P</u> c R
and my recomme	endations are a	s follows	:				:	
Yours truly,			2					

OIL CONSERVATION DIVISION SANTA FE