

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company DCP Midstream, LP	Contact Greg Kardos
Address 370 17 TH Street, Ste. 2500, Denver, CO 80202	Telephone No. 432-620-4050
Facility Name Linam AGI #1 Wellsite	Facility Type: Class II Injection Well

Surface Owner State of New Mexico	Mineral Owner DCP Midstream, LP	Lease No. 1
-----------------------------------	---------------------------------	-------------

LOCATION OF RELEASE

AP# 30025385760000

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	30	18S	37E	1980	South	1980	West	Lea

Latitude N32° 43'00.7" Longitude W103°17'33.8"

NATURE OF RELEASE

Type of Release 10 ppg Brine Water	Volume of Release 200 Bbbs	Volume Recovered 0 Bbbs
Source of Release Drilling Site Reserve Pit	Date and Hour of Occurrence NA (See below)	Date and Hour of Discovery 10/21/2007, 1700 Hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD District I, Mr. Chris Williams.	
By Whom? Dan Breeding (Drilling Engineer)	Date and Hour 10/22/2007, 1500 Hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No NA	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NA


Describe Cause of Problem and Remedial Action Taken.*

The reserve pit liner was installed on 10/18/07 in 40 mph winds. Preliminary loads of fresh and brine waters were pumped into the two horseshoe areas of the pit on 10/18/07 to keep the 20 mil liner from blowing away. The pits were completely filled by the close of day 10/19/07. On 10/20/07, a decrease in pit volume was observed indicating a possible leak, so the water levels were marked and monitored. On 10/21/07, the leak was confirmed and the remaining brine was vacuumed out of the pit; then the liner was repaired. There were 2 loads of water not accounted for (approximately 200 bbbs). The NMOCD was notified within 24 hours of quantification and correction of the leak. Permission was given by Mr. Chris Williams to continue operations, provided an investigation and possible remediation of the area takes place after operations are completed.

Describe Area Affected and Cleanup Action Taken.*

Any affected areas and cleanup actions will be determined after operations are completed and the pit liner removed. The pit will be closed based in accordance with NMOCD rules and guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Greg Kardos	Approved by District Supervisor: 	
Title: Environmental Manager	Approval Date: 11/2/07	Expiration Date: 2/3/07
E-mail Address: gckardos@dcpmidstream.com	Conditions of Approval.	Attached <input type="checkbox"/>
Date: 11/02/2007	Phone: 432-620-4050	

RP#1652