

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

X Initial Report X Final Report

Name of Company	Range Operating New Mexico, Inc.	Contact	Linda C. Stiles
Address	777 Main Street Suite 800 Fort Worth TX 76102	Telephone No.	(817) 869-4208
Facility Name	Elliott B Federal # 2	Facility Type	Well site

Surface Owner	BLM	Mineral Owner	See Attached	Lease No.	
---------------	-----	---------------	--------------	-----------	--

**LOCATION OF RELEASE**


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
AJ	16	22S	37E					Lea

3002510077

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Vapor(Gas) Mist	Volume of Release	?	Volume Recovered	0
Source of	Casing Flowline leak	Date and Hour of Occurrence	11-6-07	Date and Hour of Discovery	11:30 am 11-6-07
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Linda Stiles(Range) Gary Wink NMOCD		
By Whom?	Chris Garcia	Date and Hour	11-7-07		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	NA		
If a Watercourse was Impacted, Describe Fully.*	NA				
Describe Cause of Problem and Remedial Action Taken.*	Poly-line weld opened up causing misty gas to blow into pasture. Refused poly-line and checked for line blockage.				
Describe Area Affected and Cleanup Action Taken.*	250' SE of Elliott B Federal #2 Area affected was 250'L x 75' W. Spray affected area with microblaze and recheck area in a couple of weeks.				



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Linda C. Stiles</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Linda C. Stiles	<i>J. Johnson</i> Approved by District Supervisor: <b>ENVIRONMENTAL ENGINEER</b>	
Title:	Sr. Engineering Tech	Approval Date:	11.27.07
E-mail Address:	lstiles@rangeresources.com	Expiration Date:	→
Date:	11-06-07	Conditions of Approval.	Attached <input type="checkbox"/>
Phone:	(817) 869-4208		

\* Attach Additional Sheets If Necessary

RPT#1666

**SPILL REPORT FORM – RANGE PRODUCTION COMPANY  
USEPA REGULATION 40 CFR 112 / RRC SWR 8, 20 & 91**

<b>DATE SPILL DISCOVERED:</b> 11-06-07	<b>TIME:</b> 1130am	<b>NAME OF RESPONDER:</b> Kenny Angel	
<b>LEASE WHERE SPILL OCCURED:</b> Elliott B Federal #2 flowline		<b>SOURCE OF SPILL (PIPELINE, TANK, ETC.)</b> Flowline	
<b>COUNTY WHERE SPILL OCCURRED:</b> Lea County		<b>WEATHER CONDITIONS:</b> Warm	
<b>(IF KNOWN) SIZE OF SPILL:</b> 250x75	<b>DID SPILL REACH A DITCH OR STORM DRAIN?</b> NO	<b>DID SPILL REACH NAVIGABLE WATERS, STREAM OR POND:</b> NO	
<b>CAUSE OF SPILL AND REMEDIAL ACTION TAKEN:</b> Poly-line weld opened up causing misty gas to blow into pasture. Refused poly-line and checked for line blockage.			
<b>TYPE OF DISCHARGE (OIL , WATER, FUEL, ETC.):</b> Water	<b>QUANTITY SPILLED (BBLs):</b> ?	<b>DURATION OF SPILL:</b> ?	
<b>TIME SPILL CONTAINED:</b> 11:30 am	<b>DATE SPILL CONTAINED:</b> 11-6-07	<b>BBLs RECOVERED:</b> 0	
<b>DEATHS/INJURIES/ACCIDENTS:</b> N/A			
<b>DESCRIBE AREA AFFECTED AND CLEANUP ACTION TAKEN:</b> 250' SE of Elliott Federal #2 well. Area affected was 250'x75'. Spray affected area w/ microblaze and recheck area after a couple of weeks.			
<b>WITHIN COMPANY</b>			
<b>REPORTED BY:</b> Kenny Angel	<b>TO:</b> Chris Garcia	<b>TIME</b> 11:30	<b>DATE:</b> 11-6-07
<b>REPORTED BY:</b> Chris Garcia	<b>TO:</b> Linda Stiles	<b>TIME:</b> 133pm	<b>DATE:</b> 11-06-07
<b>AGENCIES NOTIFIED</b>			
<b>AGENCY:</b>	<b>REPORTED TO:</b>	<b>TIME</b>	<b>DATE:</b>
NMOCD	Gary Wink	12:00pm	11-06-07
USFS			
BLM			
RRC OF TEXAS			

Fill out this form the same day the spill event is discovered and FAX to:  
SPCC Coordinator 100 Throckmorton Street, Suite 1200, Fort Worth TX 76102 (817) 869-9108