

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

FEB 22 2008

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OCD-ARTESIA

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

241598

Release Notification and Corrective Action

NSEB 0803737626

OPERATOR

Initial Report Final Report

Name of Company Fairway Resources Operating, LLC	Contact Kenneth Pearce
Address 538 Silicon Drive, Ste. 101, Southlake, TX 76092	Telephone No. 817-416-1946
Facility Name Midnight Matador "A" #4 30-015-01231	Facility Type Oil well

Surface Owner US-BLM	Mineral Owner US-BLM	Lease No. NM LC-055561
----------------------	----------------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	35	17S	27E	990'	North	1,650	East	Eddy

Latitude 32 degrees 47' 42.4"

Longitude 104 degrees 14' 44.9"

NATURE OF RELEASE

Type of Release Oil and produced water	Volume of Release Unknown	Volume Recovered 0
Source of Release wellhead	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 1/16/08 8:00 a.m. MST
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken *

This is a corrected initial report - A BLM inspection on 1-16-2008 found evidence of old leakage and soil contamination on the north side of the wellhead area and location. No free liquids were found, no current leakage was detected.

Describe Area Affected and Cleanup Action Taken.*

The affected area is on well pad and off of the north side. No free liquids were present so no liquids were recovered. Clean-up actions have not begun. A work plan proposal is being prepared for the clean-up of contaminants and will be submitted by March 6, 2008, as per email instructions from Sherry Bonham dated 2-6-2008.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kenneth Pearce</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Kenneth Pearce	Approved by District Supervisor: <i>T Gunn by SB</i>	
Title: Engineer	Approval Date: <i>2-22-08</i>	Expiration Date:
E-mail Address: <i>kpearce@fairwayresources.com</i>	Conditions of Approval: <i>REMEDIATION</i>	Attached <input type="checkbox"/>
Date: 2/18/08	Phone: 817-416-1946	<i>Plan Due ON OR BEFORE 3-6-08</i>

* Attach Additional Sheets If Necessary

PSEB0803737626

2RP-124