


A'



DST #1 OH 9220 - 9390'
OP 5" PF Strong blow
GTS 4 1/2" 640# 1/4" Chk Est 930 MCF
100" ISIP 3725# PF 1411 - 1273#
OP 20" FF 32# Incr to 1500# on 3/8" Chk
(Est 5362 MCFGPD) FF 1290 - 2665#
SI due to suspect hole in pipe
200" FSIP 3722#
SI WOCU

[illegible]