

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Linn operating	Contact Dennis Potter
Address 13694 Lovington hwy. Loco Hills, N.M. 88255	Telephone No. 505-206-7673
Facility Name Keel A # 34	Facility Type Producing well
Surface Owner B.L.M.	Mineral Owner Fed. Gov't.
Lease No. API #: 30-015-28233	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	7	17S	31E		1053' FSL		2604' FWL	EDDY

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 80 bbls.	Volume Recovered 60 bbls
Source of Release Injection Line	Date and Hour of Occurrence 9:30 AM	Date and Hour of Discovery 10/23/2010
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Terry Gregston and Jim Amos	10:00 AM
By Whom? Dennis Potter	Date and Hour 10/23/2010 11:00 AM.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**RECEIVED**  
DEC 27 2010  
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Injection leak on a 2" H.P. Fiberglas injection line was found approx. at 9:30 A.M. We immediately blocked in section of line where the leak was. I called Out a vacuum truck to start recovering water. Then I notified my office, then the BLM office. I then notified Holly corp. because the leak was by their lines. I then had the gang dig the leak out by hand and prepare to repair.

Describe Area Affected and Cleanup Action Taken.\*  
Affected area was approx 100 yards due south of the location all wtr had run into a sand dune area and was contained there. Talon LPE was called out to take soil samples and they were sent to Cardinal labs for analysis. Further soil remediation will be determined after tests results are received.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Dennis J. Potter</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Dennis J. Potter	Approved by District Supervisor: <i>Mike Brannan</i>	
Title: Production Specialist / Ass't. Production Foreman.	Approval Date: 3/9/11	Expiration Date:
E-mail Address: dpotter@linenergy.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. <b>SUBMIT REMEDIATION</b>	Attached <input type="checkbox"/>
Date: _____ Phone: 505-206-7673	<b>PROPOSAL NOT LATER THAN:</b> 4/9/11	

\* Attach Additional Sheets If Necessary

2 RP. 572