

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
MAR 31 2011
NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submits copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

NMW 1109553848

OPERATOR Initial Report Final Report

Name of Company Linn Energy	Contact Dennis Potter
Address PO Box 69, Loco Hills, NM 88255	Telephone No. 575 677 2327
Facility Name J L Keel B #94	Facility Type Oil Well

Surface Owner BLM	Mineral Owner BLM	Lease No. NMLC029435B API 30-015-28251
-------------------	-------------------	---

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	8	17S	31E					Eddy

Latitude N32.8470 Longitude W103.8916 (Release Site)

NATURE OF RELEASE

Type of Release Produced Water/Hydrocarbons	Volume of Release Unknown	Volume Recovered Unknown
Source of Release Flow Line	Date and Hour of Occurrence Unknown	Date and Hour of Discovery Feb 11
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* The release is a result of a flow line failure during freezing weather and is located approximately .5 miles west of the well. This release caused an "overspray" of fluid into the pasture on two sides of the lease road (north and south). The affected area on the north side of the road is approximately 150' x 150' and the south side is approximately 30' x 100'. Delineation will be conducted and the results used to formulate a work plan for submission to NM OCD and BLM for review and approval.		
Describe Area Affected and Cleanup Action Taken.*		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Dennis J. Potter</i>	OIL CONSERVATION DIVISION	
Printed Name: Dennis Potter	Signed By <i>Mike Brannon</i> Approved by District Supervisor:	
Title: Assistant Production Foreman	Approval Date: <i>4/5/11</i>	Expiration Date:
E-mail Address: dpotter@linenergy.com	Conditions of Approval: Attached <input type="checkbox"/>	
Date: 30Mar11 Phone: 505 206 7673		

* Attach Additional Sheets If Necessary

REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY:

5/5/11

2 RP-709

Bratcher, Mike, EMNRD

From: Vernon Black [vernon@hungry-horse.com]
Sent: Thursday, March 31, 2011 6:27 PM
To: Terry_gregston@nm.blm.gov; Bratcher, Mike, EMNRD; avalero@linnenergy.com; dpotter@linnenergy.com
Subject: Emailing: Initial C 141 J L Keel B #94
Attachments: Initial C 141 J L Keel B #94.pdf

Your message is ready to be sent with the following file or link attachments:

Initial C 141 J L Keel B #94

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.