

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-27787

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

NMLB 11132-54815

Name of Company BOPCO, L.P. <i>260737</i>	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name Poker Lake Unit #89	Facility Type E&P

Surface Owner Federal	Mineral Owner Federal	Lease No NML C061705B
-----------------------	-----------------------	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	25	24S	30E					Eddy

Latitude N 32.189988 Longitude W 103.832185

NATURE OF RELEASE

Type of Release: Produced water and crude oil	Volume of Release: 455 bbls of produced water and 6 bbls of crude oil. Total fluid 461 bbls.	Volume Recovered: 430 bbls of produced water and 5 bbls of crude oil. Total fluid 435 bbls
Source of Release: Storage tank overflow	Date and Hour of Occurrence 5/11/11, Hour unknown	Date and Hour of Discovery 5/11/11 8:55 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher NMOCD and Jim Amos BLM	
By Whom? Tony Savoie	Date and Hour 5/11/11 9:11 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

RECEIVED
 MAY 12 2011
 NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* The primary water transfer pump coupling between the motor and pump failed, the secondary pump failed to come on due to a communication problem between the primary and secondary pump. The pump was repaired and the electrical communication problem was corrected.

Describe Area Affected and Cleanup Action Taken.*The entire area of the earthen containment approximately 3500 sq. ft was covered with the fluid. The containment breached causing approximately 70 bbls of produced water to spill onto the caliche well pad and battery pad. This area was approximately 3268 sq. ft. All of the free standing fluid was removed with a vacuum truck. A remediation plan including new containment construction will be developed in accordance with the NMOCD and BLM remediation and containment guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by District Supervisor Signed By <i>Mike Bratcher</i>	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: <u>5/12/2011</u>	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/11/11 Phone: 432-556-8730	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: <u>6/12/2011</u>	

2RP-780

* Attach Additional Sheets If Necessary