



Post Office Box 61229  
Houston, Texas 77208-1229

1111 Travis Street  
Houston, Texas 77002

Phone: (832) 839-4601  
ccreekmore@hilcorp.com

R-204

March 1, 2019

Bureau of Land Management  
Farmington Resource Area  
6251 College Blvd., Suite A  
Farmington, NM 87402

Commissioner of Public Lands  
State of New Mexico  
P. O. Box 1148  
Santa Fe, NM 87501-1148

Oil Conservation Division  
State of New Mexico  
1220 S. Saint Francis Drive  
Santa Fe, NM 87505

**2019 PLAN OF DEVELOPMENT  
FOR THE SAN JUAN 29-6 UNIT  
NO. 14-08-001-439  
RIO ARRIBA COUNTY, NEW MEXICO**

Pursuant to Section 10 of the San Juan 29-6 Unit Agreement, Hilcorp Energy Company ("Hilcorp"), as Unit Operator, hereby submits the proposed 2019 Plan of Development and Operations ("POD").

**I. PERIOD**

This plan will be effective from April 1, 2019 through March 31, 2020. The 2020 Plan will be submitted on or before March 1, 2020.

**II. 2018 PLAN REVIEW OF OPERATIONS**

**A. Production History:** During 2018, cumulative production from the San Juan 29-6 Unit was 14.4 BCF gas; 16.6 MBO oil; and 66.6 MBW produced water. Refer to Exhibit A attached for a listing of all wells in the San Juan 29-6 Unit.

**B. Participating Areas:** The Participating Areas currently established in the San Juan 29-6 Unit are as follows:

| FORMATION       | EXPANSION | EFFECTIVE DATE |
|-----------------|-----------|----------------|
| DAKOTA "A"      | 000       | 31-DEC-74      |
| DAKOTA          | 015       | 10-JUL-11      |
| FRUITLAND COAL  | 020       | 01-FEB-04      |
| MESAVERDE       | 037       | 01-FEB-88      |
| PICTURED CLIFFS | 005       | 01-JAN-01      |

**C. Drilling Program:** As proposed, Hilcorp successfully drilled and completed the San Juan Unit 29-6 Unit Com 601 #H.

**D.** During 2018, Hilcorp undertook and completed the following projects:

| Well Name                        | API        | Sec. | Twp  | Rng  | Formation         | Type               |
|----------------------------------|------------|------|------|------|-------------------|--------------------|
| SAN JUAN 29-6 UNIT 205A          | 3003927855 | 21   | 029N | 006W | FRUITLAND COAL    | PUMP/TUBING REPAIR |
| SAN JUAN 29-6 UNIT 215A          | 3003927511 | 3    | 029N | 006W | FRUITLAND COAL    | PUMP/TUBING REPAIR |
| SAN JUAN 29-6 UNIT 216A          | 3003927512 | 4    | 029N | 006W | FRUITLAND COAL    | PUMP/TUBING REPAIR |
| SAN JUAN 29-6 UNIT 217           | 3003924794 | 5    | 029N | 006W | FRUITLAND COAL    | PUMP/TUBING REPAIR |
| SAN JUAN 29-6 UNIT 258           | 3003924766 | 16   | 029N | 006W | FRUITLAND COAL    | PUMP/TUBING REPAIR |
| SAN JUAN 29-6 UNIT 97            | 3003920241 | 35   | 029N | 006W | DAKOTA/ME SAVERDE | TUBING REPAIR      |
| SAN JUAN 29-6 UNIT WATER WELL #1 | N/A        | 28   | 029N | 006W | GRUNDFOS          | ESP REPAIR         |
| SAN JUAN 29-6 UNIT WATER WELL #1 | N/A        | 28   | 029N | 006W | GRUNDFOS          | ESP REPAIR         |

**E. Facility Program:** The 2018 POD, as approved, provided for no additional facilities. No additional facility projects were undertaken by Hilcorp during this period.

**F. Plugging & Abandonment Program:** The 2018 POD, as approved, provided for no activity. No additional projects were undertaken by Hilcorp during the 2018 period.

### **III. 2019 PLAN OF DEVELOPMENT AND OPERATIONS**

A summary of key activities planned for 2019 includes:

**A. Drilling Program:** Hilcorp anticipates drilling new wells in the San Juan 29-6 Unit during 2019 outlined below. Other new drill opportunities are being evaluated and will be executed as they arise.

| Well Name                 | API | Sec. | Twp  | Rng  | Formation | Type      |
|---------------------------|-----|------|------|------|-----------|-----------|
| SAN JUAN 29-6 UNIT 601 2H | TBD | 08   | 029N | 006W | MANCOS    | NEW DRILL |
| SAN JUAN 29-6 UNIT 601 3H | TBD | 08   | 029N | 006W | MANCOS    | NEW DRILL |
| SAN JUAN 29-6 UNIT 601 4H | TBD | 08   | 029N | 006W | MANCOS    | NEW DRILL |

**B. Workovers/Recompletion Program:** Hilcorp anticipates at least eight (8) recompletion projects in the Unit during 2019, summarized in the table below. Additional workovers,

rate adds and optimization projects will be evaluated and executed as they arise.

| Well Name                     | API        | Sec. | Twp  | Rng  | Formation          | Type                  |
|-------------------------------|------------|------|------|------|--------------------|-----------------------|
| SAN JUAN<br>29-6 UNIT<br>104M | 3003927592 | 14   | 029N | 006W | PICTURED<br>CLIFFS | RECOMPLETE/COMMINGLED |
| SAN JUAN<br>29-6 UNIT<br>107F | 3003929728 | 36   | 029N | 006W | PICTURED<br>CLIFFS | RECOMPLETE/COMMINGLED |
| SAN JUAN<br>29-6 UNIT<br>10A  | 3003921119 | 02   | 029N | 006W | PICTURED<br>CLIFFS | RECOMPLETE/COMMINGLED |
| SAN JUAN<br>29-6 UNIT 114     | 3003922995 | 07   | 029N | 006W | MESAVERDE          | RECOMPLETE/COMMINGLED |
| SAN JUAN<br>29-6 UNIT<br>22M  | 3003927507 | 12   | 029N | 006W | PICTURED<br>CLIFFS | RECOMPLETE/COMMINGLED |
| SAN JUAN<br>29-6 UNIT 33F     | 3003927552 | 13   | 029N | 006W | PICTURED<br>CLIFFS | RECOMPLETE/COMMINGLED |
| SAN JUAN<br>29-6 UNIT 45      | 3003907539 | 27   | 029N | 006W | PICTURED<br>CLIFFS | RECOMPLETE/COMMINGLED |
| SAN JUAN<br>29-6 UNIT<br>92M  | 3003927555 | 12   | 029N | 006W | PICTURED<br>CLIFFS | RECOMPLETE/COMMINGLED |

**C. Facility Program:** Throughout 2019, Hilcorp will conduct routine repairs and replacement of facilities required to maintain and increase field production, including construction of additional gas lift lines and/or gas flow lines, expansion of production facilities (including electrical and piping upgrades), and construction of additional water disposal, injection or processing equipment.

**D. Plugging & Abandonment Program:** Hilcorp does not anticipate plugging/abandoning any wells in the Unit at this time. Hilcorp will evaluate and implement additional P&A projects as they arise.

In accordance to Section 10 of the Unit Agreement, please provide your approvals by executing and returning a copy of this letter to the undersigned.

Please contact me at (832) 839-4601 if there are any questions regarding this letter.

Sincerely,  
HILCORP ENERGY COMPANY



Chuck Creekmore,  
Division Landman

cc: Working Interest Owners

San Juan 29-6 Unit  
2019 Plan of Development

BETTY T JOHNSTON MARITAL TRUST  
BIG SNOWY EXPLORATION LLLP  
BP AMERICA PRODUCTION COMPANY  
CHARLES W GAY  
ELAINE G HOWE  
EULA MAY JOHNSTON TRUST 661  
FRANK N GIBBARD JR  
GRAYFORE PARTNERS LP  
J&M RAYMOND LTD  
HILCORP SAN JUAN, LP  
LOGOS RESOURCES II LLC

LORRAYN GAY HACKER  
MCELVAIN OIL COMPANY  
PGC GAS COMPANY  
PINTAIL PRODUCTION CO INC  
PRODUCTION GATHERING CO LP  
RESOURCE DEVELOPMENT TECHNOLOGY LLC  
RKC INC  
SABLE ENERGY LTD  
SAN JUAN BASIN PARTNERSHIP  
T H MCELVAIN OIL & GAS LLLP  
TAMACAM LLC

V A JOHNSTON LTD  
VAUGHAN-MCELVAIN ENERGY INC

**SAN JUAN 29-6 UNIT  
2019 PLAN OF DEVELOPMENT APPROVALS**

\_\_\_\_\_  
**Bureau of Land Management**

\_\_\_\_\_  
**Date**

\_\_\_\_\_  
**New Mexico Oil Conservation Division**

\_\_\_\_\_  
**Date**

\_\_\_\_\_  
**New Mexico Commissioner of Public Lands**

\_\_\_\_\_  
**Date**



## San Juan 29-6 Unit Exhibit "A"

| API #      | WELL NAME               | POOL/FORMATION   | STATUS         | ST | COUNTY     | SEC | TWP  | RGE  | QTR  | OPERATOR               |
|------------|-------------------------|------------------|----------------|----|------------|-----|------|------|------|------------------------|
| 3003907704 | San Juan 29-6 Unit 001  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 3   | 029N | 006W | NENE | Hilcorp Energy Company |
| 3003921124 | San Juan 29-6 Unit 001A | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 3   | 029N | 006W | SESE | Hilcorp Energy Company |
| 3003929430 | San Juan 29-6 Unit 001B | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 3   | 029N | 006W | NWNE | Hilcorp Energy Company |
| 3003926743 | San Juan 29-6 Unit 001C | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 3   | 029N | 006W | NWSE | Hilcorp Energy Company |
| 3003907605 | San Juan 29-6 Unit 002  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 14  | 029N | 014W | SWSW | Hilcorp Energy Company |
| 3003921121 | San Juan 29-6 Unit 002A | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 14  | 029N | 014W | SENE | Hilcorp Energy Company |
| 3003907530 | San Juan 29-6 Unit 003  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 25  | 029N | 025W | NWSW | Hilcorp Energy Company |
| 3003921576 | San Juan 29-6 Unit 003A | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 25  | 029N | 025W | NWNW | Hilcorp Energy Company |
| 3003907607 | San Juan 29-6 Unit 004  | Blanco-Mesaverde | Perm Abandoned | NM | Rio Arriba | 17  | 029N | 006W |      | Hilcorp Energy Company |
| 3003921228 | San Juan 29-6 Unit 004A | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 17  | 029N | 006W | SWNW | Hilcorp Energy Company |
| 3003930127 | San Juan 29-6 Unit 004B | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 17  | 029N | 006W | NWNW | Hilcorp Energy Company |
| 3003930706 | San Juan 29-6 Unit 004M | Basin Dakota     | Flowing        | NM | Rio Arriba | 17  | 029N | 006W | SENE | Hilcorp Energy Company |
| 3003930706 | San Juan 29-6 Unit 004M | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 17  | 029N | 006W | SENE | Hilcorp Energy Company |
| 3003920513 | San Juan 29-6 Unit 004Y | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 17  | 029N | 017W | SWSW | Hilcorp Energy Company |
| 3003907518 | San Juan 29-6 Unit 005  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 30  | 029N | 006W | SESE | Hilcorp Energy Company |
| 3003921264 | San Juan 29-6 Unit 005A | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 30  | 029N | 030W | SENE | Hilcorp Energy Company |
| 3003930748 | San Juan 29-6 Unit 005M | Basin Dakota     | Flowing        | NM | Rio Arriba | 30  | 029N | 006W | SESE | Hilcorp Energy Company |
| 3003930748 | San Juan 29-6 Unit 005M | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 30  | 029N | 006W | SESE | Hilcorp Energy Company |
| 3003930664 | San Juan 29-6 Unit 005N | Basin Dakota     | Flowing        | NM | Rio Arriba | 25  | 029N | 007W | SENE | Hilcorp Energy Company |
| 3003930664 | San Juan 29-6 Unit 005N | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 25  | 029N | 007W | SENE | Hilcorp Energy Company |
| 3003907573 | San Juan 29-6 Unit 006  | Blanco Mesaverde | Perm Abandoned | NM | Rio Arriba | 21  | 029N | 006W |      | Hilcorp Energy Company |
| 3003921251 | San Juan 29-6 Unit 006A | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 21  | 029N | 021W | NENW | Hilcorp Energy Company |
| 3003929753 | San Juan 29-6 Unit 006B | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 21  | 029N | 021W | NWNW | Hilcorp Energy Company |
| 3003929337 | San Juan 29-6 Unit 006C | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 21  | 029N | 021W | SWSW | Hilcorp Energy Company |
| 3003907473 | San Juan 29-6 Unit 007  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 34  | 029N | 034W | SWSW | Hilcorp Energy Company |
| 3003921367 | San Juan 29-6 Unit 007A | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 34  | 029N | 034W | SWNW | Hilcorp Energy Company |
| 3003907688 | San Juan 29-6 Unit 008  | Blanco Mesaverde | Perm Abandoned | NM | Rio Arriba | 1   | 029N | 006W |      | Hilcorp Energy Company |
| 3003921123 | San Juan 29-6 Unit 008A | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 1   | 029N | 006W | SENE | Hilcorp Energy Company |
| 3003926184 | San Juan 29-6 Unit 008B | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 1   | 029N | 006W | NWNW | Hilcorp Energy Company |
| 3003929751 | San Juan 29-6 Unit 008M | Basin Dakota     | Flowing        | NM | Rio Arriba | 1   | 029N | 006W | NESW | Hilcorp Energy Company |
| 3003929751 | San Juan 29-6 Unit 008M | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 1   | 029N | 006W | NESW | Hilcorp Energy Company |
| 3003920425 | San Juan 29-6 Unit 008Y | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 1   | 029N | 006W | NWSW | Hilcorp Energy Company |
| 3003907476 | San Juan 29-6 Unit 009  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 36  | 029N | 036W | SWSW | Hilcorp Energy Company |
| 3003921311 | San Juan 29-6 Unit 009A | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 36  | 029N | 036W | SWNW | Hilcorp Energy Company |
| 3003907703 | San Juan 29-6 Unit 010  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 2   | 029N | 006W | NWNE | Hilcorp Energy Company |
| 3003921119 | San Juan 29-6 Unit 010A | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 2   | 029N | 006W | SESE | Hilcorp Energy Company |
| 3003926706 | San Juan 29-6 Unit 010B | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 2   | 029N | 006W | NENE | Hilcorp Energy Company |
| 3003926707 | San Juan 29-6 Unit 010C | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 2   | 029N | 006W | NWSE | Hilcorp Energy Company |
| 3003907640 | San Juan 29-6 Unit 011  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 7   | 029N | 006W | SWSW | Hilcorp Energy Company |
| 3003921386 | San Juan 29-6 Unit 011A | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 7   | 029N | 006W | NWNW | Hilcorp Energy Company |
| 3003929276 | San Juan 29-6 Unit 011B | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 7   | 029N | 007W | NENW | Hilcorp Energy Company |
| 3003929930 | San Juan 29-6 Unit 011C | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 7   | 029N | 006W | SESE | Hilcorp Energy Company |
| 3003907699 | San Juan 29-6 Unit 012  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 6   | 029N | 006W | SENE | Hilcorp Energy Company |
| 3003921563 | San Juan 29-6 Unit 012A | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 6   | 029N | 006W | NWSE | Hilcorp Energy Company |
| 3003927521 | San Juan 29-6 Unit 012B | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 6   | 029N | 006W | NWNE | Hilcorp Energy Company |
| 3003926748 | San Juan 29-6 Unit 012C | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 6   | 029N | 006W | NESE | Hilcorp Energy Company |
| 3003921562 | San Juan 29-6 Unit 013A | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 6   | 029N | 006W | NWNW | Hilcorp Energy Company |
| 3003926740 | San Juan 29-6 Unit 013B | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 6   | 029N | 006W | NENW | Hilcorp Energy Company |
| 3003930385 | San Juan 29-6 Unit 013C | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 7   | 029N | 007W | NWNE | Hilcorp Energy Company |
| 3003921564 | San Juan 29-6 Unit 014A | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 7   | 029N | 007W | NESE | Hilcorp Energy Company |
| 3003929410 | San Juan 29-6 Unit 014B | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 7   | 029N | 007W | SWNE | Hilcorp Energy Company |
| 3003929750 | San Juan 29-6 Unit 014C | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 7   | 029N | 007W | SWSE | Hilcorp Energy Company |
| 3003907692 | San Juan 29-6 Unit 015  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 2   | 029N | 006W | NESW | Hilcorp Energy Company |
| 3003921120 | San Juan 29-6 Unit 015A | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 2   | 029N | 006W | NENW | Hilcorp Energy Company |

|            |                         |                            |         |    |            |    |      |      |      |                        |
|------------|-------------------------|----------------------------|---------|----|------------|----|------|------|------|------------------------|
| 3003926705 | San Juan 29-6 Unit 015B | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 2  | 029N | 006W | NWNW | Hilcorp Energy Company |
| 3003926704 | San Juan 29-6 Unit 015C | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 2  | 029N | 006W | SWSW | Hilcorp Energy Company |
| 3003907471 | San Juan 29-6 Unit 016  | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 32 | 029N | 006W | SESW | Hilcorp Energy Company |
| 3003907471 | San Juan 29-6 Unit 016  | Blanco P. C. South         | Flowing | NM | Rio Arriba | 32 | 029N | 006W | SESW | Hilcorp Energy Company |
| 3003921090 | San Juan 29-6 Unit 016A | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 32 | 029N | 032W | NWNW | Hilcorp Energy Company |
| 3003921415 | San Juan 29-6 Unit 017A | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 1  | 029N | 006W | NWSE | Hilcorp Energy Company |
| 3003927503 | San Juan 29-6 Unit 017B | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 1  | 029N | 006W | SWNE | Hilcorp Energy Company |
| 3003927599 | San Juan 29-6 Unit 017C | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 1  | 029N | 006W | SWSE | Hilcorp Energy Company |
| 3003927599 | San Juan 29-6 Unit 017C | Gobernador Pictured Cliffs | Flowing | NM | Rio Arriba | 1  | 029N | 006W | SWSE | Hilcorp Energy Company |
| 3003927599 | San Juan 29-6 Unit 017C | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 1  | 029N | 006W | SWSE | Hilcorp Energy Company |
| 3003921561 | San Juan 29-6 Unit 018A | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 5  | 029N | 005W | SWNW | Hilcorp Energy Company |
| 3003926188 | San Juan 29-6 Unit 018B | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 5  | 029N | 005W | NENW | Hilcorp Energy Company |
| 3003929521 | San Juan 29-6 Unit 018C | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 5  | 029N | 005W | NWSW | Hilcorp Energy Company |
| 3003926444 | San Juan 29-6 Unit 018R | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 5  | 029N | 005W | SWSW | Hilcorp Energy Company |
| 3003921419 | San Juan 29-6 Unit 019A | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 8  | 029N | 006W | NESE | Hilcorp Energy Company |
| 3003929454 | San Juan 29-6 Unit 019B | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 8  | 029N | 006W | SENE | Hilcorp Energy Company |
| 3003929532 | San Juan 29-6 Unit 019C | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 8  | 029N | 008W | SWSE | Hilcorp Energy Company |
| 3003926421 | San Juan 29-6 Unit 019R | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 8  | 029N | 008W | NWNE | Hilcorp Energy Company |
| 3003921565 | San Juan 29-6 Unit 020A | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 8  | 029N | 008W | NWNW | Hilcorp Energy Company |
| 3003929522 | San Juan 29-6 Unit 020B | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 8  | 029N | 008W | SWNW | Hilcorp Energy Company |
| 3003930929 | San Juan 29-6 Unit 020C | Basin Dakota               | Flowing | NM | Rio Arriba | 8  | 029N | 006W | NWSW | Hilcorp Energy Company |
| 3003930929 | San Juan 29-6 Unit 020C | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 8  | 029N | 006W | NWSW | Hilcorp Energy Company |
| 3003907674 | San Juan 29-6 Unit 021  | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 11 | 029N | 006W | NENE | Hilcorp Energy Company |
| 3003921567 | San Juan 29-6 Unit 021A | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 11 | 029N | 011W | SESE | Hilcorp Energy Company |
| 3003907676 | San Juan 29-6 Unit 022  | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 12 | 029N | 006W | NWNE | Hilcorp Energy Company |
| 3003921425 | San Juan 29-6 Unit 022A | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 12 | 029N | 006W | SWSE | Hilcorp Energy Company |
| 3003927507 | San Juan 29-6 Unit 022M | Basin Dakota               | Flowing | NM | Rio Arriba | 12 | 029N | 006W | NWSE | Hilcorp Energy Company |
| 3003927507 | San Juan 29-6 Unit 022M | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 12 | 029N | 006W | NWSE | Hilcorp Energy Company |
| 3003929757 | San Juan 29-6 Unit 022N | Basin Dakota               | Flowing | NM | Rio Arriba | 12 | 029N | 006W | SWNE | Hilcorp Energy Company |
| 3003929757 | San Juan 29-6 Unit 022N | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 12 | 029N | 006W | SWNE | Hilcorp Energy Company |
| 3003921424 | San Juan 29-6 Unit 023A | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 12 | 029N | 006W | SWNW | Hilcorp Energy Company |
| 3003921252 | San Juan 29-6 Unit 024A | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 21 | 029N | 021W | SWSE | Hilcorp Energy Company |
| 3003907500 | San Juan 29-6 Unit 025  | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 32 | 029N | 032W | NWNE | Hilcorp Energy Company |
| 3003907500 | San Juan 29-6 Unit 025  | Blanco P. C. South         | Flowing | NM | Rio Arriba | 32 | 029N | 032W | NWNE | Hilcorp Energy Company |
| 3003921092 | San Juan 29-6 Unit 025A | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 32 | 029N | 006W | SWSE | Hilcorp Energy Company |
| 3003921092 | San Juan 29-6 Unit 025A | Blanco P. C. South         | Flowing | NM | Rio Arriba | 32 | 029N | 006W | SWSE | Hilcorp Energy Company |
| 3003926180 | San Juan 29-6 Unit 025B | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 32 | 029N | 006W | NESE | Hilcorp Energy Company |
| 3003926799 | San Juan 29-6 Unit 025C | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 32 | 029N | 032W | NENE | Hilcorp Energy Company |
| 3003907611 | San Juan 29-6 Unit 026  | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 13 | 029N | 013W | NESW | Hilcorp Energy Company |
| 3003921568 | San Juan 29-6 Unit 026A | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 13 | 029N | 013W | NWNW | Hilcorp Energy Company |
| 3003907572 | San Juan 29-6 Unit 027  | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 23 | 029N | 023W | NESW | Hilcorp Energy Company |
| 3003921412 | San Juan 29-6 Unit 027A | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 23 | 029N | 023W | NENW | Hilcorp Energy Company |
| 3003907560 | San Juan 29-6 Unit 028  | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 24 | 029N | 024W | SESW | Hilcorp Energy Company |
| 3003921574 | San Juan 29-6 Unit 028A | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 24 | 029N | 024W | NWNW | Hilcorp Energy Company |
| 3003907686 | San Juan 29-6 Unit 029  | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 3  | 029N | 006W | SESW | Hilcorp Energy Company |
| 3003921118 | San Juan 29-6 Unit 029A | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 3  | 029N | 006W | SENE | Hilcorp Energy Company |
| 3003926179 | San Juan 29-6 Unit 029B | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 3  | 029N | 006W | NENW | Hilcorp Energy Company |
| 3003929466 | San Juan 29-6 Unit 029C | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 3  | 029N | 006W | NWSW | Hilcorp Energy Company |
| 3003907663 | San Juan 29-6 Unit 030  | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 10 | 029N | 006W | SENE | Hilcorp Energy Company |
| 3003921422 | San Juan 29-6 Unit 030A | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 10 | 029N | 006W | NESE | Hilcorp Energy Company |
| 3003907639 | San Juan 29-6 Unit 031  | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 10 | 029N | 006W | SWSW | Hilcorp Energy Company |
| 3003921421 | San Juan 29-6 Unit 031A | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 10 | 029N | 006W | NENW | Hilcorp Energy Company |
| 3003926197 | San Juan 29-6 Unit 031B | Basin Dakota               | Flowing | NM | Rio Arriba | 10 | 029N | 010W | SWNW | Hilcorp Energy Company |
| 3003926197 | San Juan 29-6 Unit 031B | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 10 | 029N | 010W | SWNW | Hilcorp Energy Company |
| 3003927516 | San Juan 29-6 Unit 031M | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 10 | 029N | 006W | NESW | Hilcorp Energy Company |
| 3003907651 | San Juan 29-6 Unit 032  | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 11 | 029N | 006W | NWSW | Hilcorp Energy Company |
| 3003921423 | San Juan 29-6 Unit 032A | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 11 | 029N | 006W | SENE | Hilcorp Energy Company |
| 3003907636 | San Juan 29-6 Unit 033  | Basin Dakota               | Flowing | NM | Rio Arriba | 13 | 029N | 006W | NWNE | Hilcorp Energy Company |
| 3003907636 | San Juan 29-6 Unit 033  | Blanco-Mesaverde           | Flowing | NM | Rio Arriba | 13 | 029N | 006W | NWNE | Hilcorp Energy Company |

|            |                         |                      |                |    |            |    |      |      |      |                        |
|------------|-------------------------|----------------------|----------------|----|------------|----|------|------|------|------------------------|
| 3003921569 | San Juan 29-6 Unit 033A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 13 | 029N | 013W | NWSE | Hilcorp Energy Company |
| 3003927552 | San Juan 29-6 Unit 033F | Basin Dakota         | Flowing        | NM | Rio Arriba | 13 | 029N | 013W | SWNE | Hilcorp Energy Company |
| 3003927552 | San Juan 29-6 Unit 033F | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 13 | 029N | 013W | SWNE | Hilcorp Energy Company |
| 3003927527 | San Juan 29-6 Unit 033M | Basin Dakota         | Flowing        | NM | Rio Arriba | 13 | 029N | 013W | SWSE | Hilcorp Energy Company |
| 3003927527 | San Juan 29-6 Unit 033M | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 13 | 029N | 013W | SWSE | Hilcorp Energy Company |
| 3003907628 | San Juan 29-6 Unit 034  | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 14 | 029N | 014W | NENE | Hilcorp Energy Company |
| 3003921122 | San Juan 29-6 Unit 034A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 14 | 029N | 014W | NESE | Hilcorp Energy Company |
| 3003982386 | San Juan 29-6 Unit 035  | Basin Dakota         | Flowing        | NM | Rio Arriba | 15 | 029N | 015W | SWSW | Hilcorp Energy Company |
| 3003982386 | San Juan 29-6 Unit 035  | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 15 | 029N | 015W | SWSW | Hilcorp Energy Company |
| 3003921570 | San Juan 29-6 Unit 035A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 15 | 029N | 015W | NWNW | Hilcorp Energy Company |
| 3003929752 | San Juan 29-6 Unit 035F | Basin Dakota         | Flowing        | NM | Rio Arriba | 15 | 029N | 015W | NWSW | Hilcorp Energy Company |
| 3003929752 | San Juan 29-6 Unit 035F | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 15 | 029N | 015W | NWSW | Hilcorp Energy Company |
| 3003926423 | San Juan 29-6 Unit 035M | Basin Dakota         | Flowing        | NM | Rio Arriba | 15 | 029N | 015W | SESE | Hilcorp Energy Company |
| 3003926423 | San Juan 29-6 Unit 035M | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 15 | 029N | 015W | SESE | Hilcorp Energy Company |
| 3003907624 | San Juan 29-6 Unit 036  | Blanco Mesaverde     | Perm Abandoned | NM | Rio Arriba | 15 | 029N | 006W |      | Hilcorp Energy Company |
| 3003921571 | San Juan 29-6 Unit 036A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 15 | 029N | 015W | NWSE | Hilcorp Energy Company |
| 3003907631 | San Juan 29-6 Unit 037  | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 16 | 029N | 016W | NENE | Hilcorp Energy Company |
| 3003921225 | San Juan 29-6 Unit 037A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 16 | 029N | 016W | SESE | Hilcorp Energy Company |
| 3003907606 | San Juan 29-6 Unit 038  | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 16 | 029N | 032W | SESW | Hilcorp Energy Company |
| 3003921224 | San Juan 29-6 Unit 038A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 16 | 029N | 016W | NWNW | Hilcorp Energy Company |
| 3003907589 | San Juan 29-6 Unit 039  | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 22 | 029N | 022W | NWNE | Hilcorp Energy Company |
| 3003921572 | San Juan 29-6 Unit 039A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 22 | 029N | 022W | NESE | Hilcorp Energy Company |
| 3003907585 | San Juan 29-6 Unit 040  | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 23 | 029N | 023W | SENE | Hilcorp Energy Company |
| 3003921573 | San Juan 29-6 Unit 040A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 23 | 029N | 023W | SWSE | Hilcorp Energy Company |
| 3003907591 | San Juan 29-6 Unit 041  | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 24 | 029N | 024W | NWNE | Hilcorp Energy Company |
| 3003921575 | San Juan 29-6 Unit 041A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 24 | 029N | 024W | NWSE | Hilcorp Energy Company |
| 3003907542 | San Juan 29-6 Unit 042  | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 25 | 029N | 025W | SWNE | Hilcorp Energy Company |
| 3003921577 | San Juan 29-6 Unit 042A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 25 | 029N | 025W | NWSE | Hilcorp Energy Company |
| 3003960070 | San Juan 29-6 Unit 043  | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 26 | 029N | 026W | SWNE | Hilcorp Energy Company |
| 3003921324 | San Juan 29-6 Unit 043A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 26 | 029N | 026W | NWSE | Hilcorp Energy Company |
| 3003907519 | San Juan 29-6 Unit 044  | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 26 | 029N | 026W | SESW | Hilcorp Energy Company |
| 3003921402 | San Juan 29-6 Unit 044A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 26 | 029N | 026W | SWNW | Hilcorp Energy Company |
| 3003907539 | San Juan 29-6 Unit 045  | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 27 | 029N | 027W | SENE | Hilcorp Energy Company |
| 3003921325 | San Juan 29-6 Unit 045A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 27 | 029N | 027W | NESE | Hilcorp Energy Company |
| 3003907526 | San Juan 29-6 Unit 046  | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 27 | 029N | 027W | NESW | Hilcorp Energy Company |
| 3003921287 | San Juan 29-6 Unit 046A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 27 | 029N | 027W | NWNW | Hilcorp Energy Company |
| 3003907550 | San Juan 29-6 Unit 047  | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 28 | 029N | 028W | NWNE | Hilcorp Energy Company |
| 3003907550 | San Juan 29-6 Unit 047  | Blanco P. C. South   | Flowing        | NM | Rio Arriba | 28 | 029N | 028W | NWNE | Hilcorp Energy Company |
| 3003907550 | San Juan 29-6 Unit 047  | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 28 | 029N | 028W | NWNE | Hilcorp Energy Company |
| 3003921261 | San Juan 29-6 Unit 047A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 28 | 029N | 028W | SWSE | Hilcorp Energy Company |
| 3003926186 | San Juan 29-6 Unit 047B | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 28 | 029N | 028W | SENE | Hilcorp Energy Company |
| 3003927238 | San Juan 29-6 Unit 047M | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 28 | 029N | 028W | SESE | Hilcorp Energy Company |
| 3003907502 | San Juan 29-6 Unit 048  | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 35 | 029N | 035W | NENE | Hilcorp Energy Company |
| 3003921316 | San Juan 29-6 Unit 048A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 35 | 029N | 035W | NESE | Hilcorp Energy Company |
| 3003907474 | San Juan 29-6 Unit 049  | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 35 | 029N | 035W | SESW | Hilcorp Energy Company |
| 3003921315 | San Juan 29-6 Unit 049A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 35 | 029N | 035W | SWNW | Hilcorp Energy Company |
| 3003907495 | San Juan 29-6 Unit 050  | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 36 | 029N | 036W | SWNE | Hilcorp Energy Company |
| 3003921312 | San Juan 29-6 Unit 050A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 36 | 029N | 036W | NWSE | Hilcorp Energy Company |
| 3003907470 | San Juan 29-6 Unit 051  | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 31 | 029N | 006W | SESW | Hilcorp Energy Company |
| 3003907470 | San Juan 29-6 Unit 051  | Blanco P. C. South   | Flowing        | NM | Rio Arriba | 31 | 029N | 006W | SESW | Hilcorp Energy Company |
| 3003921088 | San Juan 29-6 Unit 051A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 31 | 029N | 006W | NWNW | Hilcorp Energy Company |
| 3003921088 | San Juan 29-6 Unit 051A | Blanco P. C. South   | Flowing        | NM | Rio Arriba | 31 | 029N | 006W | NWNW | Hilcorp Energy Company |
| 3003907503 | San Juan 29-6 Unit 052  | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 34 | 029N | 034W | NWNE | Hilcorp Energy Company |
| 3003921368 | San Juan 29-6 Unit 052A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 34 | 029N | 034W | SESE | Hilcorp Energy Company |
| 3003907509 | San Juan 29-6 Unit 053  | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 31 | 029N | 031W | NWNE | Hilcorp Energy Company |
| 3003907509 | San Juan 29-6 Unit 053  | Blanco P. C. South   | Flowing        | NM | Rio Arriba | 31 | 029N | 031W | NWNE | Hilcorp Energy Company |
| 3003921086 | San Juan 29-6 Unit 053A | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 31 | 029N | 006W | SWSE | Hilcorp Energy Company |
| 3003921086 | San Juan 29-6 Unit 053A | Blanco P. C. South   | Flowing        | NM | Rio Arriba | 31 | 029N | 006W | SWSE | Hilcorp Energy Company |
| 3003907695 | San Juan 29-6 Unit 054  | Blanco-Mesaverde     | Flowing        | NM | Rio Arriba | 4  | 029N | 006W | NESW | Hilcorp Energy Company |

|            |                         |                      |         |    |            |    |      |      |      |                        |
|------------|-------------------------|----------------------|---------|----|------------|----|------|------|------|------------------------|
| 3003921416 | San Juan 29-6 Unit 054A | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 4  | 029N | 006W | SWNW | Hilcorp Energy Company |
| 3003929735 | San Juan 29-6 Unit 054B | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 4  | 029N | 006W | SESW | Hilcorp Energy Company |
| 3003929350 | San Juan 29-6 Unit 054C | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 4  | 029N | 006W | NENW | Hilcorp Energy Company |
| 3003907613 | San Juan 29-6 Unit 055  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 18 | 029N | 006W | NESW | Hilcorp Energy Company |
| 3003929359 | San Juan 29-6 Unit 055B | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 18 | 029N | 006W | SESW | Hilcorp Energy Company |
| 3003929360 | San Juan 29-6 Unit 055C | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 18 | 029N | 006W | SENW | Hilcorp Energy Company |
| 3003907468 | San Juan 29-6 Unit 056  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 33 | 029N | 033W | SESW | Hilcorp Energy Company |
| 3003921085 | San Juan 29-6 Unit 056A | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 33 | 029N | 033W | NENW | Hilcorp Energy Company |
| 3003907504 | San Juan 29-6 Unit 057  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 33 | 029N | 033W | NENE | Hilcorp Energy Company |
| 3003921087 | San Juan 29-6 Unit 057A | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 33 | 029N | 033W | SESE | Hilcorp Energy Company |
| 3003907527 | San Juan 29-6 Unit 058  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 28 | 029N | 028W | NESW | Hilcorp Energy Company |
| 3003921262 | San Juan 29-6 Unit 058A | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 28 | 029N | 006W | NWNW | Hilcorp Energy Company |
| 3003921262 | San Juan 29-6 Unit 058A | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 28 | 029N | 006W | NWNW | Hilcorp Energy Company |
| 3003929231 | San Juan 29-6 Unit 058C | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 28 | 029N | 028W | SENW | Hilcorp Energy Company |
| 3003907698 | San Juan 29-6 Unit 059  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 5  | 029N | 006W | SENE | Hilcorp Energy Company |
| 3003921417 | San Juan 29-6 Unit 059A | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 5  | 029N | 006W | NESE | Hilcorp Energy Company |
| 3003929463 | San Juan 29-6 Unit 059B | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 5  | 029N | 006W | NWNE | Hilcorp Energy Company |
| 3003929868 | San Juan 29-6 Unit 059C | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 5  | 029N | 005W | SWSE | Hilcorp Energy Company |
| 3003907621 | San Juan 29-6 Unit 060  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 18 | 029N | 006W | SENE | Hilcorp Energy Company |
| 3003921227 | San Juan 29-6 Unit 060A | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 18 | 029N | 006W | NWSE | Hilcorp Energy Company |
| 3003929765 | San Juan 29-6 Unit 060C | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 18 | 029N | 006W | NESE | Hilcorp Energy Company |
| 3003930497 | San Juan 29-6 Unit 060M | Basin Dakota         | Flowing | NM | Rio Arriba | 18 | 029N | 006W | SENW | Hilcorp Energy Company |
| 3003930497 | San Juan 29-6 Unit 060M | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 18 | 029N | 006W | SENW | Hilcorp Energy Company |
| 3003907577 | San Juan 29-6 Unit 061  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 19 | 029N | 006W | NESW | Hilcorp Energy Company |
| 3003921247 | San Juan 29-6 Unit 061A | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 19 | 029N | 006W | NENW | Hilcorp Energy Company |
| 3003929618 | San Juan 29-6 Unit 061B | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 19 | 029N | 006W | SWNW | Hilcorp Energy Company |
| 3003930985 | San Juan 29-6 Unit 061M | Basin Dakota         | Flowing | NM | Rio Arriba | 19 | 029N | 006W | NESW | Hilcorp Energy Company |
| 3003930985 | San Juan 29-6 Unit 061M | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 19 | 029N | 006W | NESW | Hilcorp Energy Company |
| 3003907701 | San Juan 29-6 Unit 062  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 4  | 029N | 006W | NENE | Hilcorp Energy Company |
| 3003921126 | San Juan 29-6 Unit 062A | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 4  | 029N | 004W | SESE | Hilcorp Energy Company |
| 3003927864 | San Juan 29-6 Unit 062B | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 4  | 029N | 006W | SWNE | Hilcorp Energy Company |
| 3003929434 | San Juan 29-6 Unit 062C | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 4  | 029N | 006W | NESE | Hilcorp Energy Company |
| 3003907553 | San Juan 29-6 Unit 063  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 30 | 029N | 006W | NENE | Hilcorp Energy Company |
| 3003921089 | San Juan 29-6 Unit 063A | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 30 | 029N | 030W | SESE | Hilcorp Energy Company |
| 3003929764 | San Juan 29-6 Unit 063B | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 30 | 029N | 030W | SENE | Hilcorp Energy Company |
| 3003929452 | San Juan 29-6 Unit 063C | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 30 | 029N | 030W | NWSE | Hilcorp Energy Company |
| 3003907666 | San Juan 29-6 Unit 064  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 9  | 029N | 006W | SWNE | Hilcorp Energy Company |
| 3003921566 | San Juan 29-6 Unit 064A | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 9  | 029N | 009W | SESE | Hilcorp Energy Company |
| 3003929870 | San Juan 29-6 Unit 064B | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 9  | 029N | 006W | NWNE | Hilcorp Energy Company |
| 3003929331 | San Juan 29-6 Unit 064M | Basin Dakota         | Flowing | NM | Rio Arriba | 9  | 029N | 009W | NWSE | Hilcorp Energy Company |
| 3003929331 | San Juan 29-6 Unit 064M | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 9  | 029N | 009W | NWSE | Hilcorp Energy Company |
| 3003907594 | San Juan 29-6 Unit 065  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 19 | 029N | 006W | NENE | Hilcorp Energy Company |
| 3003921248 | San Juan 29-6 Unit 065A | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 19 | 029N | 006W | NWSE | Hilcorp Energy Company |
| 3003930447 | San Juan 29-6 Unit 065B | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 19 | 029N | 006W | NESE | Hilcorp Energy Company |
| 3003929808 | San Juan 29-6 Unit 065C | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 19 | 029N | 006W | NWNE | Hilcorp Energy Company |
| 3003907660 | San Juan 29-6 Unit 066  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 9  | 029N | 009W | NESW | Hilcorp Energy Company |
| 3003921420 | San Juan 29-6 Unit 066A | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 9  | 029N | 006W | NWNW | Hilcorp Energy Company |
| 3003929533 | San Juan 29-6 Unit 066B | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 9  | 029N | 009W | SWSW | Hilcorp Energy Company |
| 3003907547 | San Juan 29-6 Unit 068  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 29 | 029N | 006W | NENE | Hilcorp Energy Company |
| 3003907547 | San Juan 29-6 Unit 068  | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 29 | 029N | 006W | NENE | Hilcorp Energy Company |
| 3003921091 | San Juan 29-6 Unit 068A | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 29 | 029N | 029W | SWSE | Hilcorp Energy Company |
| 3003926185 | San Juan 29-6 Unit 068B | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 29 | 029N | 029W | SWNE | Hilcorp Energy Company |
| 3003929563 | San Juan 29-6 Unit 068C | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 29 | 029N | 029W | NESE | Hilcorp Energy Company |
| 3003907549 | San Juan 29-6 Unit 069  | Basin Dakota         | Flowing | NM | Rio Arriba | 26 | 029N | 026W | NENE | Hilcorp Energy Company |
| 3003907549 | San Juan 29-6 Unit 069  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 26 | 029N | 026W | NENE | Hilcorp Energy Company |
| 3003926340 | San Juan 29-6 Unit 069M | Basin Dakota         | Flowing | NM | Rio Arriba | 26 | 029N | 026W | NENW | Hilcorp Energy Company |
| 3003926340 | San Juan 29-6 Unit 069M | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 26 | 029N | 026W | NENW | Hilcorp Energy Company |
| 3003907517 | San Juan 29-6 Unit 070  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 29 | 029N | 029W | SESW | Hilcorp Energy Company |
| 3003921263 | San Juan 29-6 Unit 070A | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 29 | 029N | 029W | SWNW | Hilcorp Energy Company |


|            |                         |                      |         |    |            |    |      |      |      |                        |
|------------|-------------------------|----------------------|---------|----|------------|----|------|------|------|------------------------|
| 3003921263 | San Juan 29-6 Unit 070A | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 29 | 029N | 029W | SWNW | Hilcorp Energy Company |
| 3003926738 | San Juan 29-6 Unit 070B | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 29 | 029N | 029W | NWSW | Hilcorp Energy Company |
| 3003926717 | San Juan 29-6 Unit 070C | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 29 | 029N | 029W | SENW | Hilcorp Energy Company |
| 3003907634 | San Juan 29-6 Unit 071  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 17 | 029N | 017W | NWNE | Hilcorp Energy Company |
| 3003921229 | San Juan 29-6 Unit 071A | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 17 | 029N | 006W | SWSE | Hilcorp Energy Company |
| 3003929867 | San Juan 29-6 Unit 071C | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 16 | 029N | 016W | NWSW | Hilcorp Energy Company |
| 3003930133 | San Juan 29-6 Unit 071M | Basin Dakota         | Flowing | NM | Rio Arriba | 17 | 029N | 017W | NWNE | Hilcorp Energy Company |
| 3003930133 | San Juan 29-6 Unit 071M | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 17 | 029N | 017W | NWNE | Hilcorp Energy Company |
| 3003907558 | San Juan 29-6 Unit 072  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 22 | 029N | 022W | SWSW | Hilcorp Energy Company |
| 3003921344 | San Juan 29-6 Unit 072A | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 22 | 029N | 022W | SENW | Hilcorp Energy Company |
| 3003921344 | San Juan 29-6 Unit 072A | Basin Fruitland Coal | Flowing | NM | Rio Arriba | 22 | 029N | 022W | SENW | Hilcorp Energy Company |
| 3003907571 | San Juan 29-6 Unit 073  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 20 | 029N | 006W | NWSW | Hilcorp Energy Company |
| 3003921249 | San Juan 29-6 Unit 073A | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 20 | 029N | 006W | NWNW | Hilcorp Energy Company |
| 3003926676 | San Juan 29-6 Unit 073B | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 20 | 029N | 006W | NENW | Hilcorp Energy Company |
| 3003926673 | San Juan 29-6 Unit 073C | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 20 | 029N | 006W | SESW | Hilcorp Energy Company |
| 3003907584 | San Juan 29-6 Unit 074  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 20 | 029N | 006W | SENE | Hilcorp Energy Company |
| 3003921250 | San Juan 29-6 Unit 074A | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 20 | 029N | 020W | NESE | Hilcorp Energy Company |
| 3003929923 | San Juan 29-6 Unit 074B | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 20 | 029N | 020W | NWSE | Hilcorp Energy Company |
| 3003929694 | San Juan 29-6 Unit 074C | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 20 | 029N | 006W | NWNE | Hilcorp Energy Company |
| 3003907579 | San Juan 29-6 Unit 075  | Basin Dakota         | Flowing | NM | Rio Arriba | 23 | 029N | 023W | SENE | Hilcorp Energy Company |
| 3003929749 | San Juan 29-6 Unit 075F | Basin Dakota         | Flowing | NM | Rio Arriba | 23 | 029N | 023W | NENE | Hilcorp Energy Company |
| 3003929749 | San Juan 29-6 Unit 075F | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 23 | 029N | 023W | NENE | Hilcorp Energy Company |
| 3003927553 | San Juan 29-6 Unit 075M | Basin Dakota         | Flowing | NM | Rio Arriba | 23 | 029N | 023W | SESE | Hilcorp Energy Company |
| 3003927553 | San Juan 29-6 Unit 075M | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 23 | 029N | 023W | SESE | Hilcorp Energy Company |
| 3003907557 | San Juan 29-6 Unit 076  | Blanco P. C. South   | Flowing | NM | Rio Arriba | 23 | 029N | 023W | SESW | Hilcorp Energy Company |
| 3003929866 | San Juan 29-6 Unit 076F | Basin Dakota         | Flowing | NM | Rio Arriba | 23 | 029N | 023W | NWSW | Hilcorp Energy Company |
| 3003929866 | San Juan 29-6 Unit 076F | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 23 | 029N | 023W | NWSW | Hilcorp Energy Company |
| 3003926341 | San Juan 29-6 Unit 076M | Basin Dakota         | Flowing | NM | Rio Arriba | 23 | 029N | 023W | SWNW | Hilcorp Energy Company |
| 3003926341 | San Juan 29-6 Unit 076M | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 23 | 029N | 023W | SWNW | Hilcorp Energy Company |
| 3003907581 | San Juan 29-6 Unit 077  | Basin Dakota         | Flowing | NM | Rio Arriba | 22 | 029N | 022W | SENE | Hilcorp Energy Company |
| 3003907581 | San Juan 29-6 Unit 077  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 22 | 029N | 022W | SENE | Hilcorp Energy Company |
| 3003926409 | San Juan 29-6 Unit 077M | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 22 | 029N | 022W | SESE | Hilcorp Energy Company |
| 3003907578 | San Juan 29-6 Unit 078  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 22 | 029N | 022W | NWSW | Hilcorp Energy Company |
| 3003927509 | San Juan 29-6 Unit 078M | Basin Dakota         | Flowing | NM | Rio Arriba | 22 | 029N | 022W | NWNW | Hilcorp Energy Company |
| 3003927509 | San Juan 29-6 Unit 078M | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 22 | 029N | 022W | NWNW | Hilcorp Energy Company |
| 3003920225 | San Juan 29-6 Unit 079  | Basin Dakota         | Flowing | NM | Rio Arriba | 24 | 029N | 024W | SWSW | Hilcorp Energy Company |
| 3003920225 | San Juan 29-6 Unit 079  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 24 | 029N | 024W | SWSW | Hilcorp Energy Company |
| 3003927573 | San Juan 29-6 Unit 079M | Basin Dakota         | Flowing | NM | Rio Arriba | 24 | 029N | 024W | SENW | Hilcorp Energy Company |
| 3003927573 | San Juan 29-6 Unit 079M | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 24 | 029N | 024W | SENW | Hilcorp Energy Company |
| 3003908077 | San Juan 29-6 Unit 080  | Basin Dakota         | Flowing | NM | Rio Arriba | 24 | 029N | 024W | SWNE | Hilcorp Energy Company |
| 3003908077 | San Juan 29-6 Unit 080  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 24 | 029N | 024W | SWNE | Hilcorp Energy Company |
| 3003927559 | San Juan 29-6 Unit 080M | Basin Dakota         | Flowing | NM | Rio Arriba | 24 | 029N | 024W | SWSE | Hilcorp Energy Company |
| 3003927559 | San Juan 29-6 Unit 080M | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 24 | 029N | 024W | SWSE | Hilcorp Energy Company |
| 3003907528 | San Juan 29-6 Unit 081  | Basin Dakota         | Flowing | NM | Rio Arriba | 25 | 029N | 025W | NWSW | Hilcorp Energy Company |
| 3003929863 | San Juan 29-6 Unit 081F | Basin Dakota         | Flowing | NM | Rio Arriba | 25 | 029N | 025W | SWSW | Hilcorp Energy Company |
| 3003929863 | San Juan 29-6 Unit 081F | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 25 | 029N | 025W | SWSW | Hilcorp Energy Company |
| 3003926374 | San Juan 29-6 Unit 081M | Basin Dakota         | Flowing | NM | Rio Arriba | 25 | 029N | 025W | SENW | Hilcorp Energy Company |
| 3003926374 | San Juan 29-6 Unit 081M | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 25 | 029N | 025W | SENW | Hilcorp Energy Company |
| 3003920357 | San Juan 29-6 Unit 082  | Basin Dakota         | Flowing | NM | Rio Arriba | 25 | 029N | 025W | NWNE | Hilcorp Energy Company |
| 3003920357 | San Juan 29-6 Unit 082  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 25 | 029N | 025W | NWNE | Hilcorp Energy Company |
| 3003926462 | San Juan 29-6 Unit 082M | Basin Dakota         | Flowing | NM | Rio Arriba | 25 | 029N | 025W | SWSE | Hilcorp Energy Company |
| 3003926462 | San Juan 29-6 Unit 082M | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 25 | 029N | 025W | SWSE | Hilcorp Energy Company |
| 3003907604 | San Juan 29-6 Unit 083  | Basin Dakota         | Flowing | NM | Rio Arriba | 13 | 029N | 013W | SWSW | Hilcorp Energy Company |
| 3003907604 | San Juan 29-6 Unit 083  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 13 | 029N | 013W | SWSW | Hilcorp Energy Company |
| 3003927526 | San Juan 29-6 Unit 083M | Basin Dakota         | Flowing | NM | Rio Arriba | 13 | 029N | 013W | NENW | Hilcorp Energy Company |
| 3003927526 | San Juan 29-6 Unit 083M | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 13 | 029N | 013W | NENW | Hilcorp Energy Company |
| 3003907623 | San Juan 29-6 Unit 084  | Basin Dakota         | Flowing | NM | Rio Arriba | 14 | 029N | 014W | SWNE | Hilcorp Energy Company |
| 3003907623 | San Juan 29-6 Unit 084  | Blanco-Mesaverde     | Flowing | NM | Rio Arriba | 14 | 029N | 014W | SWNE | Hilcorp Energy Company |
| 3003926183 | San Juan 29-6 Unit 084M | Basin Dakota         | Flowing | NM | Rio Arriba | 14 | 029N | 014W | NWNW | Hilcorp Energy Company |

|            |                         |                  |                |    |            |    |      |      |      |                        |
|------------|-------------------------|------------------|----------------|----|------------|----|------|------|------|------------------------|
| 3003926183 | San Juan 29-6 Unit 084M | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 14 | 029N | 014W | NWNW | Hilcorp Energy Company |
| 3003907551 | San Juan 29-6 Unit 085  | Basin Dakota     | Flowing        | NM | Rio Arriba | 27 | 029N | 027W | NENE | Hilcorp Energy Company |
| 3003907551 | San Juan 29-6 Unit 085  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 27 | 029N | 027W | NENE | Hilcorp Energy Company |
| 3003926343 | San Juan 29-6 Unit 085M | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 27 | 029N | 002W | SWSE | Hilcorp Energy Company |
| 3003907516 | San Juan 29-6 Unit 086  | Basin Dakota     | Flowing        | NM | Rio Arriba | 27 | 029N | 027W | SESW | Hilcorp Energy Company |
| 3003907516 | San Juan 29-6 Unit 086  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 27 | 029N | 027W | SESW | Hilcorp Energy Company |
| 3003926443 | San Juan 29-6 Unit 086M | Basin Dakota     | Flowing        | NM | Rio Arriba | 27 | 029N | 027W | NENW | Hilcorp Energy Company |
| 3003926443 | San Juan 29-6 Unit 086M | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 27 | 029N | 027W | NENW | Hilcorp Energy Company |
| 3003907492 | San Juan 29-6 Unit 087  | Basin Dakota     | Flowing        | NM | Rio Arriba | 33 | 029N | 033W | SENE | Hilcorp Energy Company |
| 3003907492 | San Juan 29-6 Unit 087  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 33 | 029N | 033W | SENE | Hilcorp Energy Company |
| 3003926187 | San Juan 29-6 Unit 087M | Basin Dakota     | Flowing        | NM | Rio Arriba | 33 | 029N | 033W | SWSE | Hilcorp Energy Company |
| 3003926187 | San Juan 29-6 Unit 087M | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 33 | 029N | 033W | SWSE | Hilcorp Energy Company |
| 3003907491 | San Juan 29-6 Unit 088  | Basin Dakota     | Flowing        | NM | Rio Arriba | 33 | 029N | 033W | NWSW | Hilcorp Energy Company |
| 3003907491 | San Juan 29-6 Unit 088  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 33 | 029N | 033W | NWSW | Hilcorp Energy Company |
| 3003927554 | San Juan 29-6 Unit 088M | Basin Dakota     | Flowing        | NM | Rio Arriba | 33 | 029N | 033W | SENE | Hilcorp Energy Company |
| 3003927554 | San Juan 29-6 Unit 088M | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 33 | 029N | 033W | SENE | Hilcorp Energy Company |
| 3003907641 | San Juan 29-6 Unit 089  | Basin Dakota     | Flowing        | NM | Rio Arriba | 11 | 029N | 006W | SWSW | Hilcorp Energy Company |
| 3003927520 | San Juan 29-6 Unit 089F | Basin Dakota     | Flowing        | NM | Rio Arriba | 11 | 029N | 006W | SESW | Hilcorp Energy Company |
| 3003927520 | San Juan 29-6 Unit 089F | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 11 | 029N | 006W | SESW | Hilcorp Energy Company |
| 3003927581 | San Juan 29-6 Unit 089M | Basin Dakota     | Perm Abandoned | NM | Rio Arriba | 11 | 029N | 006W |      | Hilcorp Energy Company |
| 3003927581 | San Juan 29-6 Unit 089M | Blanco Mesaverde | Perm Abandoned | NM | Rio Arriba | 11 | 029N | 006W |      | Hilcorp Energy Company |
| 3003930145 | San Juan 29-6 Unit 089R | Basin Dakota     | Flowing        | NM | Rio Arriba | 11 | 029N | 011W | NWSE | Hilcorp Energy Company |
| 3003930145 | San Juan 29-6 Unit 089R | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 11 | 029N | 011W | NWSE | Hilcorp Energy Company |
| 3003907622 | San Juan 29-6 Unit 090  | Basin Dakota     | Flowing        | NM | Rio Arriba | 15 | 029N | 015W | SWNE | Hilcorp Energy Company |
| 3003907622 | San Juan 29-6 Unit 090  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 15 | 029N | 015W | SWNE | Hilcorp Energy Company |
| 3003927623 | San Juan 29-6 Unit 090F | Basin Dakota     | Flowing        | NM | Rio Arriba | 15 | 029N | 015W | NENE | Hilcorp Energy Company |
| 3003927623 | San Juan 29-6 Unit 090F | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 15 | 029N | 015W | NENE | Hilcorp Energy Company |
| 3003927560 | San Juan 29-6 Unit 090M | Basin Dakota     | Flowing        | NM | Rio Arriba | 15 | 029N | 006W | NENW | Hilcorp Energy Company |
| 3003927560 | San Juan 29-6 Unit 090M | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 15 | 029N | 006W | NENW | Hilcorp Energy Company |
| 3003907582 | San Juan 29-6 Unit 091  | Basin Dakota     | Perm Abandoned | NM | Rio Arriba | 21 | 029N | 006W |      | Hilcorp Energy Company |
| 3003907582 | San Juan 29-6 Unit 091  | Blanco Mesaverde | Perm Abandoned | NM | Rio Arriba | 21 | 029N | 006W |      | Hilcorp Energy Company |
| 3003929516 | San Juan 29-6 Unit 091F | Basin Dakota     | Flowing        | NM | Rio Arriba | 21 | 029N | 021W | NWNE | Hilcorp Energy Company |
| 3003929516 | San Juan 29-6 Unit 091F | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 21 | 029N | 021W | NWNE | Hilcorp Energy Company |
| 3003926419 | San Juan 29-6 Unit 091M | Basin Dakota     | Flowing        | NM | Rio Arriba | 21 | 029N | 021W | NESE | Hilcorp Energy Company |
| 3003926419 | San Juan 29-6 Unit 091M | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 21 | 029N | 021W | NESE | Hilcorp Energy Company |
| 3003907646 | San Juan 29-6 Unit 092  | Basin Dakota     | Flowing        | NM | Rio Arriba | 12 | 029N | 006W | SWSW | Hilcorp Energy Company |
| 3003907646 | San Juan 29-6 Unit 092  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 12 | 029N | 006W | SWSW | Hilcorp Energy Company |
| 3003927555 | San Juan 29-6 Unit 092M | Basin Dakota     | Flowing        | NM | Rio Arriba | 12 | 029N | 006W | NENW | Hilcorp Energy Company |
| 3003927555 | San Juan 29-6 Unit 092M | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 12 | 029N | 006W | NENW | Hilcorp Energy Company |
| 3003907629 | San Juan 29-6 Unit 093  | Basin Dakota     | Flowing        | NM | Rio Arriba | 16 | 029N | 016W | NWNE | Hilcorp Energy Company |
| 3003907629 | San Juan 29-6 Unit 093  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 16 | 029N | 016W | NWNE | Hilcorp Energy Company |
| 3003926405 | San Juan 29-6 Unit 093M | Basin Dakota     | Flowing        | NM | Rio Arriba | 16 | 029N | 016W | SWSE | Hilcorp Energy Company |
| 3003926405 | San Juan 29-6 Unit 093M | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 16 | 029N | 016W | SWSE | Hilcorp Energy Company |
| 3003907603 | San Juan 29-6 Unit 094  | Basin Dakota     | Flowing        | NM | Rio Arriba | 16 | 029N | 016W | SWSW | Hilcorp Energy Company |
| 3003907603 | San Juan 29-6 Unit 094  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 16 | 029N | 016W | SWSW | Hilcorp Energy Company |
| 3003926339 | San Juan 29-6 Unit 094M | Basin Dakota     | Flowing        | NM | Rio Arriba | 16 | 029N | 016W | SENE | Hilcorp Energy Company |
| 3003926339 | San Juan 29-6 Unit 094M | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 16 | 029N | 016W | SENE | Hilcorp Energy Company |
| 3003920027 | San Juan 29-6 Unit 095  | Basin Dakota     | Flowing        | NM | Rio Arriba | 34 | 029N | 034W | NWSW | Hilcorp Energy Company |
| 3003920027 | San Juan 29-6 Unit 095  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 34 | 029N | 034W | NWSW | Hilcorp Energy Company |
| 3003926466 | San Juan 29-6 Unit 095M | Basin Dakota     | Flowing        | NM | Rio Arriba | 34 | 029N | 034W | SWSE | Hilcorp Energy Company |
| 3003926466 | San Juan 29-6 Unit 095M | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 34 | 029N | 034W | SWSE | Hilcorp Energy Company |
| 3003920241 | San Juan 29-6 Unit 097  | Basin Dakota     | Flowing        | NM | Rio Arriba | 35 | 029N | 035W | SWSW | Hilcorp Energy Company |
| 3003920241 | San Juan 29-6 Unit 097  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 35 | 029N | 035W | SWSW | Hilcorp Energy Company |
| 3003926342 | San Juan 29-6 Unit 097M | Basin Dakota     | Flowing        | NM | Rio Arriba | 35 | 029N | 035W | SWSE | Hilcorp Energy Company |
| 3003926342 | San Juan 29-6 Unit 097M | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 35 | 029N | 035W | SWSE | Hilcorp Energy Company |
| 3003920297 | San Juan 29-6 Unit 098  | Basin Dakota     | Flowing        | NM | Rio Arriba | 26 | 029N | 026W | NESW | Hilcorp Energy Company |
| 3003920297 | San Juan 29-6 Unit 098  | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 26 | 029N | 026W | NESW | Hilcorp Energy Company |
| 3003926458 | San Juan 29-6 Unit 098M | Basin Dakota     | Flowing        | NM | Rio Arriba | 26 | 029N | 026W | NESE | Hilcorp Energy Company |
| 3003926458 | San Juan 29-6 Unit 098M | Blanco-Mesaverde | Flowing        | NM | Rio Arriba | 26 | 029N | 026W | NESE | Hilcorp Energy Company |

|            |                         |                            |                |    |            |    |      |      |      |                        |
|------------|-------------------------|----------------------------|----------------|----|------------|----|------|------|------|------------------------|
| 3003920298 | San Juan 29-6 Unit 099  | Basin Dakota               | Flowing        | NM | Rio Arriba | 34 | 029N | 034W | NENE | Hilcorp Energy Company |
| 3003920298 | San Juan 29-6 Unit 099  | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 34 | 029N | 034W | NENE | Hilcorp Energy Company |
| 3003926430 | San Juan 29-6 Unit 099M | Basin Dakota               | Flowing        | NM | Rio Arriba | 34 | 029N | 034W | SENW | Hilcorp Energy Company |
| 3003926430 | San Juan 29-6 Unit 099M | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 34 | 029N | 034W | SENW | Hilcorp Energy Company |
| 3003920299 | San Juan 29-6 Unit 100  | Basin Dakota               | Flowing        | NM | Rio Arriba | 35 | 029N | 035W | SWNE | Hilcorp Energy Company |
| 3003920299 | San Juan 29-6 Unit 100  | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 35 | 029N | 035W | SWNE | Hilcorp Energy Company |
| 3003926337 | San Juan 29-6 Unit 100M | Basin Dakota               | Flowing        | NM | Rio Arriba | 35 | 029N | 035W | NENW | Hilcorp Energy Company |
| 3003926337 | San Juan 29-6 Unit 100M | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 35 | 029N | 035W | NENW | Hilcorp Energy Company |
| 3003920355 | San Juan 29-6 Unit 101  | Basin Dakota               | Flowing        | NM | Rio Arriba | 36 | 029N | 036W | NWNE | Hilcorp Energy Company |
| 3003926338 | San Juan 29-6 Unit 101M | Basin Dakota               | Flowing        | NM | Rio Arriba | 36 | 029N | 036W | SWSE | Hilcorp Energy Company |
| 3003926338 | San Juan 29-6 Unit 101M | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 36 | 029N | 036W | SWSE | Hilcorp Energy Company |
| 3003930721 | San Juan 29-6 Unit 101N | Basin Dakota               | Flowing        | NM | Rio Arriba | 36 | 029N | 006W | SENE | Hilcorp Energy Company |
| 3003930721 | San Juan 29-6 Unit 101N | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 36 | 029N | 006W | SENE | Hilcorp Energy Company |
| 3003920365 | San Juan 29-6 Unit 102  | Basin Dakota               | Flowing        | NM | Rio Arriba | 10 | 029N | 006W | SWNE | Hilcorp Energy Company |
| 3003920365 | San Juan 29-6 Unit 102  | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 10 | 029N | 006W | SWNE | Hilcorp Energy Company |
| 3003927517 | San Juan 29-6 Unit 102M | Basin Dakota               | Flowing        | NM | Rio Arriba | 10 | 029N | 006W | SWSE | Hilcorp Energy Company |
| 3003927517 | San Juan 29-6 Unit 102M | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 10 | 029N | 006W | SWSE | Hilcorp Energy Company |
| 3003920359 | San Juan 29-6 Unit 103  | Basin Dakota               | Flowing        | NM | Rio Arriba | 11 | 029N | 011W | SWNE | Hilcorp Energy Company |
| 3003920359 | San Juan 29-6 Unit 103  | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 11 | 029N | 011W | SWNE | Hilcorp Energy Company |
| 3003927519 | San Juan 29-6 Unit 103M | Basin Dakota               | Flowing        | NM | Rio Arriba | 11 | 029N | 006W | NWNW | Hilcorp Energy Company |
| 3003927519 | San Juan 29-6 Unit 103M | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 11 | 029N | 006W | NWNW | Hilcorp Energy Company |
| 3003920490 | San Juan 29-6 Unit 104  | Basin Dakota               | Flowing        | NM | Rio Arriba | 14 | 029N | 014W | SESW | Hilcorp Energy Company |
| 3003920490 | San Juan 29-6 Unit 104  | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 14 | 029N | 014W | SESW | Hilcorp Energy Company |
| 3003927592 | San Juan 29-6 Unit 104M | Basin Dakota               | Flowing        | NM | Rio Arriba | 14 | 029N | 014W | SWSE | Hilcorp Energy Company |
| 3003927592 | San Juan 29-6 Unit 104M | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 14 | 029N | 014W | SWSE | Hilcorp Energy Company |
| 3003926467 | San Juan 29-6 Unit 105R | Basin Dakota               | Flowing        | NM | Rio Arriba | 28 | 029N | 028W | SWSW | Hilcorp Energy Company |
| 3003926467 | San Juan 29-6 Unit 105R | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 28 | 029N | 028W | SWSW | Hilcorp Energy Company |
| 3003921039 | San Juan 29-6 Unit 106  | Basin Dakota               | Flowing        | NM | Rio Arriba | 31 | 029N | 006W | SWSW | Hilcorp Energy Company |
| 3003921039 | San Juan 29-6 Unit 106  | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 31 | 029N | 006W | SWSW | Hilcorp Energy Company |
| 3003927542 | San Juan 29-6 Unit 106M | Basin Dakota               | Flowing        | NM | Rio Arriba | 31 | 029N | 006W | NWSE | Hilcorp Energy Company |
| 3003927542 | San Juan 29-6 Unit 106M | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 31 | 029N | 006W | NWSE | Hilcorp Energy Company |
| 3003920453 | San Juan 29-6 Unit 107  | Basin Dakota               | Flowing        | NM | Rio Arriba | 36 | 029N | 036W | SWSW | Hilcorp Energy Company |
| 3003929728 | San Juan 29-6 Unit 107F | Basin Dakota               | Flowing        | NM | Rio Arriba | 36 | 029N | 036W | NESW | Hilcorp Energy Company |
| 3003929728 | San Juan 29-6 Unit 107F | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 36 | 029N | 036W | NESW | Hilcorp Energy Company |
| 3003927568 | San Juan 29-6 Unit 107M | Basin Dakota               | Flowing        | NM | Rio Arriba | 36 | 029N | 036W | NENW | Hilcorp Energy Company |
| 3003927568 | San Juan 29-6 Unit 107M | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 36 | 029N | 036W | NENW | Hilcorp Energy Company |
| 3003927531 | San Juan 29-6 Unit 108  | Basin Dakota               | Flowing        | NM | Rio Arriba | 31 | 029N | 031W | SENE | Hilcorp Energy Company |
| 3003927531 | San Juan 29-6 Unit 108  | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 31 | 029N | 031W | SENE | Hilcorp Energy Company |
| 3003927536 | San Juan 29-6 Unit 108M | Basin Dakota               | Flowing        | NM | Rio Arriba | 31 | 029N | 006W | SWNW | Hilcorp Energy Company |
| 3003927536 | San Juan 29-6 Unit 108M | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 31 | 029N | 006W | SWNW | Hilcorp Energy Company |
| 3003927529 | San Juan 29-6 Unit 109  | Basin Dakota               | Flowing        | NM | Rio Arriba | 32 | 029N | 032W | SENW | Hilcorp Energy Company |
| 3003927529 | San Juan 29-6 Unit 109  | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 32 | 029N | 032W | SENW | Hilcorp Energy Company |
| 3003930233 | San Juan 29-6 Unit 109M | Basin Dakota               | Flowing        | NM | Rio Arriba | 32 | 029N | 032W | SWNW | Hilcorp Energy Company |
| 3003930233 | San Juan 29-6 Unit 109M | Blanco-Mesaverde           | Flowing        | NM | Rio Arriba | 32 | 029N | 032W | SWNW | Hilcorp Energy Company |
| 3003921440 | San Juan 29-6 Unit 110  | Gobernador Pictured Cliffs | Flowing        | NM | Rio Arriba | 1  | 029N | 006W | SWNE | Hilcorp Energy Company |
| 3003921790 | San Juan 29-6 Unit 111  | Gobernador Pictured Cliffs | Flowing        | NM | Rio Arriba | 1  | 029N | 006W | NENW | Hilcorp Energy Company |
| 3003922995 | San Juan 29-6 Unit 114  | Basin Dakota               | Flowing        | NM | Rio Arriba | 7  | 029N | 007W | NENE | Hilcorp Energy Company |
| 3003926681 | San Juan 29-6 Unit 116P | Blanco P. C. South         | Flowing        | NM | Rio Arriba | 27 | 029N | 027W | NESW | Hilcorp Energy Company |
| 3003926681 | San Juan 29-6 Unit 116P | Basin Fruitland Coal       | Flowing        | NM | Rio Arriba | 27 | 029N | 027W | NESW | Hilcorp Energy Company |
| 3003907693 | San Juan 29-6 Unit 13   | Blanco Mesaverde           | Perm Abandoned | NM | Rio Arriba | 6  | 029N | 006W |      | Hilcorp Energy Company |
| 3003907673 | San Juan 29-6 Unit 14   | Blanco Mesaverde           | Perm Abandoned | NM | Rio Arriba | 7  | 029N | 006W |      | Hilcorp Energy Company |
| 3003907702 | San Juan 29-6 Unit 17   | Blanco Mesaverde           | Perm Abandoned | NM | Rio Arriba | 1  | 029N | 006W |      | Hilcorp Energy Company |
| 3003907682 | San Juan 29-6 Unit 18   | Blanco Mesaverde           | Perm Abandoned | NM | Rio Arriba | 5  | 029N | 006W |      | Hilcorp Energy Company |
| 3003907675 | San Juan 29-6 Unit 19   | Blanco Mesaverde           | Perm Abandoned | NM | Rio Arriba | 8  | 029N | 006W |      | Hilcorp Energy Company |
| 3003907652 | San Juan 29-6 Unit 20   | Blanco Mesaverde           | Perm Abandoned | NM | Rio Arriba | 8  | 029N | 006W |      | Hilcorp Energy Company |
| 3003924597 | San Juan 29-6 Unit 201  | Basin Fruitland Coal       | Flowing        | NM | Rio Arriba | 6  | 029N | 006W | SENE | Hilcorp Energy Company |
| 3003927504 | San Juan 29-6 Unit 201A | Basin Fruitland Coal       | Flowing        | NM | Rio Arriba | 6  | 029N | 006W | NESE | Hilcorp Energy Company |
| 3003924899 | San Juan 29-6 Unit 202  | Basin Fruitland Coal       | Flowing        | NM | Rio Arriba | 6  | 029N | 006W | NWSW | Hilcorp Energy Company |
| 3003927501 | San Juan 29-6 Unit 202A | Basin Fruitland Coal       | Flowing        | NM | Rio Arriba | 6  | 029N | 006W | NWNW | Hilcorp Energy Company |

|            |                              |                      |                |    |            |    |      |      |      |                        |
|------------|------------------------------|----------------------|----------------|----|------------|----|------|------|------|------------------------|
| 3003924735 | San Juan 29-6 Unit 203       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 7  | 029N | 006W | SWSW | Hilcorp Energy Company |
| 3003927544 | San Juan 29-6 Unit 203A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 7  | 029N | 006W | SWNW | Hilcorp Energy Company |
| 3003924822 | San Juan 29-6 Unit 204       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 7  | 029N | 007W | NENE | Hilcorp Energy Company |
| 3003927505 | San Juan 29-6 Unit 204A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 7  | 029N | 007W | NWSE | Hilcorp Energy Company |
| 3003924931 | San Juan 29-6 Unit 205       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 21 | 029N | 021W | NESW | Hilcorp Energy Company |
| 3003927855 | San Juan 29-6 Unit 205A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 21 | 029N | 021W | NENW | Hilcorp Energy Company |
| 3003924521 | San Juan 29-6 Unit 206       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 4  | 029N | 006W | SENE | Hilcorp Energy Company |
| 3003924516 | San Juan 29-6 Unit 207       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 2  | 029N | 006W | NESW | Hilcorp Energy Company |
| 3003927546 | San Juan 29-6 Unit 207A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 2  | 029N | 006W | NWNW | Hilcorp Energy Company |
| 3003924599 | San Juan 29-6 Unit 208       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 17 | 029N | 017W | SESW | Hilcorp Energy Company |
| 3003927540 | San Juan 29-6 Unit 208A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 17 | 029N | 006W | SWNW | Hilcorp Energy Company |
| 3003924580 | San Juan 29-6 Unit 209       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 17 | 029N | 017W | NWNE | Hilcorp Energy Company |
| 3003927539 | San Juan 29-6 Unit 209A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 17 | 029N | 006W | NWSE | Hilcorp Energy Company |
| 3003924747 | San Juan 29-6 Unit 210       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 20 | 029N | 006W | NWSW | Hilcorp Energy Company |
| 3003927835 | San Juan 29-6 Unit 210A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 20 | 029N | 006W | NENW | Hilcorp Energy Company |
| 3003924723 | San Juan 29-6 Unit 211       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 20 | 029N | 006W | SENE | Hilcorp Energy Company |
| 3003929606 | San Juan 29-6 Unit 211A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 20 | 029N | 020W | NWSE | Hilcorp Energy Company |
| 3003924592 | San Juan 29-6 Unit 212       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 30 | 029N | 006W | SESW | Hilcorp Energy Company |
| 3003924581 | San Juan 29-6 Unit 213       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 30 | 029N | 030W | SENE | Hilcorp Energy Company |
| 3003924606 | San Juan 29-6 Unit 214       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 3  | 029N | 006W | NENE | Hilcorp Energy Company |
| 3003927562 | San Juan 29-6 Unit 214A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 3  | 029N | 006W | SESE | Hilcorp Energy Company |
| 3003924726 | San Juan 29-6 Unit 215       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 3  | 029N | 006W | SESW | Hilcorp Energy Company |
| 3003927511 | San Juan 29-6 Unit 215A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 3  | 029N | 006W | NENW | Hilcorp Energy Company |
| 3003924607 | San Juan 29-6 Unit 216       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 4  | 029N | 006W | NESW | Hilcorp Energy Company |
| 3003927512 | San Juan 29-6 Unit 216A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 4  | 029N | 006W | NWNW | Hilcorp Energy Company |
| 3003924794 | San Juan 29-6 Unit 217       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 5  | 029N | 006W | SENE | Hilcorp Energy Company |
| 3003927502 | San Juan 29-6 Unit 217A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 5  | 029N | 005W | SWSE | Hilcorp Energy Company |
| 3003924746 | San Juan 29-6 Unit 218       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 5  | 029N | 005W | NWSW | Hilcorp Energy Company |
| 3003927506 | San Juan 29-6 Unit 218A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 5  | 029N | 005W | NWNW | Hilcorp Energy Company |
| 3003924608 | San Juan 29-6 Unit 219       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 10 | 029N | 006W | SWNE | Hilcorp Energy Company |
| 3003924690 | San Juan 29-6 Unit 220       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 11 | 029N | 006W | NENE | Hilcorp Energy Company |
| 3003929279 | San Juan 29-6 Unit 220A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 11 | 029N | 011W | SWSE | Hilcorp Energy Company |
| 3003924680 | San Juan 29-6 Unit 221       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 11 | 029N | 006W | SWSW | Hilcorp Energy Company |
| 3003927859 | San Juan 29-6 Unit 221A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 11 | 029N | 006W | SWNW | Hilcorp Energy Company |
| 3003924758 | San Juan 29-6 Unit 222       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 12 | 029N | 006W | SWNE | Hilcorp Energy Company |
| 3003924681 | San Juan 29-6 Unit 223       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 12 | 029N | 006W | NESW | Hilcorp Energy Company |
| 3003924759 | San Juan 29-6 Unit 224       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 13 | 029N | 006W | NWNE | Hilcorp Energy Company |
| 3003925267 | San Juan 29-6 Unit 225R      | Basin Fruitland Coal | Perm Abandoned | NM | Rio Arriba | 13 | 029N | 006W |      | Hilcorp Energy Company |
| 3003924668 | San Juan 29-6 Unit 226       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 14 | 029N | 014W | SWNE | Hilcorp Energy Company |
| 3003924669 | San Juan 29-6 Unit 227       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 14 | 029N | 014W | SESW | Hilcorp Energy Company |
| 3003924683 | San Juan 29-6 Unit 228 (POW) | Basin Fruitland Coal | Perm Abandoned | NM | Rio Arriba | 15 | 029N | 006W |      | Hilcorp Energy Company |
| 3003924684 | San Juan 29-6 Unit 229       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 35 | 029N | 035W | SESW | Hilcorp Energy Company |
| 3003924609 | San Juan 29-6 Unit 230       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 35 | 029N | 035W | NENE | Hilcorp Energy Company |
| 3003924610 | San Juan 29-6 Unit 231       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 36 | 029N | 036W | NWNE | Hilcorp Energy Company |
| 3003924728 | San Juan 29-6 Unit 233       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 26 | 029N | 026W | SESW | Hilcorp Energy Company |
| 3003924900 | San Juan 29-6 Unit 234       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 34 | 029N | 034W | SESW | Hilcorp Energy Company |
| 3003924823 | San Juan 29-6 Unit 235       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 34 | 029N | 034W | NENE | Hilcorp Energy Company |
| 3003924729 | San Juan 29-6 Unit 236       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 18 | 029N | 006W | NESW | Hilcorp Energy Company |
| 3003927534 | San Juan 29-6 Unit 236A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 18 | 029N | 006W | NENW | Hilcorp Energy Company |
| 3003924804 | San Juan 29-6 Unit 237       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 1  | 029N | 006W | NWNE | Hilcorp Energy Company |
| 3003927532 | San Juan 29-6 Unit 237A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 1  | 029N | 006W | SWSE | Hilcorp Energy Company |
| 3003924805 | San Juan 29-6 Unit 238       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 1  | 029N | 006W | NWSW | Hilcorp Energy Company |
| 3003927489 | San Juan 29-6 Unit 238A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 1  | 029N | 006W | NENW | Hilcorp Energy Company |
| 3003924705 | San Juan 29-6 Unit 239       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 2  | 029N | 006W | NWNE | Hilcorp Energy Company |
| 3003927543 | San Juan 29-6 Unit 239A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 2  | 029N | 006W | SESE | Hilcorp Energy Company |
| 3003924932 | San Juan 29-6 Unit 240       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 18 | 029N | 006W | SENE | Hilcorp Energy Company |
| 3003927541 | San Juan 29-6 Unit 240A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 18 | 029N | 006W | NESE | Hilcorp Energy Company |
| 3003924933 | San Juan 29-6 Unit 241       | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 19 | 029N | 006W | NENE | Hilcorp Energy Company |
| 3003927870 | San Juan 29-6 Unit 241A      | Basin Fruitland Coal | Flowing        | NM | Rio Arriba | 19 | 029N | 006W | NWSE | Hilcorp Energy Company |

|            |                              |                            |                |    |            |    |      |      |      |                        |
|------------|------------------------------|----------------------------|----------------|----|------------|----|------|------|------|------------------------|
| 3003924730 | San Juan 29-6 Unit 242       | Basin Fruitland Coal       | Flowing        | NM | Rio Arriba | 19 | 029N | 006W | NESW | Hilcorp Energy Company |
| 3003927561 | San Juan 29-6 Unit 242A      | Basin Fruitland Coal       | Flowing        | NM | Rio Arriba | 19 | 029N | 006W | NENW | Hilcorp Energy Company |
| 3003924943 | San Juan 29-6 Unit 243       | Basin Fruitland Coal       | Flowing        | NM | Rio Arriba | 31 | 029N | 031W | SENE | Hilcorp Energy Company |
| 3003924978 | San Juan 29-6 Unit 244 (POW) | Basin Fruitland Coal       | Perm Abandoned | NM | Rio Arriba | 31 | 029N | 006W |      | Hilcorp Energy Company |
| 3003924910 | San Juan 29-6 Unit 245       | Basin Fruitland Coal       | Flowing        | NM | Rio Arriba | 8  | 029N | 008W | NWNE | Hilcorp Energy Company |
| 3003927508 | San Juan 29-6 Unit 245A      | Basin Fruitland Coal       | Flowing        | NM | Rio Arriba | 8  | 029N | 008W | NWNW | Hilcorp Energy Company |
| 3003924824 | San Juan 29-6 Unit 246       | Basin Fruitland Coal       | Perm Abandoned | NM | Rio Arriba | 8  | 029N | 006W |      | Hilcorp Energy Company |
| 3003925414 | San Juan 29-6 Unit 247R      | Basin Fruitland Coal       | Perm Abandoned | NM | Rio Arriba | 10 | 029N | 006W |      | Hilcorp Energy Company |
| 3003925161 | San Juan 29-6 Unit 248 (POW) | Basin Fruitland Coal       | Perm Abandoned | NM | Rio Arriba | 15 | 029N | 006W |      | Hilcorp Energy Company |
| 3003925201 | San Juan 29-6 Unit 249       | Basin Fruitland Coal       | Flowing        | NM | Rio Arriba | 22 | 029N | 022W | NWNE | Hilcorp Energy Company |
| 3003925169 | San Juan 29-6 Unit 251       | Basin Fruitland Coal       | Flowing        | NM | Rio Arriba | 23 | 029N | 023W | NESW | Hilcorp Energy Company |
| 3003925456 | San Juan 29-6 Unit 257R      | Basin Fruitland Coal       | Flowing        | NM | Rio Arriba | 9  | 029N | 006W | NWNW | Hilcorp Energy Company |
| 3003924766 | San Juan 29-6 Unit 258       | Basin Fruitland Coal       | Flowing        | NM | Rio Arriba | 16 | 029N | 016W | SESW | Hilcorp Energy Company |
| 3003924763 | San Juan 29-6 Unit 259       | Basin Fruitland Coal       | Flowing        | NM | Rio Arriba | 9  | 029N | 006W | NWNE | Hilcorp Energy Company |
| 3003924767 | San Juan 29-6 Unit 260       | Basin Fruitland Coal       | Flowing        | NM | Rio Arriba | 16 | 029N | 016W | SWNE | Hilcorp Energy Company |
| 3003925090 | San Juan 29-6 Unit 262       | Basin Fruitland Coal       | Flowing        | NM | Rio Arriba | 21 | 029N | 021W | NENE | Hilcorp Energy Company |
| 3003925188 | San Juan 29-6 Unit 263       | Basin Fruitland Coal       | Flowing        | NM | Rio Arriba | 22 | 029N | 022W | NWSW | Hilcorp Energy Company |
| 3003925535 | San Juan 29-6 Unit 264       | Basin Fruitland Coal       | Flowing        | NM | Rio Arriba | 27 | 029N | 027W | NENE | Hilcorp Energy Company |
| 3003921226 | San Juan 29-6 Unit 55A       | Blanco Mesaverde           | Perm Abandoned | NM | Rio Arriba | 18 | 029N | 006W |      | Hilcorp Energy Company |
| 3003908076 | San Juan 29-6 Unit NP 096    | Basin Dakota               | Perm Abandoned | NM | Rio Arriba | 2  | 029N | 006W |      | Hilcorp Energy Company |
| 3003924807 | San Juan 29-6 Unit SWD 301   | Swd;Morrison Bluff Entrada | Disposal       | NM | Rio Arriba | 2  | 029N | 006W |      | Hilcorp Energy Company |



**San Juan 29-6 Unit  
Rio Arriba County, NM**



San Juan 29-6 Unit



Oil and Gas Well

RIO ARRIBA

0 0.3 0.6 1.2 1.8 2.4 Miles