



Post Office Box 61229
Houston, Texas 77208-1229

1111 Travis Street
Houston, Texas 77002

Phone: (832) 839-4601
ccreekmore@hilcorp.com

March 1, 2019

R-256

Bureau of Land Management
Farmington Resource Area
6251 College Blvd., Suite A
Farmington, NM 87402

Commissioner of Public Lands
State of New Mexico
P. O. Box 1148
Santa Fe, NM 87501-1148

Oil Conservation Division
State of New Mexico
1220 S. Saint Francis Drive
Santa Fe, NM 87505

**2019 PLAN OF DEVELOPMENT
FOR THE SAN JUAN 31-6 UNIT
NO. 14-08-001-464
RIO ARriba COUNTY, NEW MEXICO**

Pursuant to Section 10 of the San Juan 31-6 Unit Agreement, Hilcorp Energy Company ("Hilcorp"), as Unit Operator, hereby submits the proposed 2019 Plan of Development and Operations ("POD").

I. PERIOD

This plan will be effective from April 1, 2019 through March 31, 2020. The 2020 Plan will be submitted on or before March 1, 2020.

II. 2018 PLAN REVIEW OF OPERATIONS

A. Production History: During 2018, cumulative production from the San Juan 31-6 Unit Unit was 6.7 BCF gas; 0 MBO oil; and 98 MBW produced water. Refer to Exhibit A attached for a listing of all wells in the San Juan 31-6 Unit.

B. Participating Areas: The Participating Areas currently established in the San Juan 31-6 Unit are as follows:

FORMATION	EXPANSION	EFFECTIVE DATE
DAKOTA	016	01-OCT-07
FRUITLAND COAL	016	1-FEB-01
MESAVERDE	022	01-SEP-04

C. Drilling Program: The 2018 POD, as approved, provided for no drilling activity. No additional drilling projects were undertaken by Hilcorp during this period.

D. Workovers/Recompletion Program: During 2018, Hilcorp undertook and completed the

following projects:

Well Name	API	Sec.	Twp	Rng	Formation	Type
SAN JUAN 31-6 UNIT 201A	3003927468	1	030N	006W	FRUITLAND COAL	PUMP/TUBING REPAIR
SAN JUAN 31-6 UNIT 213	3003924531	5	030N	006W	FRUITLAND COAL	PUMP/TUBING REPAIR
SAN JUAN 31-6 UNIT 223	3003924638	32	031N	006W	FRUITLAND COAL	PUMP/TUBING REPAIR
SAN JUAN 31-6 UNIT 229A	3003927400	28	031N	006W	FRUITLAND COAL	PUMP/TUBING REPAIR
SAN JUAN 31-6 UNIT 27M	3003930320	29	031N	006W	DAKOTA/ME SAVERDE	TUBING REPAIR

E. Facility Program: The 2018 POD, as approved, provided for no additional facilities. No additional facility projects were undertaken by Hilcorp during this period.

F. Plugging & Abandonment Program: The 2018 POD, as approved, provided for no planned P&A activity. No additional projects were undertaken by Hilcorp during this period.

III. 2019 PLAN OF DEVELOPMENT AND OPERATIONS

A summary of key activities planned for 2019 includes:

A. Drilling Program: Hilcorp does not anticipate drilling any new wells in the San Juan Unit during 2019. However, new drill opportunities will be evaluated and executed as they arise.

B. Workovers/Recompletion Program: Hilcorp anticipates at least five (5) recompletion projects in the Unit during 2019, summarized in the table below. Additional workovers, rate adds and optimization projects will be evaluated and executed as they arise.

Well Name	API	Sec.	Twp	Rng	Formation	Type
SAN JUAN 31-6 UNIT 30	3003921807	35	031N	006W	PICTURED CLIFFS	RECOMPLETE/COMMINGLE
SAN JUAN 31-6 UNIT 36	3003922488	27	031N	006W	PICTURED CLIFFS	RECOMPLETE/COMMINGLE
San Juan 31-6 Unit 39	3003923149	28	031N	006W	MESAVERDE	RECOMPLETE/COMMINGLE
SAN JUAN 31-6 UNIT 49	3003923158	05	030N	006W	MESAVERDE	RECOMPLETE/COMMINGLE
SAN JUAN 31-6 UNIT 9	3003907949	27	031N	006W	PICTURED CLIFFS	RECOMPLETE/COMMINGLE

C. Facility Program: Throughout 2019, Hilcorp will conduct routine repairs and replacement of facilities required to maintain and increase field production, including construction of additional gas lift lines and/or gas flow lines, expansion of production facilities (including electrical and piping upgrades), and construction of additional water disposal, injection or processing equipment.

D. Plugging & Abandonment Program: Hilcorp does not anticipate plugging/abandoning any wells in the Unit at this time. Hilcorp will evaluate and implement additional P&A projects as they arise.

In accordance to Section 10 of the Unit Agreement, please provide your approvals by executing and returning a copy of this letter to the undersigned.

Please contact me at (832) 839-4601 if there are any questions regarding this letter.

Sincerely,
HILCORP ENERGY COMPANY



Chuck Creekmore,
Division Landman

cc: Working Interest Owners

*BP AMERICA PRODUCTION COMPANY
ENDURING RESOURCES IV LLC
HILCORP SAN JUAN, LP
LOGOS RESOURCES II LLC*



San Juan 31-6 Unit Exhibit "A"

API #	WELL NAME	POOL/FORMATION	STATUS	ST	COUNTY	SEC	TWP	RGE	QTR	OPERATOR
3003907921	San Juan 31-6 Unit 003	Blanco Mesaverde	Perm Abandoned	NM	Rio Arriba	6	030N	006W		Hilcorp Energy Company
3003922757	San Juan 31-6 Unit 003A	Blanco-Mesaverde	Flowing	NM	Rio Arriba	6	030N	0006W	SWSE	Hilcorp Energy Company
3003929736	San Juan 31-6 Unit 003M	Basin Dakota	Flowing	NM	Rio Arriba	6	030N	0006W	SWSE	Hilcorp Energy Company
3003929736	San Juan 31-6 Unit 003M	Blanco-Mesaverde	Flowing	NM	Rio Arriba	6	030N	0006W	SWSE	Hilcorp Energy Company
3003926077	San Juan 31-6 Unit 003R	Basin Dakota	Flowing	NM	Rio Arriba	6	030N	0006W	SWNE	Hilcorp Energy Company
3003926077	San Juan 31-6 Unit 003R	Blanco-Mesaverde	Flowing	NM	Rio Arriba	6	030N	0006W	SWNE	Hilcorp Energy Company
3003926760	San Juan 31-6 Unit 004M	Basin Dakota	Flowing	NM	Rio Arriba	4	030N	0006W	NWSE	Hilcorp Energy Company
3003926760	San Juan 31-6 Unit 004M	Blanco-Mesaverde	Flowing	NM	Rio Arriba	4	030N	0006W	NWSE	Hilcorp Energy Company
3003930264	San Juan 31-6 Unit 004N	Basin Dakota	Flowing	NM	Rio Arriba	4	030N	0006W	SENE	Hilcorp Energy Company
3003930264	San Juan 31-6 Unit 004N	Blanco-Mesaverde	Flowing	NM	Rio Arriba	4	030N	0006W	SENE	Hilcorp Energy Company
3003930319	San Juan 31-6 Unit 004P	Basin Dakota	Flowing	NM	Rio Arriba	4	030N	0006W	SWSE	Hilcorp Energy Company
3003930319	San Juan 31-6 Unit 004P	Blanco-Mesaverde	Flowing	NM	Rio Arriba	4	030N	0006W	SWSE	Hilcorp Energy Company
3003907934	San Juan 31-6 Unit 005	Blanco Mesaverde	Perm Abandoned	NM	Rio Arriba	31	031N	006W		Hilcorp Energy Company
3003922763	San Juan 31-6 Unit 005A	Blanco-Mesaverde	Flowing	NM	Rio Arriba	31	031N	0006W	SWNW	Hilcorp Energy Company
3003907914	San Juan 31-6 Unit 006	Blanco-Mesaverde	Flowing	NM	Rio Arriba	1	030N	007W	NWSW	Hilcorp Energy Company
3003922748	San Juan 31-6 Unit 006A	Blanco-Mesaverde	Flowing	NM	Rio Arriba	1	030N	007W	SWNW	Hilcorp Energy Company
3003930358	San Juan 31-6 Unit 006F	Basin Dakota	Flowing	NM	Rio Arriba	1	030N	007W	SWNW	Hilcorp Energy Company
3003930358	San Juan 31-6 Unit 006F	Blanco-Mesaverde	Flowing	NM	Rio Arriba	1	030N	007W	SWNW	Hilcorp Energy Company
3003926769	San Juan 31-6 Unit 006M	Basin Dakota	Flowing	NM	Rio Arriba	1	030N	007W	NESW	Hilcorp Energy Company
3003926769	San Juan 31-6 Unit 006M	Blanco-Mesaverde	Flowing	NM	Rio Arriba	1	030N	007W	NESW	Hilcorp Energy Company
3003907917	San Juan 31-6 Unit 007	Blanco Mesaverde	Perm Abandoned	NM	Rio Arriba	1	030N	007W		Hilcorp Energy Company
3003922749	San Juan 31-6 Unit 007A	Blanco-Mesaverde	Flowing	NM	Rio Arriba	1	030N	007W	SWSE	Hilcorp Energy Company
3003929621	San Juan 31-6 Unit 007F	Basin Dakota	Flowing	NM	Rio Arriba	1	030N	007W	SESE	Hilcorp Energy Company
3003929621	San Juan 31-6 Unit 007F	Blanco-Mesaverde	Flowing	NM	Rio Arriba	1	030N	007W	SESE	Hilcorp Energy Company
3003930324	San Juan 31-6 Unit 007M	Basin Dakota	Flowing	NM	Rio Arriba	1	030N	007W	SWNE	Hilcorp Energy Company
3003930324	San Juan 31-6 Unit 007M	Blanco-Mesaverde	Flowing	NM	Rio Arriba	1	030N	007W	SWNE	Hilcorp Energy Company
3003907915	San Juan 31-6 Unit 008	Blanco-Mesaverde	Flowing	NM	Rio Arriba	6	030N	0006W	NWSW	Hilcorp Energy Company
3003923020	San Juan 31-6 Unit 008A	Blanco-Mesaverde	Flowing	NM	Rio Arriba	6	030N	0006W	NENW	Hilcorp Energy Company
3003926481	San Juan 31-6 Unit 008M	Basin Dakota	Flowing	NM	Rio Arriba	6	030N	0006W	SWSW	Hilcorp Energy Company
3003926481	San Juan 31-6 Unit 008M	Blanco-Mesaverde	Flowing	NM	Rio Arriba	6	030N	0006W	SWSW	Hilcorp Energy Company
3003930311	San Juan 31-6 Unit 008N	Basin Dakota	Flowing	NM	Rio Arriba	6	030N	0006W	NWSW	Hilcorp Energy Company
3003930311	San Juan 31-6 Unit 008N	Blanco-Mesaverde	Flowing	NM	Rio Arriba	6	030N	0006W	NWSW	Hilcorp Energy Company
3003907949	San Juan 31-6 Unit 009	Blanco-Mesaverde	Flowing	NM	Rio Arriba	27	031N	0006W	NENE	Hilcorp Energy Company
3003907929	San Juan 31-6 Unit 010	Blanco Mesaverde	Perm Abandoned	NM	Rio Arriba	32	031N	006W		Hilcorp Energy Company
3003907937	San Juan 31-6 Unit 011	Blanco-Mesaverde	Flowing	NM	Rio Arriba	31	031N	0006W	NENE	Hilcorp Energy Company
3003907905	San Juan 31-6 Unit 012	Blanco-Mesaverde	Flowing	NM	Rio Arriba	2	030N	0006W	SESW	Hilcorp Energy Company
3003907912	San Juan 31-6 Unit 013	Blanco-Mesaverde	Flowing	NM	Rio Arriba	4	030N	0006W	NWSW	Hilcorp Energy Company
3003929643	San Juan 31-6 Unit 013G	Basin Dakota	Flowing	NM	Rio Arriba	4	030N	0006W	SWNW	Hilcorp Energy Company
3003929643	San Juan 31-6 Unit 013G	Blanco-Mesaverde	Flowing	NM	Rio Arriba	4	030N	0006W	SWNW	Hilcorp Energy Company
3003929652	San Juan 31-6 Unit 013H	Blanco-Mesaverde	Flowing	NM	Rio Arriba	4	030N	0006W	SWSW	Hilcorp Energy Company
3003929905	San Juan 31-6 Unit 013M	Basin Dakota	Flowing	NM	Rio Arriba	4	030N	0006W	NWNW	Hilcorp Energy Company
3003929905	San Juan 31-6 Unit 013M	Blanco-Mesaverde	Flowing	NM	Rio Arriba	4	030N	0006W	NWNW	Hilcorp Energy Company
3003907907	San Juan 31-6 Unit 014	Blanco-Mesaverde	Flowing	NM	Rio Arriba	5	030N	0006W	SWSW	Hilcorp Energy Company
3003982388	San Juan 31-6 Unit 015	Blanco Mesaverde	Perm Abandoned	NM	Rio Arriba	2	030N	006W		Hilcorp Energy Company
3003907928	San Juan 31-6 Unit 016	Basin Dakota	Perm Abandoned	NM	Rio Arriba	33	031N	006W		Hilcorp Energy Company
3003907928	San Juan 31-6 Unit 016	Blanco Mesaverde	Perm Abandoned	NM	Rio Arriba	33	031N	006W		Hilcorp Energy Company
3003929904	San Juan 31-6 Unit 016F	Basin Dakota	Flowing	NM	Rio Arriba	33	031N	0006W	SWSW	Hilcorp Energy Company
3003929904	San Juan 31-6 Unit 016F	Blanco-Mesaverde	Flowing	NM	Rio Arriba	33	031N	0006W	SWSW	Hilcorp Energy Company
3003926071	San Juan 31-6 Unit 016M	Basin Dakota	Flowing	NM	Rio Arriba	33	031N	0006W	NENW	Hilcorp Energy Company
3003926071	San Juan 31-6 Unit 016M	Blanco-Mesaverde	Flowing	NM	Rio Arriba	33	031N	0006W	NENW	Hilcorp Energy Company
30039300668	San Juan 31-6 Unit 016N	Basin Dakota	Flowing	NM	Rio Arriba	32	031N	0006W	NENE	Hilcorp Energy Company
30039300668	San Juan 31-6 Unit 016N	Blanco-Mesaverde	Flowing	NM	Rio Arriba	32	031N	0006W	NENE	Hilcorp Energy Company
3003907908	San Juan 31-6 Unit 017	Blanco-Mesaverde	Flowing	NM	Rio Arriba	1	030N	0006W	SESW	Hilcorp Energy Company
3003982389	San Juan 31-6 Unit 018	Blanco-Mesaverde	Flowing	NM	Rio Arriba	3	030N	0006W	NESW	Hilcorp Energy Company

3003929649	San Juan 31-6 Unit 018G	Basin Dakota	Flowing	NM	Rio Arriba	3	030N	0006W	SWNW	Hilcorp Energy Company
3003929649	San Juan 31-6 Unit 018G	Blanco-Mesaverde	Flowing	NM	Rio Arriba	3	030N	0006W	SWNW	Hilcorp Energy Company
3003930559	San Juan 31-6 Unit 018N	Basin Dakota	Flowing	NM	Rio Arriba	3	030N	0006W	SENE	Hilcorp Energy Company
3003930559	San Juan 31-6 Unit 018N	Blanco-Mesaverde	Flowing	NM	Rio Arriba	3	030N	0006W	SENE	Hilcorp Energy Company
3003907938	San Juan 31-6 Unit 019	Blanco-Mesaverde	Flowing	NM	Rio Arriba	32	031N	0006W	NENE	Hilcorp Energy Company
3003907924	San Juan 31-6 Unit 020	Blanco-Mesaverde	Flowing	NM	Rio Arriba	3	030N	0006W	NWNE	Hilcorp Energy Company
3003929849	San Juan 31-6 Unit 020G	Basin Dakota	Flowing	NM	Rio Arriba	3	030N	0006W	SESE	Hilcorp Energy Company
3003929849	San Juan 31-6 Unit 020G	Blanco-Mesaverde	Flowing	NM	Rio Arriba	3	030N	0006W	SESE	Hilcorp Energy Company
3003907916	San Juan 31-6 Unit 022	Blanco-Mesaverde	Flowing	NM	Rio Arriba	5	030N	0006W	SWNE	Hilcorp Energy Company
3003982390	San Juan 31-6 Unit 023	Blanco-Mesaverde	Flowing	NM	Rio Arriba	34	031N	0006W	SWNE	Hilcorp Energy Company
3003920779	San Juan 31-6 Unit 024	Basin Dakota	Flowing	NM	Rio Arriba					Hilcorp Energy Company
3003920779	San Juan 31-6 Unit 024	Dakota	Perm Abandoned	NM	Rio Arriba	27	031N	006W		Hilcorp Energy Company
3003925279	San Juan 31-6 Unit 024E	Dakota	Perm Abandoned	NM	Rio Arriba	27	031N	006W		Hilcorp Energy Company
3003930424	San Juan 31-6 Unit 024F	Basin Dakota	Perm Abandoned	NM	Rio Arriba	27	031N	006W		Hilcorp Energy Company
3003923169	San Juan 31-6 Unit 025	Basin Dakota	Flowing	NM	Rio Arriba	33	031N	0006W	NENE	Hilcorp Energy Company
3003923169	San Juan 31-6 Unit 025	Blanco-Mesaverde	Flowing	NM	Rio Arriba	33	031N	0006W	NENE	Hilcorp Energy Company
3003925282	San Juan 31-6 Unit 025E	Basin Dakota	Flowing	NM	Rio Arriba	33	031N	0006W	NWSE	Hilcorp Energy Company
3003925282	San Juan 31-6 Unit 025E	Blanco-Mesaverde	Flowing	NM	Rio Arriba	33	031N	0006W	NWSE	Hilcorp Energy Company
3003930013	San Juan 31-6 Unit 025M	Basin Dakota	Flowing	NM	Rio Arriba	33	031N	0006W	SENE	Hilcorp Energy Company
3003930013	San Juan 31-6 Unit 025M	Blanco-Mesaverde	Flowing	NM	Rio Arriba	33	031N	0006W	SENE	Hilcorp Energy Company
3003923150	San Juan 31-6 Unit 027	Basin Dakota	Flowing	NM	Rio Arriba	28	031N	0006W	SWSW	Hilcorp Energy Company
3003923150	San Juan 31-6 Unit 027	Blanco-Mesaverde	Flowing	NM	Rio Arriba	28	031N	0006W	SWSW	Hilcorp Energy Company
3003925281	San Juan 31-6 Unit 027E	Basin Dakota	Flowing	NM	Rio Arriba	28	031N	0006W	NENW	Hilcorp Energy Company
3003925281	San Juan 31-6 Unit 027E	Blanco-Mesaverde	Flowing	NM	Rio Arriba	28	031N	0006W	NENW	Hilcorp Energy Company
3003930320	San Juan 31-6 Unit 027M	Blanco-Mesaverde	Flowing	NM	Rio Arriba	29	031N	0006W	SENE	Hilcorp Energy Company
3003930320	San Juan 31-6 Unit 027M	Basin Dakota	Flowing	NM	Rio Arriba	29	031N	0006W	SENE	Hilcorp Energy Company
3003922751	San Juan 31-6 Unit 028	Basin Dakota	Flowing	NM	Rio Arriba	34	031N	0006W	NESW	Hilcorp Energy Company
3003922751	San Juan 31-6 Unit 028	Blanco-Mesaverde	Flowing	NM	Rio Arriba	34	031N	0006W	NESW	Hilcorp Energy Company
3003925128	San Juan 31-6 Unit 028E	Basin Dakota	Flowing	NM	Rio Arriba	34	031N	0006W	NWSE	Hilcorp Energy Company
3003925128	San Juan 31-6 Unit 028E	Blanco-Mesaverde	Flowing	NM	Rio Arriba	34	031N	0006W	NWSE	Hilcorp Energy Company
3003921496	San Juan 31-6 Unit 029	Blanco-Mesaverde	Flowing	NM	Rio Arriba	36	031N	0006W	NWNE	Hilcorp Energy Company
3003921807	San Juan 31-6 Unit 030	Blanco-Mesaverde	Temp Abandoned	NM	Rio Arriba	35	031N	006W		Hilcorp Energy Company
3003922110	San Juan 31-6 Unit 031	Basin Dakota	Flowing	NM	Rio Arriba	35	031N	0006W	SESE	Hilcorp Energy Company
3003922110	San Juan 31-6 Unit 031	Blanco-Mesaverde	Flowing	NM	Rio Arriba	35	031N	0006W	SESE	Hilcorp Energy Company
3003925117	San Juan 31-6 Unit 031E	Basin Dakota	Flowing	NM	Rio Arriba	35	031N	0006W	SWSW	Hilcorp Energy Company
3003925117	San Juan 31-6 Unit 031E	Blanco-Mesaverde	Flowing	NM	Rio Arriba	35	031N	0006W	SWSW	Hilcorp Energy Company
3003929637	San Juan 31-6 Unit 031F	Basin Dakota	Flowing	NM	Rio Arriba	35	031N	0006W	NESW	Hilcorp Energy Company
3003929637	San Juan 31-6 Unit 031F	Blanco-Mesaverde	Flowing	NM	Rio Arriba	35	031N	0006W	NESW	Hilcorp Energy Company
3003930357	San Juan 31-6 Unit 031P	Basin Dakota	Flowing	NM	Rio Arriba	35	031N	0006W	SESE	Hilcorp Energy Company
3003930357	San Juan 31-6 Unit 031P	Blanco-Mesaverde	Flowing	NM	Rio Arriba	35	031N	0006W	SESE	Hilcorp Energy Company
3003922059	San Juan 31-6 Unit 032	Blanco-Mesaverde	Flowing	NM	Rio Arriba	36	031N	0006W	NESW	Hilcorp Energy Company
3003922108	San Juan 31-6 Unit 033	Basin Dakota	Flowing	NM	Rio Arriba	34	031N	0006W	SWNE	Hilcorp Energy Company
3003925299	San Juan 31-6 Unit 033E	Basin Dakota	Flowing	NM	Rio Arriba	34	031N	0006W	NWNW	Hilcorp Energy Company
3003925299	San Juan 31-6 Unit 033E	Blanco-Mesaverde	Flowing	NM	Rio Arriba	34	031N	0006W	NWNW	Hilcorp Energy Company
3003922109	San Juan 31-6 Unit 035	Basin Dakota	Flowing	NM	Rio Arriba	35	031N	0006W	NENE	Hilcorp Energy Company
3003925289	San Juan 31-6 Unit 035E	Basin Dakota	Flowing	NM	Rio Arriba	35	031N	0006W	NWNW	Hilcorp Energy Company
3003925289	San Juan 31-6 Unit 035E	Blanco-Mesaverde	Flowing	NM	Rio Arriba	35	031N	0006W	NWNW	Hilcorp Energy Company
3003929636	San Juan 31-6 Unit 035G	Basin Dakota	Flowing	NM	Rio Arriba	35	031N	0006W	SENE	Hilcorp Energy Company
3003929636	San Juan 31-6 Unit 035G	Blanco-Mesaverde	Flowing	NM	Rio Arriba	35	031N	0006W	SENE	Hilcorp Energy Company
3003922488	San Juan 31-6 Unit 036	Basin Dakota	Flowing	NM	Rio Arriba	27	031N	0006W	NENE	Hilcorp Energy Company
3003925136	San Juan 31-6 Unit 036E	Blanco-Mesaverde	Flowing	NM	Rio Arriba	27	031N	0006W	NESE	Hilcorp Energy Company
3003925136	San Juan 31-6 Unit 036E	Rosa-Pictured Cliffs	Flowing	NM	Rio Arriba	27	031N	0006W	NESE	Hilcorp Energy Company
3003925136	San Juan 31-6 Unit 036E	Basin Dakota	Flowing	NM	Rio Arriba	27	031N	0006W	NESE	Hilcorp Energy Company
3003922305	San Juan 31-6 Unit 037	Basin Dakota	Flowing	NM	Rio Arriba	36	031N	0006W	SWSE	Hilcorp Energy Company
3003922305	San Juan 31-6 Unit 037	Blanco-Mesaverde	Flowing	NM	Rio Arriba	36	031N	0006W	SWSE	Hilcorp Energy Company
3003929798	San Juan 31-6 Unit 037F	Basin Dakota	Flowing	NM	Rio Arriba	36	031N	0006W	NWSE	Hilcorp Energy Company
3003929798	San Juan 31-6 Unit 037F	Blanco-Mesaverde	Flowing	NM	Rio Arriba	36	031N	0006W	NWSE	Hilcorp Energy Company
3003926434	San Juan 31-6 Unit 037M	Basin Dakota	Flowing	NM	Rio Arriba	36	031N	0006W	SWSW	Hilcorp Energy Company
3003926434	San Juan 31-6 Unit 037M	Blanco-Mesaverde	Flowing	NM	Rio Arriba	36	031N	0006W	SWSW	Hilcorp Energy Company

3003923120	San Juan 31-6 Unit 048	Blanco-Mesaverde	Flowing	NM	Rio Arriba	2	030N	0006W	SESE	Hilcorp Energy Company
3003929598	San Juan 31-6 Unit 048F	Blanco-Mesaverde	Flowing	NM	Rio Arriba	2	030N	0006W	NWSE	Hilcorp Energy Company
3003926464	San Juan 31-6 Unit 048M	Basin Dakota	Flowing	NM	Rio Arriba	2	030N	0006W	NWSW	Hilcorp Energy Company
3003926464	San Juan 31-6 Unit 048M	Blanco-Mesaverde	Flowing	NM	Rio Arriba	2	030N	0006W	NWSW	Hilcorp Energy Company
3003923158	San Juan 31-6 Unit 049	Basin Dakota	Flowing	NM	Rio Arriba	5	030N	0006W	SENE	Hilcorp Energy Company
3003929903	San Juan 31-6 Unit 049F	Basin Dakota	Flowing	NM	Rio Arriba	5	030N	0006W	NENE	Hilcorp Energy Company
3003929903	San Juan 31-6 Unit 049F	Blanco-Mesaverde	Flowing	NM	Rio Arriba	5	030N	0006W	NENE	Hilcorp Energy Company
3003929668	San Juan 31-6 Unit 049G	Basin Dakota	Flowing	NM	Rio Arriba	5	030N	0006W	NWSE	Hilcorp Energy Company
3003929668	San Juan 31-6 Unit 049G	Blanco-Mesaverde	Flowing	NM	Rio Arriba	5	030N	0006W	NWSE	Hilcorp Energy Company
3003930476	San Juan 31-6 Unit 049P	Basin Dakota	Flowing	NM	Rio Arriba	5	030N	0006W	NESE	Hilcorp Energy Company
3003930476	San Juan 31-6 Unit 049P	Blanco-Mesaverde	Flowing	NM	Rio Arriba	5	030N	0006W	NESE	Hilcorp Energy Company
3003923448	San Juan 31-6 Unit 050	Basin Dakota	Flowing	NM	Rio Arriba	31	031N	0006W	NWSW	Hilcorp Energy Company
3003923448	San Juan 31-6 Unit 050	Blanco-Mesaverde	Flowing	NM	Rio Arriba	31	031N	0006W	NWSW	Hilcorp Energy Company
3003930117	San Juan 31-6 Unit 050M	Basin Dakota	Flowing	NM	Rio Arriba	31	031N	0006W	SENE	Hilcorp Energy Company
3003930117	San Juan 31-6 Unit 050M	Blanco-Mesaverde	Flowing	NM	Rio Arriba	31	031N	0006W	SENE	Hilcorp Energy Company
3003923447	San Juan 31-6 Unit 051	Basin Dakota	Flowing	NM	Rio Arriba	5	030N	0006W	NESW	Hilcorp Energy Company
3003926479	San Juan 31-6 Unit 051M	Blanco-Mesaverde	Flowing	NM	Rio Arriba	5	030N	0006W	NENW	Hilcorp Energy Company
3003923744	San Juan 31-6 Unit 053	Basin Dakota	Flowing	NM	Rio Arriba	1	030N	0006W	NWSE	Hilcorp Energy Company
3003923744	San Juan 31-6 Unit 053	Blanco-Mesaverde	Flowing	NM	Rio Arriba	1	030N	0006W	NWSE	Hilcorp Energy Company
3003930023	San Juan 31-6 Unit 053M	Basin Dakota	Flowing	NM	Rio Arriba	1	030N	0006W	NWSW	Hilcorp Energy Company
3003930023	San Juan 31-6 Unit 053M	Blanco-Mesaverde	Flowing	NM	Rio Arriba	1	030N	0006W	NWSW	Hilcorp Energy Company
3003926932	San Juan 31-6 Unit 054	Basin Mancos	Flowing	NM	Rio Arriba	1	030N	0006W	SENE	Hilcorp Energy Company
3003926932	San Juan 31-6 Unit 054	Blanco-Mesaverde	Flowing	NM	Rio Arriba	1	030N	0006W	SENE	Hilcorp Energy Company
3003924445	San Juan 31-6 Unit 2006	Basin Fruitland Coal	Flowing	NM	Rio Arriba	4	030N	0006W	SESW	Hilcorp Energy Company
3003927472	San Juan 31-6 Unit 2006A	Basin Fruitland Coal	Perm Abandoned	NM	Rio Arriba	4	030N	006W		Hilcorp Energy Company
3003924591	San Juan 31-6 Unit 201	Basin Fruitland Coal	Flowing	NM	Rio Arriba	1	030N	0006W	SWNE	Hilcorp Energy Company
3003927468	San Juan 31-6 Unit 201A	Basin Fruitland Coal	Flowing	NM	Rio Arriba	1	030N	0006W	SWSE	Hilcorp Energy Company
3003924525	San Juan 31-6 Unit 202	Basin Fruitland Coal	Flowing	NM	Rio Arriba	1	030N	0006W	NESW	Hilcorp Energy Company
3003927467	San Juan 31-6 Unit 202A	Basin Fruitland Coal	Flowing	NM	Rio Arriba	1	030N	0006W	NWNW	Hilcorp Energy Company
3003924433	San Juan 31-6 Unit 203	Basin Fruitland Coal	Flowing	NM	Rio Arriba	3	030N	0006W	NENE	Hilcorp Energy Company
3003927469	San Juan 31-6 Unit 203A	Basin Fruitland Coal	Flowing	NM	Rio Arriba	3	030N	0006W	SESE	Hilcorp Energy Company
3003924437	San Juan 31-6 Unit 204	Basin Fruitland Coal	Flowing	NM	Rio Arriba	3	030N	0006W	SESW	Hilcorp Energy Company
3003927470	San Juan 31-6 Unit 204A	Basin Fruitland Coal	Flowing	NM	Rio Arriba	3	030N	0006W	NWNW	Hilcorp Energy Company
3003924486	San Juan 31-6 Unit 205	Basin Fruitland Coal	Monitoring Well	NM	Rio Arriba	4	030N	006W	SWNE	Hilcorp Energy Company
3003927471	San Juan 31-6 Unit 205A	Basin Fruitland Coal	Flowing	NM	Rio Arriba	4	030N	0006W	SWSE	Hilcorp Energy Company
3003925691	San Juan 31-6 Unit 205R	Basin Fruitland Coal	Flowing	NM	Rio Arriba	4	030N	0006W	SWNE	Hilcorp Energy Company
3003924457	San Juan 31-6 Unit 207	Basin Fruitland Coal	Flowing	NM	Rio Arriba	6	030N	0006W	NWNE	Hilcorp Energy Company
3003924436	San Juan 31-6 Unit 208	Basin Fruitland Coal	Perm Abandoned	NM	Rio Arriba	6	030N	006W		Hilcorp Energy Company
3003924432	San Juan 31-6 Unit 209	Basin Fruitland Coal	Flowing	NM	Rio Arriba	1	030N	007W	NWSW	Hilcorp Energy Company
3003929453	San Juan 31-6 Unit 209A	Basin Fruitland Coal	Flowing	NM	Rio Arriba	1	030N	007W	NWNW	Hilcorp Energy Company
3003924694	San Juan 31-6 Unit 210	Basin Fruitland Coal	Flowing	NM	Rio Arriba	2	030N	0006W	NWNE	Hilcorp Energy Company
3003927481	San Juan 31-6 Unit 210A	Basin Fruitland Coal	Flowing	NM	Rio Arriba	2	030N	0006W	SESE	Hilcorp Energy Company
3003924514	San Juan 31-6 Unit 211	Basin Fruitland Coal	Flowing	NM	Rio Arriba	2	030N	0006W	SESW	Hilcorp Energy Company
3003927478	San Juan 31-6 Unit 211A	Basin Fruitland Coal	Flowing	NM	Rio Arriba	2	030N	0006W	NWNW	Hilcorp Energy Company
3003924686	San Juan 31-6 Unit 212	Basin Fruitland Coal	Flowing	NM	Rio Arriba	5	030N	0006W	SENE	Hilcorp Energy Company
3003927812	San Juan 31-6 Unit 212A	Basin Fruitland Coal	Perm Abandoned	NM	Rio Arriba	5	030N	006W		Hilcorp Energy Company
3003924531	San Juan 31-6 Unit 213	Basin Fruitland Coal	Flowing	NM	Rio Arriba	5	030N	0006W	NESW	Hilcorp Energy Company
3003927807	San Juan 31-6 Unit 213A	Basin Fruitland Coal	Flowing	NM	Rio Arriba	5	030N	0006W	NENW	Hilcorp Energy Company
3003924937	San Juan 31-6 Unit 214	Basin Fruitland Coal	Flowing	NM	Rio Arriba	36	031N	0006W	SWNE	Hilcorp Energy Company
3003927331	San Juan 31-6 Unit 214A	Basin Fruitland Coal	Flowing	NM	Rio Arriba	36	031N	0006W	NESE	Hilcorp Energy Company
3003924639	San Juan 31-6 Unit 215	Basin Fruitland Coal	Flowing	NM	Rio Arriba	36	031N	0006W	NESW	Hilcorp Energy Company
3003927321	San Juan 31-6 Unit 215A	Basin Fruitland Coal	Flowing	NM	Rio Arriba	36	031N	0006W	SWNW	Hilcorp Energy Company
3003925017	San Juan 31-6 Unit 216	Basin Fruitland Coal	Flowing	NM	Rio Arriba	35	031N	0006W	NENE	Hilcorp Energy Company
3003929409	San Juan 31-6 Unit 216A	Basin Fruitland Coal	Flowing	NM	Rio Arriba	2	030N	0006W	NENE	Hilcorp Energy Company
3003924671	San Juan 31-6 Unit 217	Basin Fruitland Coal	Flowing	NM	Rio Arriba	35	031N	0006W	SWSW	Hilcorp Energy Company
3003927335	San Juan 31-6 Unit 217A	Basin Fruitland Coal	Flowing	NM	Rio Arriba	35	031N	0006W	NENW	Hilcorp Energy Company
3003924972	San Juan 31-6 Unit 218	Basin Fruitland Coal	Flowing	NM	Rio Arriba	34	031N	0006W	SENE	Hilcorp Energy Company
3003929422	San Juan 31-6 Unit 218A	Basin Fruitland Coal	Flowing	NM	Rio Arriba	3	030N	0006W	NWNE	Hilcorp Energy Company
3003924672	San Juan 31-6 Unit 219	Basin Fruitland Coal	Flowing	NM	Rio Arriba	34	031N	0006W	NESW	Hilcorp Energy Company

