

JUN 13 1979

UNITED STATES OIL CONSERVATION DIVISION
DEPARTMENT OF THE INTERIOR SANTA FE
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other Wildcat
well well

2. NAME OF OPERATOR

TransOcean Oil, Inc.

3. ADDRESS OF OPERATOR

77002

1700 First City East, 1111 Fannin, Houston Tx

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE:

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐☐FRACTURE TREAT ☐☐SHOOT OR ACIDIZE ☐☐REPAIR WELL ☐☐PULL OR ALTER CASING ☐☐MULTIPLE COMPLETE ☐☐CHANGE ZONES ☐☐ABANDON* ☐☐

(other) SUBSEQUENT REPORT OF ABANDONMENT

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Set cmt plug at 9700-9500' (100 sx C1 "B" + 3% D-28 RET).
2. Set cmt plug at 8950-8750' (100 sx C1 "B" + 3% D-28 RET).
3. Set cmt plug at 8400-8200' (100 sx C1 "B" + 3% D-28 RET).
4. Set cmt plug at 5500-5200' (225 sx C1 "B" NEAT).
5. Set cmt plug at 700-500' (125 sx C1 "B" NEAT).
6. Set Dry Hole marker w/50 sxs C1 "B" NEAT at surface.
7. Cleaned up surface location.

PLUGS SET NOVEMBER 17/78.

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

C.S. Jones

TITLE Manager

DATE June 8, 1979

Western Drilling Division

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: