

11-1-3100-1
(November 1983)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Budget Bureau No. 1004-1
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO

NM 61418

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
SWEPT ET AL MANGAS
MOUNTAINS FEDERAL

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

WILDCAT

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

NW/4 SW/4 SEC. 21

T3S-R15W

12. COUNTY OR PARISH 13. STATE

CATRON

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. DRY

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

SHELL WESTERN E&P INC.

3. ADDRESS OF OPERATOR

P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

8465' SOUTH & 11,083' EAST OF NW CORNER OF
SEC. 18

(Est) 506' FWL & 2197' FSL SEC. 21

14. XXXXXXXX API NO.

30-003-20016

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

9034' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

TD @ 7808'

NOTE: PLUGGING OPNS NOS. 3 - 6 WILL UTILIZE CLS "H" NEAT CMT.

1. Set a 150' balance plug (using CLs "H" cmt + 0.2% HR-7) 75' below top of ABO & 75' above top of Abo.
2. POH to 4895'. Set balance plug (using CLs "H" cmt + 3% salt) from 4895' - 4795', 50' cmt outside and 50' cmt inside 9-5/8" csg @ 4845'. WOC for 4 hrs & tag plug.
3. POH to 3900'. Set balance plug from 3900' - 3800'.
4. Perf @ 2050'. Sqz cmt behind 9-5/8" csg from 2050' - 1950'. inside 9-5/8" csg from 2050' - 1950'.
5. Perf @ 892'. Set cmt ret @ 792'. Sqz CLs "H" Neat cmt behind 9-5/8" from 892' - 792' & place 100' cmt inside 9-5/8" csg below ret. Set 15 sx cmt on top of ret.
6. Sqz 50' cmt into 13-3/8" X 9-5/8" annulus. Cut off csg 4' below GL. Set 50' balanced plug inside 9-5/8" csg from 50' to surf.

(CONTINUED ON REVERSE SIDE)

18. I hereby certify that the foregoing is true and correct

SIGNED

A. J. FORE

TITLE SUPERVISOR REG. & PERMITS

DATE 12-04-87

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

PETER W. CHESTER

DATE

DEC 8 1987

*See Instructions on Reverse Side

BUREAU OF LAND MANAGEMENT

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any statement or representation as to any matter within its jurisdiction.

7. Weld cap (w/BLM --required info permanently inscribed) on csg.

NOTE: Oral approval to P&A granted 11/24/87 from BLM's Mr. Peter Chester. Obtained approval 11/25/87 from Mr. Ron Henderson of the U.S. Forest Service (Silver City) to omit installation of dry hole marker.