

U. S. LAND OFFICE New Mexico
SERIAL NUMBER 02306
LEASE OR PERMIT TO PROSPECT _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

LOG OF OIL OR GAS WELL

LOCATE WELL CORRECTLY

Company Claude Buckleberry Address 3032 Timberwolf Dr., El Paso, Texas.
Lessor or Tract Federal Field Wildcat State New Mexico
Well No. 1 Sec. 11 T. 2-N R. 16-W Meridian N.M.P.M. County Catron
Location 330 ft. ^{NE} of N Line and 330 ft. ^{NE} of E Line of Sec. 11 Elevation 7105
(Derrick floor relative to sea level)

The information given herewith is a complete and correct record of the well and all work done thereon so far as can be determined from all available records.

Signed

C. Benson Neal, Agent in Farmington, N.M.

Date January, 21-1956

The summary on this page is for the condition of the well at above date.

Commenced drilling ----- **November 17**, 19**56** Finished drilling ----- **December 25**, 19**56**

OIL OR GAS SANDS OR ZONES
(Denote gas by G)

No. 1, from ~~None~~ to _____

No. 2, from _____ to _____

No. 3, from _____ to _____

No. 4, from _____ to _____

No. 5, from _____ to _____

No. 6, from _____ to _____

IMPORTANT WATER SANDS

No. 1, from _____ to _____

No. 2, from _____ to _____

No. 3, from _____ to _____

No. 4, from _____ to _____

CASING RECORD

Size casing	Weight per foot	Threads per inch	Make	Amount	Kind of shoe	Cut and pulled from	Perforated		Purpose
							From—	To—	
8-5/8	24 1/2	8 rd. thd.	J-55	95-53	None				Surface
HISTORY OF CUT OF Casing									

MUDDING AND CEMENTING RECORD

Size casing	Where set	Number sacks of cement	Method used	Mud gravity	Amount of mud used
8-5/8	107-53	50	Balliburton	Mostly water	
Plugged and abandoned: 50 sacks at 2200-2100; 50 sacks at 2150-2000; 30 sacks at 2200-2100; 30 sacks at 1700-1600. 50 sacks at 1200-1050. Total 210 sacks of cement.					

PLUGS AND ADAPTERS

Heaving plug—Material ----- Length ----- Depth set -----
Adapters—Material ----- Size -----

SHOOTING RECORD

Size	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out

TOOLS USED

Rotary tools were used from 0 feet to 5,62 feet, and from _____ feet to _____ feet.

Cable tools were used from _____ feet to _____ feet, and from _____ feet to _____ feet.

DATES

DATES	
Plugged and abandoned	December 25, 1956
Put to producing	December 25, 1956

The production for the first 24 hours was ----- barrels of fluid of which -----% was oil; -----% emulsion; -----% water; and -----% sediment. Gravity, °Bé. -----

If gas well cu. ft. per 24 hours _____ Gallons gasoline per 1,000 cu. ft. of gas _____

Rock pressure, lbs. per sq. in. _____

EMPLOYEES

~~San Juan Drilling Co.~~, Driller _____, Driller _____
_____, Driller _____, Driller _____

FORMATION RECORD

FORMATION RECORD			
FROM—	TO—	TOTAL FEET	FORMATION
	900' 2850' 5642'		Spotted in Mancos Shale Top of Dakota Top of Permian TD-800' in Basement
The above information is the only reliable information we have on formations. A complete set of samples were sent to the School of Mines to determine the correct formations.			
FROM—	TO—	TOTAL FEET	FORMATION

The above information is the only reliable information we have on formations.

A complete set of samples were sent to the School of Mines to determine the correct formations.

