


NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	✓
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	



Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> RECOMPLETION ATTEMPT	7. Unit Agreement Name
2. Name of Operator ODESSA NATURAL CORPORATION	8. Farm or Lease Name ODESSA NATURAL CORP. N S RANCH
3. Address of Operator P. O. Box 3908, Odessa, Texas 79760	9. Well No. 3
4. Location of Well UNIT LETTER M 342 FEET FROM THE West LINE AND 537 FEET FROM THE South LINE, SECTION 24 TOWNSHIP 29N RANGE 19E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) GR 7271' KB 7284'	12. County Colfax

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

AUGUST 1, 1972 TD 5084' PBTD 4900'

- It is intended to cut off the 4-1/2" OD casing at approximately 4500'. Recover the 4-1/2" OD casing and set @ 5 sxs. regular cement plug on the 4-1/2" OD stub.
- It is also intended to cut off the 7" OD casing at its free point and to set a 15 sx regular cement plug on the 7" OD stub.
- The 7" OD casing will be pulled to a depth of approximately 2600' and cemented w/150 sxs for a completion attempt in an unnamed formation @ 2300'. This zone will be perforated and sandwater fractured.

Distribution:

3/NMOCC-Santa Fe, 1/WSRanch, 1/RLH, 1/JH, 1/JJS, 2/LC, 1/WF

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John J. Strojek TITLE MANAGER - PRODUCTION DEPT. DATE 8/1/72

APPROVED BY E. Kapteina TITLE Oil & Gas Inspector DATE 8/3/72

CONDITIONS OF APPROVAL, IF ANY: