Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office		•	
<u>- District I</u> P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO. NA
DISTRICT II P.O. Drawer DD, Artesia, NM \$8210	Santa Fe, New Mexico 87504-2088		5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			STATE FEE STATE No. 6. State Oil & Gas Lease No. NA
SUNDRY NOTICES AND REPORTS ON WELLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name
1. Type of Well; OIL OAS WELL X	OTHER		- Vermejo
2. Name of Operator	##		8. Well No.
Pennzoil Exploration & Production Company 3. Address of Operator			1-16 9. Pool name or Wildcat
P.O. Box 2967, Houston, TX 77252			Wildcat
Unit Letter P: 938 Feet From The South Line and 514 Feet From The East Line			
Section 16	Township 30 N R		NMPM Colfax County
	10. Elevation (Show whether 8027 GR	DF, RKB, RT, GR, etc.)	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	PLUG AND ABANDON X CHANGE PLANS	SUE REMEDIAL WORK COMMENCE DRILLING CASING TEST AND COMMENCE.	SSEQUENT REPORT OF: ALTERING CASING G OPNS. PLUG AND ABANDONMENT EMENT JOB
Fill wellbore with fopen perfs at 1634-3	luid. Tag plug at 17	lO. Set CIBP a	t 1600' which is above the 11 sacks. Set 50' surface
			•
I hereby certify that the information about the true	and complete to the best of my knowledge and	belief.	
SIGNATURE	ellumpun ,	Operations Su	perintendent DATE 3/28/90
TYPEORPRINTHAME L. D. Will	iamson		TELEPHONE NO.505-376-281
(This space for State Use)	10		