JIM SNYDER DRILLING COMPANY 1507 Denver Club Building Denver, Colorado 80202



Well Name, $\frac{2Hc}{hc}$ $\frac{1}{28}$ $\frac{1}{21}$ Location $\frac{2c}{hc}$ $\frac{1}{28}$ $\frac{1}{21}$ $\frac{1}{4}$

PLUGGING REPORT

colfax county cole
Operator MIRLA CILC
This well was filled with Wt mud.
sacks were put at the bottom of surface pipe and
sacks at the top of the surface pipe.
Bottom hole plugs (if any) 25 SMS 6 3324

To my knowledge, no junk was left in the hole.
Signed: Signed:
Toolpusher
JIM SNYDER DRILLING COMPANY
Date <u> </u>

