

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER- <input checked="" type="checkbox"/> Dry hole
Name of Operator Pennzoil Company		
Address of Operator P. O. Box 2967 Houston, Texas 77001 Attn: Kenneth R. Huddleston		
Location of well UNIT LETTER <u>S</u> , <u>2310</u> FEET FROM THE <u>North</u> LINE AND <u>990</u> FEET FROM THE <u>West</u> LINE, SECTION <u>33</u> TOWNSHIP <u>32N</u> RANGE <u>17E</u> N.M.P.M.		

7. Unit Agreement Name
8. Farm or Lease Name Vermejo Ranch
9. Well No. 3
10. Field and Pool, or Wildcat Wildcat
12. County Colfax

15. Elevation (Show whether DF, RT, GR, etc.)  
8524'

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

FORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
PERMANENTLY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	
OTHER <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Drilled to 3992' with air.

2. Logged well

VEREAL PERMISSION TO PLUG WELL AS FOLLOWS WAS RECEIVED FROM MR. ULVOG ON 6-15-81:

1. Set 75 sx "H" + 2% CaCl<sub>2</sub> @ 3771' - 3610' = 161'
  2. Set 75 sx "H" + 2% CaCl<sub>2</sub> @ 310' - 149' = 161'
  3. Set 50 sx "H" + 2% CaCl<sub>2</sub> @ 90' - 0' = 90'
  4. Cut off head and install dry hole marker.
- All work was completed 6-16-81.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Kenneth R. Huddleston

TITLE Sr. V.P. Production

DATE 6-16-81

Carl Ulvog

STATE OF NEW MEXICO 87501

6/23/81