Used 75 sacks of cement. The weather is clear with scattered March 6 cont. clouds and cold.

No drilling. Waited until 11:00 am for cement to cure. March 7, 1984 Hooked up flow line for cuttings. Dozer dug pit for cuttings to blow into. Tried going in hole but bit wouldn't go past 160°. Came out of hole. Ordered a new bit. The dozer left the Koehler area. The weather is clear and warm.

Began drilling at 12:30 am. Drilled from 320' to 390' (70'). March 8, 1984 Stopped and worked on blowout preventer. Using a 6 1/8" Ingersall Rand hammer bit. Continued drilling at 11:00 am Drilled from 390' to 1,300' (910'). Wilson Corp. delivered fuel to rig. Stopped drilling at 7:30 pm. Weather is clear and warm.

Began drilling at 8:35 am. Drilled from 1,300° to 2,320° (1,020° March 9, 1984 Depth of 2,000' reached at 4:15 pm. Expecting 1,000' of drill pipe to be delivered some time tonight. Stopped drilling today at 8:30 pm. Tripped out of hole for bit change and to add other drill pipe. Weather is clear and warm.

No drilling. Waiting for a new bit and additional drill pipe March 10, 1984 to arrive. Drill pipe arrived at 3:30 pm. Drill crew went to Colorado Springs to pick up new bit. 35 joints of 44" drill pipe were unloaded at location. Weather is clear and warm.

Tripped new bit and 30 joints of 412" drill pipe back in hole. March 11, 1984 Began drilling at 11:10 pm and stopped at 11:40 pm. Drilled from 2,320 to 2,380 (60) today. Had to ream hole from 1,600 to 2,320'. Weather is clear and warm.

Began drilling at 9:45 am. Drilled from 2,380' to 3,400' (1,020' March 12, 1984 Slight show of gas in hole this morning in form of vapors coming out of blooey line. Stopped drilling today at 8:05 pm.

Began drilling at 8:45 am. Drilled from 3,400' to 3,675' (275') Entered Dakota Ss at 8:55 am at 3,411' or 3,412'. Some water encountered at 3,605' No oil or gas shows in Dakota Ss. Bottomed hole at 1:00 pm at 3,440 in the Morrison Fm. (Total Depth corrected to 3,675' with float valves, differences in length of new pipe, bit, and hammer) Tripped out of hole. Placed a 7" plug with a valve in the top of the surface casing. Weather is clear and warm.

Valve was opened. Slight gas pressure was built up; approximatel 25 psi. Gave off a 2' lazy flare. No way of telling at present whether gas is coming from the Dakota Ss or a shale or limestone unit above. Truck and trailer with drill pipe had been moved off of location and out of area when drill site was checked at 4:00 pm. Ray Holifield & Assoc. - Dallas, Tx has agreed to pay for logging of well... no idea when this will occur. Drill crew has left for Kentucky. Bob Scoggins left for Shreveport, La. Scoggins called Jack Donaldson to let him know about truck and trailer with drill pipe. Got a call from the sheriff's office saying Donaldson had contacted them.... want to go out to location

March 13, 1984

March 14, 1984