

Submit 3 Copies To Appropriate District
Office
District I -
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-007-20102
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other COALBED METHANE

2. Name of Operator
EL PASO ENERGY RATON, LLC

3. Address of Operator
P.O. BOX 190; RATON, NM 87740

4. Well Location
Unit Letter I : 1920' feet from the SOUTH line and 330' feet from the EAST line
Section 29 Township 32N Range 20E NMPM COFAX County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
8058' (GR)

7. Lease Name or Unit Agreement Name:
VPR 'A'

8. Well No. **24**
9. Pool name or Wildcat
Stubblefield Canyon Raton - Vermejo Gas

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: PERFORATE ADDITIONAL ZONES & STIMULATE ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

5/12/00 Pull rods & tubing. Perforate: 2028' - 2034' & 2019' - 2026'. All 4 spf.

Stimulate: 30000# 20/40 & 100000# 12/20 Sand with 370000 scf N2 70 Quality foam.

5/13/00 Perforate: 1757' - 1761' & 1743' - 1747'. All 4spf.

Stimulate: 20000# 20/40 & 50000# 12/20 Sand with 235000 scf N2 70 Quality foam.

5/15-19/00 Clean out to 2310'. Ran After Frac Log (Patterson). Ran tubing & rods. Return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joel L. Pettit TITLE WELL SITE SUPERVISOR DATE 9/16/00

Type or print name: JOEL L. PETTIT Telephone No.: (505) 445-4620

(This space for State use)

APPROVED BY [Signature] TITLE DISTRICT SUPERVISOR DATE 9/25/00
Conditions of approval, if any: