

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-007-20144
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: VPR D
8. Well No. 11
9. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other Coal Bed Methane	
2. Name of Operator El Paso Energy Raton, LLC	
3. Address of Operator P O Box 190 Raton N.M. 87740	
4. Well Location Unit Letter <u>L</u> : <u>1616</u> feet from the <u>South</u> line and <u>1070</u> feet from the <u>West</u> line Section <u>5</u> Township <u>30N</u> Range <u>18E</u> NMPM Colfax County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 8566' (GR)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: Commingle Raton coals with the Vermejo coals ☒

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. POH with tubing and rods
2. Perforate 1441-43, 1424-26, 1346-49, 1329-34, 1277-79, 1241-43, all 4spf
3. Stimulate perforations with N2 foam frac. (Frac details to be decided.)
4. Perforate 966-69, 962-64, 911-13, all 4spf
5. Stimulate perforations with N2 foam frac. (Frac details to be decided.)
6. Perforate 822-24, 783-86, all 4spf
7. Stimulate perforations with N2 foam frac. (Frac details to be decided.)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Potter TITLE Completion Consultant DATE 12-18-00

Type or print name Mike Potter

Telephone No. 505 445-4185

(This space for State use)

APPROVED BY [Signature] TITLE DISTRICT SUPERVISOR DATE 12/22/00

Conditions of approval, if any: