Submit 3 Copies To Appropriate District	State of New Mexico			Form C-103		
Office	Energy, Minerals and Natural Resources			Revised March 25, 1999		
District I	Energy, manerals an			WELL API NO. 3	30-007-20370	İ
1625 N. French Dr., Hobbs, NM 87240 District II	OIL CONCEDU/	TIONII	MOISION			_
811 South First, Artesia, NM 87210	OIL CONSERVATION DIVISION			5. Indicate Type of	f Lease	
District III	1220 South St Francis			STATE	FEE	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505			6. State Oil & Ga	as Lease No.	
District IV 2040 South Pacheco, Santa Fe, NM 87505						
	ES AND REPORTS ON	WELLS		7. Lease Name or	Unit Agreement Name	:
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A						
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				VPR C		
PROPOSALS.)						
1. Type of Well:						
Oil Well Gas Well Other COALBED METHANE				8. Well No. 9	6	7
2. Name of Operator				8. Well No.	· ·	
EL PASO ENERGY RATON, L.L.C.				9. Pool name or V	Wildcat	
3. Address of Operator P.O. BOX 190 RATON, NM 87740				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		İ
P.O. BOX	90 KATON, NW 07	740				
4. Well Location	feet from the Nor	-th lir	ne and 1974	feet from the We	estline	i
Unit Letter <u>C</u> : 77 Section 30 Township		21E		olfax County		
Section 30 Township	10. Elevation (Show wi	hether DR		tc.)		
		7687° ((GR)		and the second of the second o	
11 Check	Appropriate Box to Inc	licate Na	ture of Notice, R	Report or Other Dat	ia	
NOTICE OF IN	TENTION TO		SUE	SEQUENT RE	PURTUE.	
PERFORM REMEDIAL WORK			REMEDIAL WOR		ALTERING CASING	
PERFORM REMEDIAL WORK	PEOG AND ADAMON	<u>. </u>				
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DE	RILLING OPNS. 🔲	PLUG AND	
TEMPORARIET ABANDON L		_			ABANDONMENT	
PULL OR ALTER CASING MULTIPLE CASING TEST			ליין מאל			
	COMPLETION		CEMENT JOB			
			OTHER:		COMPLETION	
OTHER: 12. Describe proposed or completed operations.	ations (Clearly state all pertiner	nt details, and	l give pertinent dates.	including estimated date of	of starting any proposed work	.)
12. Describe proposed or completed opers SEE RULE 1103. For Multiple Comp	oletions: Attach wellbore diagram	m of propos	ed completion or recon	npilation.		
02-07-03 HES ran cement bond log. TOO	at 36°. 1848' 3 SPF 8 Holes (5' of c	oal)				
HES frac'd 1st stage. Fracture	treatment and 50,440 lbs of 20/	40 Ottawa S	Sand, average pressure	at 3,838 psi, Final ISIP at	t 3,174 psi.	
HES perf'd 2 nd stage: 1803'-						
HES frac'd 2 nd stage: Fracture treatment and 4,010 lbs of 20/40 Ottawa Sand, average pressure at 4,433 psi, Selection.						
HES perf'd 3 rd stage: 1693'- 1695' 3 SPF 5 Holes (3' of coal) HES frac'd 3 rd stage: Fracture treatment and 7,080 lbs of 20/40 Ottawa Sand, average pressure at 4,446 psi, Screen out.						
HES frac'd 4th stage: Fracture treatment and 10,640 lbs of 20/40 Ottawa Sand, average pressure at 4,474 pst, Final 1611 at 4,220 pst.						
HES perf'd 5th stage: 1090' - 1092' 3 SPF 5 Holes (2' of coal)						
HES perf'd 6 th stage: 1043' - 1045' 3 SPF 5 Holes (2 of coar) HES frac'd 6 th stage: Fracture treatment and 21,430 lbs of 20/40 Ottawa Sand, average pressure at 3,426 psi, Final ISIP at 1,044 psi. O4-08-03 Air clean out, installed rods, tubing, and pump. Well is ready to be tested and put on production.						
04-08-03 Air clean out, installed rods, tul	ing, and pump. Well is ready to	be tested at	nd put on production.			
I hereby certify that the information above						
SIGNATURE Shirland		TLEF	Field Adm. Specia	listDATE	04/29/03_	
Type or print name: Shirley	Mitchell Tel	iephone N	lo.: (505) 445-67			
(This space for State use) APPPROVED BY	blum	TITLE_	DISTRICT!	SUPERVISOR	DATE 5/5/0.	3
Conditions of approval, if any:						
Conditions of approves, 2 ap.	1/					