STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

HO. OF COPIES ACCEIVED		
DISTRIBUTION		1
SANTA FE	17	
FILE	10	
U.S.G.S.		
LAND OFFICE		
OPERATOR	1	

OIL CONSERVATION DIVISION P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103 Revised 10-1-78

1 5 1		
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5, State Oil & Gos Lease No.
		L 6331
SUNDRY NOTICES AND REPORTS	ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CELEPEN OR PL USE "APPLICATION FOR PERMIT" (FORM C-101) FOR	SUCA TERMINATION TO THE PARTY ASSOCIATION	
<u> </u>	The state of the s	7. Unit Agreement Name
OIL A GAS WELL OTHER.	MI II	
2. Name of Operator	THE JAN STREET	8. Farm or Lease Name
Dio Dotro Itd		_
Rio Petro., Ltd.	OIL CONSERVATION DIVISION	State
	CANTARE	
4835 LBJ Freeway, Suite 635, Dallas TX 752	34	16
		10. Field and Pool, or Wildcat
UNIT LETTER O 810 FEET FROM THE South	LINE AND 1650 PEET FROM	Wildcat
THE East LINE, SECTION 15 TOWNSHIP 111	AANGE 25E	
15. Eievaner (Show whet	er DF, RT, GR, etc.)	12. County
11111111111111111111111111111111111111		Guadalupe
Check Appropriate Box To Indicate	Nature of Nation Barrer of Oil	
NOTICE OF INTENTION TO:		
NOTICE OF INTENTION TO.	SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK		
		ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING CHANGE PLANS	CASING TEST AND CEMENT JOB	
۲	ОТНЕЯ	
OTHER	7	
17. Describe Proposed or Completed Operations (Clearly state all pertinent	etails, and give pertinent dates, including	estimated date of stanting and a
work) SEE RULE 1103.	ciario, and give periodent dates, including	estimated date of starting any proposed
Spudded well at 12:00 P.M. on December 1, 198	3 Drilled 1/ 3//" hole +	o 361 mp . Dom 361
Spudded well at 12:00 P.M. on December 1, 198 of 13 3/8" 48# casing and cemented with 14 sa	3. Drilled 14 3/4" hole to	o 36' TD. Ran 36'
of 13 3/6 40# Casing and cemented with 14 sa	cks of neat cement from TD	to surface
Drilled 12 1/4" hole to 540 ft. and ran 533'	cks of neat cement from TD of 8 5/8" 23*casing to shu	to surface.
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to	cks of neat cement from TD of 8 5/8" 23*casing to shu O Dull casing but string n	to surface. t off water at 455'.
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to	cks of neat cement from TD of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Roy Joh	to surface. t off water at 455'. arted in first collar
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement.	cks of neat cement from TD of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Rov Joh lug at TD. 25 sack cement	to surface. t off water at 455'. arted in first collar nson December 8, 1983.
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement at top of San Andres and run 1" line in casing a	cks of neat cement from TD of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Roy Joh lug at TD, 25 sack cement	to surface. t off water at 455'. arted in first collar nson December 8, 1983. plug from 20' below
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement top of San Andres and run 1" line in casing a was plugged as follows: 35 sacks set from 105	cks of neat cement from TD of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Roy Joh lug at TD, 25 sack cement nnulus to 380' and cement 8' to 1180'. 25 sacks from	to surface. t off water at 455'. arted in first collar nson December 8, 1983. plug from 20' below back to surface. Well
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement at top of San Andres and run 1" line in casing a was plugged as follows: 35 sacks set from 105 sacks in annulus from surface to 380'. Finis	cks of neat cement from TD of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Rov Joh lug at TD, 25 sack cement nulus to 380' and cement 8' to 1180', 25 sacks from hed plugging operations at	to surface. t off water at 455'. arted in first collar nson December 8, 1983. plug from 20' below back to surface. Well
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement at top of San Andres and run 1" line in casing a	cks of neat cement from TD of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Rov Joh lug at TD, 25 sack cement nulus to 380' and cement 8' to 1180', 25 sacks from hed plugging operations at	to surface. t off water at 455'. arted in first collar nson December 8, 1983. plug from 20' below back to surface. Well
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement at top of San Andres and run 1" line in casing a was plugged as follows: 35 sacks set from 105 sacks in annulus from surface to 380'. Finis	cks of neat cement from TD of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Rov Joh lug at TD, 25 sack cement nulus to 380' and cement 8' to 1180', 25 sacks from hed plugging operations at	to surface. t off water at 455'. arted in first collar nson December 8, 1983. plug from 20' below back to surface. Well
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement at top of San Andres and run 1" line in casing a was plugged as follows: 35 sacks set from 105 sacks in annulus from surface to 380'. Finis	cks of neat cement from TD of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Rov Joh lug at TD, 25 sack cement nulus to 380' and cement 8' to 1180', 25 sacks from hed plugging operations at	to surface. t off water at 455'. arted in first collar nson December 8, 1983. plug from 20' below back to surface. Well
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement at top of San Andres and run 1" line in casing a was plugged as follows: 35 sacks set from 105 sacks in annulus from surface to 380'. Finis	cks of neat cement from TD of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Rov Joh lug at TD, 25 sack cement nulus to 380' and cement 8' to 1180', 25 sacks from hed plugging operations at	to surface. t off water at 455'. arted in first collar nson December 8, 1983. plug from 20' below back to surface. Well
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement at top of San Andres and run 1" line in casing a was plugged as follows: 35 sacks set from 105 sacks in annulus from surface to 380'. Finis	cks of neat cement from TD of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Rov Joh lug at TD, 25 sack cement nulus to 380' and cement 8' to 1180', 25 sacks from hed plugging operations at	to surface. t off water at 455'. arted in first collar nson December 8, 1983. plug from 20' below back to surface. Well
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement at top of San Andres and run 1" line in casing a was plugged as follows: 35 sacks set from 105 sacks in annulus from surface to 380'. Finis	cks of neat cement from TD of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Rov Joh lug at TD, 25 sack cement nulus to 380' and cement 8' to 1180', 25 sacks from hed plugging operations at	to surface. t off water at 455'. arted in first collar nson December 8, 1983. plug from 20' below back to surface. Well
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement at top of San Andres and run 1" line in casing a was plugged as follows: 35 sacks set from 105 sacks in annulus from surface to 380'. Finis	cks of neat cement from TD of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Rov Joh lug at TD, 25 sack cement nulus to 380' and cement 8' to 1180', 25 sacks from hed plugging operations at	to surface. t off water at 455'. arted in first collar nson December 8, 1983. plug from 20' below back to surface. Well
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement at top of San Andres and run 1" line in casing a was plugged as follows: 35 sacks set from 105 sacks in annulus from surface to 380'. Finis	cks of neat cement from TD of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Rov Joh lug at TD, 25 sack cement nulus to 380' and cement 8' to 1180', 25 sacks from hed plugging operations at	to surface. t off water at 455'. arted in first collar nson December 8, 1983. plug from 20' below back to surface. Well
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement at top of San Andres and run 1" line in casing a was plugged as follows: 35 sacks set from 105 sacks in annulus from surface to 380'. Finis	cks of neat cement from TD of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Rov Joh lug at TD, 25 sack cement nulus to 380' and cement 8' to 1180', 25 sacks from hed plugging operations at	to surface. t off water at 455'. arted in first collar nson December 8, 1983. plug from 20' below back to surface. Well
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement at top of San Andres and run 1" line in casing a was plugged as follows: 35 sacks set from 105 sacks in annulus from surface to 380'. Finis	cks of neat cement from TD of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Rov Joh lug at TD, 25 sack cement nulus to 380' and cement 8' to 1180', 25 sacks from hed plugging operations at	to surface. t off water at 455'. arted in first collar nson December 8, 1983. plug from 20' below back to surface. Well
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement at top of San Andres and run 1" line in casing a was plugged as follows: 35 sacks set from 105 sacks in annulus from surface to 380'. Finis Ran Litho density log and cored well from 619	cks of neat cement from TD of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Rov Joh lug at TD, 25 sack cement nulus to 380' and cement 8' to 1180', 25 sacks from hed plugging operations at ' to 736'.	to surface. t off water at 455'. arted in first collar nson December 8, 1983. plug from 20' below back to surface. Well
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement at top of San Andres and run 1" line in casing a was plugged as follows: 35 sacks set from 105 sacks in annulus from surface to 380'. Finis Ran Litho density log and cored well from 619	cks of neat cement from TD of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Rov Joh lug at TD, 25 sack cement nulus to 380' and cement 8' to 1180', 25 sacks from hed plugging operations at ' to 736'.	to surface. t off water at 455'. arted in first collar nson December 8, 1983. plug from 20' below back to surface. Well
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement at top of San Andres and run 1" line in casing a was plugged as follows: 35 sacks set from 105 sacks in annulus from surface to 380'. Finis Ran Litho density log and cored well from 619	cks of neat cement from ID of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Rov Joh lug at ID, 25 sack cement nulus to 380' and cement 8' to 1180', 25 sacks from hed plugging operations at ' to 736'.	to surface. t off water at 455'. arted in first collar nson December 8, 1983. plug from 20' below back to surface. Well 667' to 754' and 172 9:00 P.M. Dec.8, 1983.
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement at top of San Andres and run 1" line in casing a was plugged as follows: 35 sacks set from 105 sacks in annulus from surface to 380'. Finis Ran Litho density log and cored well from 619	cks of neat cement from TD of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Rov Joh lug at TD, 25 sack cement nulus to 380' and cement 8' to 1180', 25 sacks from hed plugging operations at ' to 736'.	to surface. t off water at 455'. arted in first collar nson December 8, 1983. plug from 20' below back to surface. Well
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement at top of San Andres and run 1" line in casing a was plugged as follows: 35 sacks set from 105 sacks in annulus from surface to 380'. Finis	cks of neat cement from ID of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Rov Joh lug at ID, 25 sack cement nulus to 380' and cement 8' to 1180', 25 sacks from hed plugging operations at ' to 736'.	to surface. t off water at 455'. arted in first collar nson December 8, 1983. plug from 20' below back to surface. Well 667' to 754' and 172 9:00 P.M. Dec.8, 1983.
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement at top of San Andres and run 1" line in casing a was plugged as follows: 35 sacks set from 105 sacks in annulus from surface to 380'. Finis Ran Litho density log and cored well from 619	cks of neat cement from ID of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Rov Joh lug at ID, 25 sack cement nulus to 380' and cement 8' to 1180', 25 sacks from hed plugging operations at ' to 736'.	to surface. t off water at 455'. arted in first collar nson December 8, 1983. plug from 20' below back to surface. Well 667' to 754' and 172 9:00 P.M. Dec.8, 1983.
Drilled 12 1/4" hole to 540 ft. and ran 533' Drilled 7 7/8" hole to 1180' TD. Attempted to 40' beneath surface. Received permission to His instructions were to set 25 sack cement at top of San Andres and run 1" line in casing a was plugged as follows: 35 sacks set from 105 sacks in annulus from surface to 380'. Finis Ran Litho density log and cored well from 619	cks of neat cement from ID of 8 5/8" 23*casing to shu o pull casing but string p plug well from Mr. Rov Joh lug at ID, 25 sack cement nulus to 380' and cement 8' to 1180', 25 sacks from hed plugging operations at ' to 736'.	to surface. t off water at 455'. arted in first collar nson December 8, 1983. plug from 20' below back to surface. Well 667' to 754' and 172 9:00 P.M. Dec.8, 1983.