

BERT THOMPSON				#1 Tucumcari 1st Nat'l Bank P-20-8N-22E			
COMPANY		WELL NO.		LEASE		S T R	
Loc.	660 fr. S L	660 fr. E L	County Guadalupe				
Spud.	8-30-59	Comp.	9-29-59	Field Wildcat			
T.D.	6032 P.B.	T.Pay		CSG. RECORD			
I.P.	P & A			Size	Depth	Sax	
				9-5/8	328	200	
Remarks: Wire line DST Failure. DST 5127							
ISIFP ISI SI O Stuck tool in hole no rec							
Tbg. at							
FORMATION RECORD							
Elev. 4804 DF 4799 64							
T.San And 536							
T.Glor 1023							
T.Arkose 3312							
T.Miss 5970							
Treatment: T.Gr 6012							
T.White Horse 288							
T.							
T.							
T.							

Co. GUADALUPE POOL WILDCAT STATE N.M. KROENLEIN 13-59

COMPANY Bert Thompson et al - #1 - Tucumcari ELEV. 4804
First Nat'l Bank

LOC (660' FNL & PEL) corr.: 660' FSL & PEL
Sec. 20, T.8-N, R. 22-E
6500' Gr.

ACID OR SHOT	CASING RECORD	TOPS
	9 5/8- 328- 200	White Horse 288
		S. And. 536
		B.S. And. 938
		Glor. 1023
		Tubb 2470
		Ark. 3312
		Miss. 5970
SPD 8-30-59	COMP 9-29-59	
I. P. F & A		
GR GOR TP CP		TP
REMARKS Wire Line DST: 5127' - no rec.		TD 6032 Gr.
		POD