

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

66 SEP 27 PM 1 19

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
Charley Johnston	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Wildcat	
12. County	
Guadalupe	

SUNDY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	
2. Name of Operator	
Kenneth M. Hankins	
3. Address of Operator	
c/o Oil Reports & Gas Services, Box 763, Hobbs, New Mexico	
4. Location of Well	
UNIT LETTER M , 330 FEET FROM THE South LINE AND 330 FEET FROM	
THE West LINE, SECTION 27 TOWNSHIP 11 N RANGE 24 E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	
4726 GR	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned 9/18/66 as follows:

5 sacks at 1270 total depth
10 sacks at 850
10 sacks at 600
10 sacks at 150
7" conductor pipe at 30' left in hole.
3 sacks in top of 7" with marker.
Mud between all plugs.

Location will be cleaned and ready for inspection on or about October 25.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. L. Smith TITLE Agent DATE 9/26/66

APPROVED BY J. E. Kapteina TITLE Oil & Gas Inspector DATE 10/26/66
CONDITIONS OF APPROVAL, IF ANY: list IV