State of New Mexico Submit 3 Copies Form C-103 Energy, Minerals, and Natural Resources Department :o Appropriate Revised 1-1-89 District Office OIL CONSERVATION DIVISION WELL API NO. DISTRICT I P.O. Box 2088 P.O. Box 1980, Hobbs, NM 88240 30-021-20050 DISTRICT II Santa Fe, New Mexico 87504-2088 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 **STATE** FEE DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" 7. Lease Name or Unit Agreement Name (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well BRAVO DOME CO2 GAS UNIT OIL GAS WELL WELL CO₂ OTHER 2. Name of Operator 8. Well No. AMOCO PRODUCTION COMPANY 1832-121G 3. Address of Operator 9. Pool name or Wildcat P.O. Box 303, AMISTAD, **NEW MEXICO** 88410 BRAVO DOME CO2 GAS UNIT . Well Location Unit Letter 1980 Feet From The North Line and Feet From The Line Section Township 18N NMPM Harding County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4723 8 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **EMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB OTHER: OTHER: 2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. MIRUSU, kill well as necessary, NUBOP, release packer, lay down production tubing and packer, run cast iron bridge plug with wireline, set CIBP at 2,398 feet, run workstring, displace casing with mud laden fluid, pressure test casing to 500 psi, cap CIBP with 3 sacks of cement, pull workstring to 1,934 feet, spot 8 sacks of cement, pull workstring to 30 feet, fill casing with cement, NDBOP, cut off wellhead, install PXA marker, RDMOSU, cut off well anchors and clean location. hereby certify that the informatrue and complete to the best of my knowledge and belief **IGNATURE** TITLE Field Foreman DATE YPE OR PRINT NAME TELEPHONE NO (505) 374-3010 This space for State Use) DISTRICT SUPERVISOR PPROVED BY 99

ONDITIONS OF APPROVAL, IF AN