

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**DISTRICT I**  
P.O. Box 1980, Hobbs NM 88241-1980

**DISTRICT II**  
P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

|  |  |
|--|--|
| WELL API NO.   | 30-021-20059   |
| 5. Indicate Type of Lease  | STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No.                                     | L 5826   |
| 7. Lease Name or Unit Agreement Name<br>WEST BRAVO DOME CDG UNIT |  |
| 8. Well No.  | 2  |
| 9. Pool name or Wildcat  | WEST BRAVO DOME  |

|  |  |
|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS<br>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)                     |  |
| 1. Type of Well:<br>OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER CO2 SUPPLY WELL  |  |
| 2. Name of Operator<br>Amerada Hess Corporation  |  |
| 3. Address of Operator<br>P. O. Box 840, Seminole, Texas 79360-0840  |  |
| 4. Well Location<br>Unit Letter <u>F</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>WEST</u> Line<br>Section <u>30</u> Township <u>19N</u> Range <u>30E</u> NMPM <u>HARDING</u> County |  |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.)<br>4442'  |  |

11.

**Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data**

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WEST BRAVO DOME CDG UNIT #2

MIRU PULLING UNIT. REPERFORATE TUBB FORMATION AND FLOW TEST FOR 144 HOURS. RUN POLYLINER TO CIMMARRON ANHYDRITE. RDMO PULLING UNIT AND CLEAN LOCATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 08/25/97  
TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 915 758-6778

(This space for State Use)

APPROVED BY Ry Johnson DISTRICT SUPERVISOR DATE 9-7-97  
CONDITIONS OF APPROVAL, IF ANY: