

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-021-20060</u>
5. Indicate Type of Lease STATE ☐ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <u>Bravo Dome Carbon Dioxide Gas Unit</u>
8. Well No. <u>BDCDGL 2032171K</u>
9. Pool name or Wildcat <u>Bravo Dome Carbon Dioxide Gas Unit</u>

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER <u>CO₂</u>	
2. Name of Operator <u>Amoco Production Company</u>	
3. Address of Operator <u>P.O. Box 3092 Houston, Texas 77253</u>	
4. Well Location Unit Letter <u>K</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>17</u> Township <u>T20N</u> Range <u>R32E</u> NMPM <u>Harding</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>4791.6</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ TEMPORARILY ABANDON ☒ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/24/92 - TPE 335 psi, CPC 300 psi
5/5/92 - Dropped 2 3/8" Standing valve + Pres tst tbg 500 psi, OK
Load Annulus w/ 32 BBL Produced water - Attempt to pres tst annulus. 100 psi, Bled to 0 psi, Annulus went on strong vacuum. Propose to MURSU, Kill well as necessary, Pull tbg x pkr, R Cast iron bridge plug + set @ 2175', Pres tst csq to 500 psi if OK, Cap CIBP w/ 25 ft cement, Land lft of tbg in well head + monitor annually

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Billy E. Prichard

TITLE

Field Foreman

DATE

5/6/92

TYPE OR PRINT NAME

Billy E. Prichard

505 374 3053
TELEPHONE NO.

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: