	LS DEPARTMENT	011 0011077	a <b></b>			
45. 07 COPIES TEE			ATION DIVISION		Sa 0. 102	
P. O. BOX 2088					Form C-103 Revised 10-1	
JANTA FE	——————————————————————————————————————	SANTA FE, NEV	V MEXICO 87501		•	
U.3.0.3.				5a. Indicate	Type of Lease	
LAND OFFICE				State	F00	
OPERATOR				5, State Off	& Gas Lease No.	
	CLIND DV NO.	TICES AND DEDODES ON	NUCL I C	mm	mmmn	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO CRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)						
01L	WELL X CO2 OTH	ra.		7. Unit Agre		
: iame of Operator					ease Name	
Amoco Production Company					BDCDGU 1931	
. Address of Operator				9. Well No.		
P. O. Box 68 Hobbs, NM 88240				311	311	
, Location of Well .				10, Field om	d Pool, or Wildcat	
UNIT LETTER J . 1980 FEET FROM THE SOUTH LINE AND 1980 FEET FRO				FEET FROM Und. TI	ubb	
Ēa a+	-	10	N 21 E			
THE Edst	LINE, SECTION	3] TOWNSHIP 19-	N RANGE 31-E	NMPM. (\\\\\\\\\\\		
mmm		15. Elevation (Show whether	DF, RT, GR, etc.)	12. County		
		3	_4532' GL	Hardin		
··	Check Appror	oriate Box To Indicate 1		ort or Other Data	*	
N	OTICE OF INTENT		•	SEQUENT REPORT	OF:	
CRFORM REMEDIAL WOR	× 🗌	PLUG AND ABANDON	REMEDIAL WORK	X	LTERING CASING	
IMPONANTLY ABANDON			COMMENCE DRILLING OPNS.	P	LUG AND ABANDONMENT	
JEL OR ALTER CASING		CHANGE PLANS	CASING TEST AND CEMENT JO	۵ ع	_	
		_	OTHER		<u> </u>	
OTHER		- <u>-</u>				
		s (Clearly state all pertinent de	tails, and give pertinent dates	, including estimated dat	e of starting any propos	
work) SEE RULE 1	103.					
with an averag 14800 gal. 30#	ge of 228 MCFD. f frac fluid an	separator for a pr Moved in service d 1340# sand. Flow 93 MCFD. Well shut	unit 6-10-81. Fra tested well thru	ced well with	r.	
				·		

Admin. Analyst

SENIOR PETROLEUM GEOLOGIST