

**STRICT I**  
O. Box 1980, Hobbs, NM 88240

**STRICT II**  
O. Drawer DD, Artesia, NM 88210

**STRICT III**  
00 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-021-20138

5. Indicate Type of Lease

STATE ☐

FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

BRAVO DOME CO2 GAS UNIT

8. Well No.

2033-301G

9. Pool name or Wildcat

BRAVO DOME CO2 GAS UNIT

### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

Type of Well

OIL  
WELL ☐

GAS  
WELL ☐

OTHER

CO2

Name of Operator

AMOCO PRODUCTION COMPANY

Address of Operator

P.O. Box 303, AMISTAD, NEW MEXICO 88410

Well Location

Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line  
Section 30 Township 20N Range 33E NMPM Harding County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

5090 GR

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

WILL OR ALTER CASING ☐

OTHER: ☐

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

Describe Proposed or Completed Operations

SEE RULE 1103.

(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)

MIRUSU, kill well as necessary, NUBOP, release packer, lay down production tubing and packer, run workstring to 2,560 feet, spot 10 sacks of class C cement, pull workstring, WOC, run workstring, tag cement, cement should be above 2,482 feet, pressure test casing to 500 psi, displace casing with corrosion inhibited fluid, pull workstring to 2,120 feet, spot 10 sacks of cement, pull workstring to 30 feet and fill casing with cement, NDBOP, RDMOSU, cut off wellhead, install PXA marker, cut off well anchors and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

NATURE DJ Holcomb TITLE Field Foreman

DATE 2-29-00

NAME OR PRINT NAME Danny J. Holcomb

TELEPHONE NO. (505) 374-3010

(is space for State Use)

APPROVED BY R. E. Johnson TITLE DISTRICT SUPERVISOR

DATE 3/9/00

CONDITIONS OF APPROVAL, IF ANY: