Submit 3 Copies To Appropriate Distr Office	ict State of	State of New Mexico			Form C-103		
District I	Energy, Minera	Energy, Minerals and Natural Resources			Revised March 25, 1999		
1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO.			
1301 W. Grand Ave., Artesia, NM 882		OIL CONSERVATION DIVISION			0-021-20216		
District III 1000 Rio Brazos Rd., Aztec, NM 8741	U	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE FEE			
District IV	Santa	Santa Fe, NM 87505		6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM 87505					Ous Louise 140.		
SUNDRY N	OTICES AND REPORTS	ON WELLS	3	7. Lease Name	or Unit Agreement N	Ioma:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				7. Lease Name or Unit Agreement Name:			
TROPOSALS.)				Bravo Dome Carbon Dioxide Gas Unit			
1. Type of Well: Oil Well Gas Well Other CO:				2133			
2. Name of Operator	Other CO ₂						
OXY USA, Inc.				8. Well No.			
3. Address of Operator				9. Pool name or Wildcat			
P. O. Box 303, Amistad, NM 88410				Bravo Dome CO ₂ Gas Unit 640 Acre Area			
4. Well Location				Diavo Boine CC	72 Gas Unit 040 Acre	Area	
Unit Letter G	1650 6. (6.)				\		
Oilli LetterG	_:1650feet from th	neNorth_	line and	1650feet fro	m theEastl	ine	
Section 35	Township	21N 1	Range 33E	NMPM	Handle		
	10. Elevation (Show	whether DR	R, RKB, RT, GR, etc.)	Harding Count	У	
11 (1)	5027' GL						
NOTICE OF	k Appropriate Box to I	ndicate Na	ature of Notice, F	Report or Other	r Data		
PERFORM REMEDIAL WORK [INTENTION TO: PLUG AND ABANDOI		SUBS	SEQUENT RE			
	T LEGG WAD ARAMDOL		REMEDIAL WORK	\boxtimes	ALTERING CASING	i 🗆	
TEMPORARILY ABANDON				LING OPNS 🗆	PLUG AND		
PULL OR ALTER CASING [MULTIPLE				ABANDONMENT	LJ	
. The Strain on Sind	COMPLETION		CASING TEST AND CEMENT JOB	P 🗆			
OTHER:		_					
	4.1		OTHER:				
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of recompilation. SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or							
recompilation.	DEE ROLE 1103. FOI MU	itipie Compi	letions: Attach well	bore diagram of p	proposed completion of	or	
0.4.04		s.					
8-4-01 - MI x RUSU, kill well,	NU BOP, unset pkr and pt	ull 2 7/8" FC	production tbg x pl	kr, PU x run 4 34"	bit, bit sub. 2 3/8"		
 8-4-01 - MI x RUSU, kill well, NU BOP, unset pkr and pull 2 7/8" FG production tbg x pkr, PU x run 4 ¾" bit, bit sub, 2 3/8" 8-5-01 - Crew days off 							
8-6-01 - Kill well, run workstring x tag fill at 2490', RU foam unit x swivel, clean out sand 2490' – 2651', circ well, RD swivel x							
8-7-U1 - Kill well, RIH with 1 jt of 3 ½" FG tailpipe, pkr. 2.7/8" FG production the PSA 22/47. TLA 22701 ND DOD							
500 psi x ok, RD MOSU, leave well SI overnight. 8-8-01 - Install meter run, open well to tank for 8 hours, rec 36 BLW, turn well to sales							
instan meter run, open	well to talk for 8 nours, red	c 36 BLW, t	urn well to sales				
	DDU/O 455	. .					
	PPWO – 475 mc	etd PA	AWO – 530 mcfd				
I hereby certify that the information	above is true and complete	e to the hest	of my knowledge	-d b -11 - E			
(1)	D. 1	o to the best	or my knowledge ar	id belief.			
SIGNATURE /// //	1 comb	TITLE	Team Leader	DA	ATE9-25-2001		
Type or print name Dan	ny J. Holcomb						
(This space for State use)	A J. HOROMB	······································		Telephone No	o. 505-374-3010		
1,		~1~~	'DIMT MILMI	11 11 Ph atm a			
APPPROVED BY \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	sopur T	ILLE DIS!	RICT SUPER	KVISO₽ ,	DATE 10/2/01		
Conditions of approval, if any	<i></i>			·	DUIE - 1 -1	_	