

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- Carbon Dioxide	7. Unit Agreement Name
2. Name of Operator SCHWARTZ CARBONICS	8. Farm or Lease Name Norman and Esther Libby
3. Address of Operator Box 37, Solano, New Mexico 87746	9. Well No. Libby 2
4. Location of Well UNIT LETTER E 1980 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 32 TOWNSHIP 20 N RANGE 31 E NMPM.	10. Field and Pool, or Wildcat Bueyeros
15. Elevation (Show whether DF, RT, GR, etc.) GL - 4600	12. County Harding

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spotted 25 sacks Class C cement containing 2% CaCl and 1/2# floccelle per sack at TD of 2124' and WOC 2 1/2 hrs. Could not tag plug. Spotted 25 sacks at same depth and WOC 2 1/2 hrs. Tagged cement at 1590' and spotted 25 sacks cement, WOC 2 hrs. Tagged cement at 768'. Mixed and pumped 100 sacks cement and circulated 10 sacks to the pit. A dry hole marker was erected and the well was plugged and abandoned on 9/26/84.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. M. Zuehlke TITLE Regional Production Manager DATE 11-12-84

APPROVED BY [Signature] TITLE [Signature] DATE 11-26-84

CONDITIONS OF APPROVAL, IF ANY: