Repairs on De Baca #2

Results of work done in the period from September 8, 1954

Cox Drilling Co. of Borger, Texas, Mr. Bob Cox Manager. (989)

Opened Well found a bridge below production of the contractor out bridge which was a (Walker Neer) cable tool, contractor 1989.

out bridge which was shuting off some of the gas flow. Very little mud and water in well.

Hole was cleared to 2118 feet where there was still a part of a pipe liner which was put in well some time ago. Some of the liner was apparently oulled, and some of it was left in well.

A perforated liner of 4 inch of 140 feet was put in well.

Also a bleeder string was put in well of 140 feet of 1 inch pipe. 1955 feet of 2 inch upset tubing, making a total of 2095 feet of bleeder string.

Well is again in production.

Repulled on De Bous #2

We clark of very dole in the parted incar versember θ_{\star} 1954 to represented if 1954 .

With Asia work which cas a (salker serr) a bla spol, conseration was land to be said the specific of the said of the said of the series of the said of

cased toll form, the bridge season coduction fining. Defiled out, tidge tide was smalling of some of as assisted vory tittle and and with the till.

note the classes of this land there the still a part of a life of the content of

. Fire al dum se don't was to real the seal the second

where a classifier was not in wall of 140 for a of limits. The first free of 2 inch areas to the f and f are real of f and f are real of the f are such as the f are the f and f are the f are

.noits.boar of along of fine