

COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<p><b>SUNDRY NOTICES AND REPORTS ON WELLS</b> DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. (USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p>
<p>5. State Oil &amp; Gas Lease No.</p>		
<p>7. Unit Agreement Name</p>		
<p>8. Farm or Lease Name</p>		
<p>Harvey E. Yates Company</p>		Mora Ranch
<p>Suite 1000 Security National Bank Building, Roswell, N.M. 88201</p>		9. Well No.
<p>#1</p>		
<p>10. Field and Pool, or Wildcat</p>		
<p>Wildcat</p>		
<p>11. Field and Pool, or Wildcat</p>		
<p>West LINE, SECTION 30 TOWNSHIP 22N RANGE 21E NMPM.</p>		
<p>15. Elevation (Show whether DF, RT, GR, etc.)</p>		12. County
<p>6600' GL</p>		Mora

<p>Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p>			
<p>NOTICE OF INTENTION TO:</p>		<p>SUBSEQUENT REPORT OF:</p>	
<p>PERFORM REMEDIAL WORK <input type="checkbox"/></p>	<p>PLUG AND ABANDON <input checked="" type="checkbox"/></p>	<p>REMEDIAL WORK <input type="checkbox"/></p>	<p>ALTERING CASING <input type="checkbox"/></p>
<p>TEMPORARILY ABANDON <input type="checkbox"/></p>	<p>CHANGE PLANS <input type="checkbox"/></p>	<p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p>	<p>PLUG AND ABANDONMENT <input type="checkbox"/></p>
<p>PULL OR ALTER CASING <input type="checkbox"/></p>	<p>OTHER <input type="checkbox"/></p>	<p>CASING TEST AND CEMENT JOB <input type="checkbox"/></p>	<p>OTHER <input type="checkbox"/></p>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work, SEE RULE 1103.

1-14-77 No economic reason to complete this well. Will plug and abandon as follows:

Plug #1 - 10 Sx @ 1443'  
Plug #2 - 10 Sx @ 1330'  
Plug #3 - 10 Sx @ 990'  
Surface Plug - 10 Sx

Dry hole marker on top.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Carl Ulvog TITLE Vice President DATE February 23, 1977

APPROVED BY Carl Ulvog TITLE  DATE 2/25/77

CONDITIONS OF APPROVAL, IF ANY: