

Rose-Coss, Dylan H, EMNRD

From: DeAnn Grant <agrant@concho.com>
Sent: Wednesday, April 10, 2019 3:20 PM
To: EMNRD-OCD-District1spills; caweaver@blm.gov
Cc: jamos@blm.gov; dmckinne@blm.gov; Jennifer Knowlton; Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell; DeAnn Grant
Subject: [EXT] (C-141 Initial) Gunner 8 Federal Com 6H & 7H Battery (30-025-41181) 03-30-2019
Attachments: (C-141 Initial) Gunner 8 Federal Com 6H & 7H Battery (30-025-41181) 03-30-2019.pdf; Spill Calculation - Gunner 8 Federal Com 6 & 7 Battery 03-30-2019.pdf

To Whom It May Concern,

Please find the attached C-141 for your consideration. Also, attached is the calculation sheet to determine the estimated release volume for Falcon Lined facilities. The liquid lost estimate is based on the spill dimensions and estimated depth of fluid in the liner. The spreadsheet will calculate the volume lost into the liner. No gravel was present in this lined facility as it is a Falcon Liner. The unrecovered volume is a residue left behind on the liner and equipment which will be cleaned by pressure wash. If you have any questions or concerns please do not hesitate to contact me

Thank you,

DeAnn Grant

HSE Administrative Assistant

agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443

